

# Roof Safety Report

Amaroo Primary School

Prepared By: Safemaster Safety Products  
Date: 13/04/18

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Amaroo Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Amaroo Primary School and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Trevor Harris (Recertification Technician)**

Roof Safety Report for  
Amaroo Primary School

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Admin Room 1-2/PP1-PP3 Room 3-7 Room 8-11/Music-Art Room 12-17 Assembly Area	Anchor Points Signage Ladder Bracket

DATE OF INSPECTION

13/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Amaroo Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
12	Surfacemount Anchor Point	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Ladder Bracket	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
14	Sign	Safemaster	Admin	1/08/2015	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
15	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
23	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
27	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
34	Purlin Fix Anchor Point	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
35	Ladder Bracket	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
36	Sign	RSS	Room 1-2/PP1-PP3	1/09/2010	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
38	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
39	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
40	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
41	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
42	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
43	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
44	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
45	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
46	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
47	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
48	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
50	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
51	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
52	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
53	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
54	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
55	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
56	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
57	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
58	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
59	Surfacemount Anchor Point	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
60	Access Strop	RSS	Room 3-7	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Ladder Bracket	RSS	Room 3-7	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Not Inspected	No Access
62	Sign	Safemaster	Room 3-7	1/10/2015	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Not Inspected	No Access
63	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
64	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
65	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
66	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
67	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
68	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
69	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
70	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
71	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
72	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
74	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
75	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
76	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
77	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
78	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
79	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
80	Surfacemount Anchor Point	RSS	Room 8-11/Music-Art	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
81	Ladder Bracket	RSS	Room 8-11/Music-Art	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
82	Sign	Safemaster	Room 8-11/Music-Art	1/10/2015	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
83	Surfacemount Anchor Point	RSS	Room 12-17	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
84	Surfacemount Anchor Point	RSS	Room 12-17	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Surfacemount Anchor Point	RSS	Room 12-17	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
86	Surfacemount Anchor Point	RSS	Room 12-17	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
87	Surfacemount Anchor Point	RSS	Room 12-17	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
88	Surfacemount Anchor Point	RSS	Room 12-17	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
89	Surfacemount Anchor Point	RSS	Room 12-17	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
90	Ladder Bracket	RSS	Room 12-17	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
91	Sign	Safemaster	Room 12-17	1/10/2015	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
92	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	2 metre strop needed for safe access and egress to roof
93	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
94	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
95	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
96	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7145

**Site:** Amaroo Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
98	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
99	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
100	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
101	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
102	Surfacemount Anchor Point	RSS	Assembly Area	1/09/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
103	Ladder Bracket	RSS	Assembly Area	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
104	Sign	Safemaster	Assembly Area	1/10/2015	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 13/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Compliance Requirements

[illegible]





Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)