

Roof Safety Report

Aquinas College

Prepared By: Safemaster Safety Products
Date: 7/5/2018

CONFIDENTIALITY/SECURITY

Information obtained from and about Aquinas College in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Aquinas College and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tony Pennington (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6218 5158 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Tony Pennington (Recertification Technician)

Roof Safety Report for
Aquinas College

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Aquinas College	Chapel Kitchen Br Paull Centre Early Years/Admin Junior School Uniform Shop Redmond Learning Centre Canteen Nunan Residence Pinder Boor Residence Gibney Residence McKenna Science Wing	Anchor Points Signage Hatches Ladders Ladder Brackets

DATE OF INSPECTION

7/5/2018

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Aquinas College buildings.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
2	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
3	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
4	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
5	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
6	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
7	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
8	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
9	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
10	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
11	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
12	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
14	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
15	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
16	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
17	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
18	Frog Link Anchor Point	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
19	Ladder Bracket	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Fail	Missing
20	Ladder Bracket	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
21	Sign	Safemaster	Chapel	1/06/2014	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
22	Purlin Fix Anchor Point	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
23	Purlin Fix Anchor Point	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Purlin Fix Anchor Point	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
27	Purlin Fix Anchor Point	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
29	Ladder Bracket	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
30	Sign	Safemaster	Kitchen	1/03/2015	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
31	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
34	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
43	Ladder Bracket	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
44	Ladder Bracket	Safemaster	Br Paull Centre	1/08/2010	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
45	Sign	Safemaster	Br Paull Centre	27/02/2017	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
46	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
47	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
48	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
50	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
51	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
52	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
53	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
54	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
55	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
56	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
57	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
58	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
59	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
60	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
62	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
63	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
64	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
65	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
66	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
67	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
68	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
69	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
70	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
71	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
72	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
74	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
75	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
76	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
77	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
78	Timber Fix Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
79	Surfacemount Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
80	Surfacemount Anchor Point	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
81	Ladder Bracket	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
82	Ladder Bracket	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
83	Ladder Bracket	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
84	Ladder Bracket	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Sign	Safemaster	Early Years/Admin	1/11/2012	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
86	Sign	Safemaster	Early Years/Admin	21/02/2017	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
87	Sign	Safemaster	Early Years/Admin	21/02/2017	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
88	Sign	Safemaster	Early Years/Admin	21/02/2017	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
89	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
90	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
91	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
92	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
93	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
94	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
95	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
96	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
98	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
99	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
100	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
101	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
102	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
103	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
104	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
105	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
106	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
107	Surfacemount Anchor Point	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
108	Hatch	Unknown	Uniform Shop	Unknown	7/05/2018	7/11/2018	AS1657:2013	Fail	Smaller than the required minimum

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Sign	Safemaster	Uniform Shop	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
110	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
111	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
112	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
113	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
114	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
115	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
116	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
117	Timber Fix Anchor Point	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
118	Ladder	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1657:2013	Fail	No Static line on Ladder over three meters high. No non slip coating on rungs.
119	Hatch	Unknown	Uniform Shop	Unknown	7/05/2018	7/11/2018	AS1657:2013	Fail	Smaller than the required minimum
120	Sign	Safemaster	Junior School	1/07/2014	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
122	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
123	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
124	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
125	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
126	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
127	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
128	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
129	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
130	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
131	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
132	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
134	Purlin Fix Anchor Point	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
135	Ladder Bracket	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
136	Sign	Safemaster	Redmond Learning Centre	1/11/2014	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
137	Purlin Fix Anchor Point	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
138	Purlin Fix Anchor Point	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
139	Purlin Fix Anchor Point	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
140	Purlin Fix Anchor Point	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
141	Purlin Fix Anchor Point	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
142	Purlin Fix Anchor Point	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
143	Purlin Fix Anchor Point	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
144	Ladder Bracket	RSS	Canteen	1/11/2014	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Sign	Safemaster	Canteen	27/02/2017	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
146	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
147	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
148	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
149	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
150	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
151	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
152	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
153	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
154	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
155	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
156	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
158	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
159	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
160	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
161	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
162	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
163	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
164	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
165	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
166	Timber Fix Anchor Point	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
167	Ladder	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1657:2013	Pass	
168	Hatch	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Sign	Safemaster	Nunan Residence	9/12/2012	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
170	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
171	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
172	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
173	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
174	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
175	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
176	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
177	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
178	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
179	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
180	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
182	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
183	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
184	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
185	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
186	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
187	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
188	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
189	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
190	Timber Fix Anchor Point	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009		Under Renovation Cannot Test
191	Ladder	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1657:2013		Under Renovation Cannot Test
192	Hatch	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1657:2013		Under Renovation Cannot Test

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Sign	Safemaster	Pinder Boor Residence	9/12/2012	7/05/2018	7/11/2018	AS1319:1994 AS1891.4:2009		Under Renovation Cannot Test
194	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
195	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
196	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
197	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
198	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
199	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
200	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
201	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
202	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
203	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
204	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
205	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
206	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
207	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
208	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
209	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
210	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
211	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
212	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
213	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
214	Timber Fix Anchor Point	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
215	Ladder	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1657:2013	Pass	
216	Hatch	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Sign	Safemaster	Gibney Residence	9/12/2012	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	
218	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
219	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
220	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
221	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
222	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
223	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
224	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
225	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
226	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
227	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
228	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Aquinas College

Job Ref: SM 5144

Site: Aquinas College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Timber Fix Anchor Point	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1891.4:2009	Pass	
230	Ladder	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1657:2013	Pass	
231	Sign	Safemaster	McKenna Science Wing	1/02/2016	7/05/2018	7/11/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Tony Pennington

DATE: 7/5/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

COMPLIANCE REQUIREMENTS

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au