

Roof Safety Report

Dalyellup College

Prepared By: Safemaster Safety Products Date: 24/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about Dalyellup College in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to BMW Bunbury and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products) 33 Catalano Road, Canning Vale 6155 PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

Trevor Harris (Recertification Technician)

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED	
BMW Bunbury	Block A Block B Block C Block D Block E Block F	Anchor Points Signage Hatch Ladder Stair Static Line Ladder Bracket	

DATE OF INSPECTION 24/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Dalyellup College buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

Inspection Log

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
23	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
27	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
28	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
29	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
30	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
31	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
32	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
33	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
34	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
35	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
36	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
38	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
39	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
40	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
41	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
42	Purlin Fix Anchor Point	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Not Certified	No Safe Access
43	Ladder Bracket	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
44	Ladder Bracket	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
45	Ladder Bracket	Safemaster	Block A	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
46	Sign	Safemaster	Block A	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
47	Sign	Safemaster	Block A	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
48	Sign	Safemaster	Block A	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
51	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
52	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
53	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
54	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
56	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
57	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
58	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
59	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
60	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
62	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
63	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
64	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
65	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
66	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
67	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
68	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
69	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
70	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
71	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
72	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
74	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
75	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
76	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
77	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
78	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
79	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
80	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
81	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
82	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
83	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
84	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Purlin Fix Anchor Point	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
86	Ladder Bracket	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
87	Hatch	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
88	Hatch	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
89	Ladder	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
90	Ladder	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
91	Vertical Static Line	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
92	Vertical Static Line	Safemaster	Block B	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
93	Sign	Safemaster	Block B	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
94	Sign	Safemaster	Block B	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
95	Sign	Safemaster	Block B	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
96	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
98	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
99	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
100	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
101	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
102	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
103	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
104	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
105	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
106	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
107	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
108	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
110	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
111	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
112	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
113	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
114	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
115	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
116	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
117	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
118	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
119	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
120	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
122	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
123	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
124	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
125	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
126	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
127	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
128	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
129	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
130	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
131	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
132	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
134	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
135	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
136	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
137	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
138	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
139	Purlin Fix Anchor Point	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
140	Ladder Bracket	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
141	Ladder Bracket	Safemaster	Block C	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
142	Sign	Safemaster	Block C	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
143	Sign	Safemaster	Block C	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
144	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
146	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
147	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
148	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
149	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
150	Purlin Fix Anchor Point	Safemaster	Block D	40391	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
151	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
152	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
153	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
154	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
155	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
156	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
158	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
159	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
160	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
161	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
162	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
163	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
164	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
165	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
166	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
167	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
168	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
170	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
171	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
172	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
173	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
174	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
175	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
176	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
177	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
178	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
179	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
180	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
182	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
183	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
184	Purlin Fix Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
185	Surfacemount Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
186	Surfacemount Anchor Point	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
187	Hatch	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
188	Hatch	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
189	Ceiling Ladder	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
190	Vertical Ladder	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
191	Pull Down Stair	Safemaster	Block D	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
192	Sign	Safemaster	Block D	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Sign	Safemaster	Block D	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
194	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
195	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
196	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
197	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
198	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
199	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
200	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
201	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
202	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
203	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
204	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
205	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
206	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
207	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
208	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
209	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
210	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
211	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
212	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
213	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
214	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
215	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
216	Purlin Fix Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
218	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
219	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
220	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
221	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
222	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
223	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
224	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
225	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
226	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
227	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	A\$1891.4:2009	Pass	
228	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
230	Surfacemount Anchor Point	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
231	Hatch	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
232	Hatch	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
233	Ceiling Ladder	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
234	Vertical Ladder	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
235	Pull Down Stair	Safemaster	Block E	1/08/2010	24/04/2018	24/10/2018	AS1657:2013	Pass	
236	Sign	Safemaster	Block E	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
237	Sign	Safemaster	Block E	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
238	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
239	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
240	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
241	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
242	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
243	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
244	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
245	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
246	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
247	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
248	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
249	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
250	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
251	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
252	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
253	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
254	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
255	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
256	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
257	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
258	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
259	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
260	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
261	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
262	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
263	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
264	Surfacemount Anchor Point	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7153

Site: Dalyellup College

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Ladder Bracket	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
266	Ladder Bracket	Safemaster	Block F	1/06/2013	24/04/2018	24/10/2018	AS1891.4:2009	Pass	
267	Sign	Safemaster	Block F	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	
268	Sign	Safemaster	Block F	1/10/2014	24/04/2018	24/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 24/04/2018

1 SIGNATURE:

Compliance Requirements

Item No	Location	Recommendations
38 -53	Block A	Anchors not certified as there is no safe access to the high roof. A 4.5mt portable ladder to be installed on the roof.
	Block B	Step to be installed as per drawing as height difference is in excess of 500mm.
	Block C	Steps/mini ladders required to 5 areas as shown on drawing as height differentials are in excess of 500mm.
	Block D	Vertical ladder to be installed to access area as shown on drawing.
	Block E	Vertical ladders to be installed to access areas as shown on drawing.
	Block F	Ladder bracket shown on drawing has not been installed.



Safemaster Safety Products 31-33 Catalano Road, Canning Vale WA 6155 PO Box 1373 Canning Vale WA 6970 Ph: (08) 6243 3111 Fax: (08) 9456 5014 Email: info@safemaster.net.au Web: www.safemaster.net.au