

Roof Safety Report

DFO Homebush, NSW 2140

Prepared By: Safemaster Safety Products Date: 20 Dec 2018

CONFIDENTIALITY/SECURITY

Information obtained from and about DFO Homebush Shopping Centre, NSW in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to DFO Homebush Shopping Centre, NSW and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products) 31-33 Catalano Road, Canning Vale 6155 PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

Jo-+

James Townsend (Recertification Technician)

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres - DFO Homebush	DFO Homebush	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

14/11/2018

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on DFO Homebush buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
2	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
3	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
4	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
5	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
6	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
7	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
8	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
9	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
10	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
11	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
13	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
14	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
15	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
16	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
17	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
18	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
19	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
20	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
21	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
22	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
24	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
25	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
26	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
27	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
28	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
29	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
30	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
31	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
32	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
33	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
35	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
36	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
37	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
38	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
39	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
40	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
41	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
42	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
43	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
44	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
46	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
47	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
48	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
49	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
50	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
51	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
52	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
53	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
54	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
55	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
57	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
58	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
59	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
60	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
61	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
62	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
63	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
64	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
65	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
66	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
68	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
69	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
70	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
71	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
72	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
73	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
74	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
75	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
76	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
77	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
79	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
80	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
81	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
82	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
83	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
84	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
85	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
86	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
87	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
88	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
90	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
91	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
92	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
93	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
94	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
95	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
96	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
97	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
98	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
99	Frog Link Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Low Pro Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
101	Low Pro Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
102	Low Pro Anchor Point 15 Kn	Aussie Height Safety	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
103	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
104	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
105	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
106	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
107	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
108	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
109	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
110	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
112	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
113	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush/Level 4 Carpark	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Fail	No Safe Access to roof
114	Surfacemount Anchor Point 15Kn	RIS	DFO Homebush/Level 4 Carpark	Unknown	14/11/2018	14/11/2019	AS1891.4:2009	Fail	No Safe Access to roof
115	Surfacemount Anchor Point 15Kn	Safemaster	L1	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
116	Surfacemount Anchor Point 15Kn	Safemaster	L1	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
117	Surfacemount Anchor Point 15Kn	Safemaster	L1	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
118	Anchor Strop	Safemaster	L1	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
119	Access Ladder (AI)	Unknown	L2	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
120	Handrail (Al)	Safemaster	L3	14/10/2018	14/11/2018	14/11/2019	AS1657:2013	Pass	
121	Access Step (AI)	Safemaster	L4	14/10/2018	14/11/2018	14/11/2019	AS1657:2013	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Handrail (Al)	Unknown	L4	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
123	Step (Al)	Safemaster	L4	14/10/2018	14/11/2018	14/11/2019	AS1657:2013	Pass	
124	Step (AI)	Safemaster	L5	14/10/2018	14/11/2018	14/11/2019	AS1657:2013	Pass	
125	Handrail (Al)	Unknown	L7	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
126	Handrail (Al)	Unknown	L9	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
127	Handrail (Al)	Unknown	L13	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
128	Access Ladder (Galv)	Unknown	L16	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
129	Access Ladder (AI)	Safemaster	L16	14/10/2018	14/11/2018	14/11/2019	AS1657:2013	Pass	
130	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
131	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
132	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
134	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
135	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
136	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
137	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
138	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
139	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
140	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
141	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
142	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
143	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
145	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
146	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
147	Surfacemount Anchor Point 15Kn	Safemaster	L17	14/10/2018	14/11/2018	14/11/2019	AS1891.4:2009	Pass	
148	Access Ladder (Galv)	Unknown	L18	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
149	Handrail (Al)	Unknown	L18	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
150	Access Ladder (Galv)	Unknown	L20	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
151	Handrail (Al)	Unknown	L20	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
152	Handrail (Al)	Unknown	L22	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
153	Handrail (Al)	Unknown	L24	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
154	Handrail (AI)	Unknown	L27	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Step (Al)	Unknown	L27	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
156	Handrail (Al)	Unknown	L29	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
157	Access Ladder (Galv)	Unknown	L30	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
158	Access Ladder (Galv)	Unknown	L31	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
159	Access Ladder (Galv)	Unknown	L32	Unknown	14/11/2018	14/11/2019	AS1657:2013	Fail	Not in Service Sign Installed
160	Access Ladder (Galv)	Unknown	L32	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
161	Access Ladder (AI)	Unknown	L33	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
162	Access Ladder (AI)	Unknown	L33	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
163	Access Ladder (AI)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
164	Access Ladder (AI)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
165	Access Ladder (AI)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	

31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 EMAIL: inspections@safemaster.net.a

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Homebush

item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Access Ladder (Galv)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
167	Handrail (Galv)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
168	Access Ladder (Galv)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
169	Handrail (Galv)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
170	Access Ladder (Galv)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
171	Handrail (Galv)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
172	Handrail (Galv)	Unknown	L34	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	
173	Handrail (Al)	Unknown	L36	Unknown	14/11/2018	14/11/2019	AS1657:2013	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 14/11/2018

SIGNATURE: JD-+

ADDITIONAL FINDINGS & RECOMMENDATIONS

Table below summarises additional findings and recommendations in support of the Roof Safety Report.

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
88	Building: General Stores Location Reference: <mark>L01</mark> Task: Access to the roof									
		Not enough fixings installed (Anchors no longer required in this area)	Trips, Slips and Falls	Awareness induction	High	Existing anchors to be replaced	Low	Client advised	Outsta nding	OH&S REGULATIONS 3.55
89	Building: General Stores Location Reference: <mark>L04</mark> Task: Access to the roof									
		Headroom is less than required minimum and handrail is missing for ladder	Trips, Slips and Falls	Awareness induction	Med	"Caution-Low Headroom" signs and extendable stiles to be installed	Low	Client advised	Outsta nding	OH&S REGULATIONS 3.7 AS/NZS 1657- 2013 3.1.5

Safemaster Safety Products PH: (08) 6243 3111 Fax: (08) 9456 5014 EMAIL: inspections@safemaster.net.au

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
90	Building: General Stores Location Reference: 10 Task: Access to the roof									
		Variation in height between walkway panels are greater than required maximum	Trips, Slips and Falls	Awareness induction	Med	High visibility safety yellow nosing to be installed	Low	Client advised	Outsta nding	OH&S REGULATIONS 3.7 AS/NZS 1657- 2018 3.3.4
91	Building: General Stores Location Reference: <mark>L26</mark> Task: Access to the roof									
		No safe access to the unit	Trips, Slips and Falls	Awareness induction	Med	Existing handrail to be extended for safe access	Low	Client advised	Outsta nding	OH&S REGULATIONS 3.7 & 3.55

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
92	Building: General Stores Location Reference: <mark>L36</mark> Task: Access to the roof									
		No safe access to the unit	Trips, Slips and Falls	Awareness induction	Med	Handrail to be installed for safe access	Low	Client advised	Outsta nding	OH&S REGULATIONS 3.7 & 3.55



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155 PO Box 1373 Canning Vale WA 6970 Ph: (08) 6243 3111 Fax: (08) 9456 5014 Email: info@safemaster.net.au Web: www.safemaster.net.au