

#### CONFIDENTIALITY/SECURITY

Information obtained from and about Lake Haven Centre, NSW in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Lake Haven Centre, NSW and not to any other source.

### **DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

#### **CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products) 33 Catalano Road, Canning Vale 6155 PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

James Townsend (Recertification Technician)

### Roof Safety Report for

### Lake Haven Centre, NSW 2263

| CLIENT                                  | BUILDINGS INSPECTED | SYSTEMS INSPECTED   |
|---|---------------------|---|
| Vicinity Centres - Lake<br>Haven Centre | Lake Haven Centre   | Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform |

#### **DATE OF INSPECTION**

10/10/2018

#### **INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Lake Haven Centre buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

### **TESTING INSTRUMENT**

Product: HILTI Tester

EMAIL: inspections@safemaster.net.au



### 31-33 Catalano Road, Canning Vale 615: CALL US: (08) 6243 311 EMAIL: inspections@safemaster net al

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location        | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|-----------------|--------------------|------------|-------------------|---------------------|--------|----------|
| 1          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 2          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 3          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 4          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 5          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 6          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 7          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 8          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 9          | Purlin Fix Anchor Point     | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 10         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 11         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster net au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location                | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|-------------------------|--------------------|------------|-------------------|---------------------|--------|----------|
| 12         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof         | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 13         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof         | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 14         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof         | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 15         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof         | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 16         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof         | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 17         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof         | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 18         | Frog Link Anchor Point      | Prevent a Fall             | Woolworths Roof         | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 19         | Surfacemount Anchor Point   | Prevent a Fall             | The Reject Shop<br>Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 20         | Surfacemount Anchor Point   | Prevent a Fall             | The Reject Shop<br>Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 21         | Surfacemount Anchor Point   | Prevent a Fall             | The Reject Shop<br>Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 22         | Surfacemount Anchor Point   | Prevent a Fall             | The Reject Shop<br>Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### 31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 FMAII : inspections@safemaster.net.a

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location                | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|-------------------------|--------------------|------------|-------------------|---------------------|--------|----------|
| 23         | Surfacemount Anchor Point   | Prevent a Fall             | The Reject Shop<br>Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 24         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 25         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 26         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 27         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 28         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 29         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 30         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 31         | Surfacemount Anchor Point   | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 32         | Purlin Fix Anchor Point     | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 33         | Purlin Fix Anchor Point     | Prevent a Fall             | Aldi Roof               | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### l-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

### CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Prevent a Fall

Main Roof

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location  | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|-----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 34         | Purlin Fix Anchor Point     | Prevent a Fall             | Aldi Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 35         | Purlin Fix Anchor Point     | Prevent a Fall             | Aldi Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 36         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 37         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 38         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 39         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 40         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 41         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 42         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 43         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

10/10/2018

10/10/2019

AS1891.4:2009

Pass

1/11/2007

Purlin Fix Anchor Point

#### l-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location  | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|-----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 45         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 46         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 47         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 48         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 49         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 50         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 51         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 52         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 53         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 54         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 55         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### -33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location  | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|-----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 56         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 57         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 58         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 59         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 60         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 61         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 62         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 63         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 64         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 65         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 66         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### 31-33 Catalano Road, Canning Vale 615 CALL US: (08) 6243 31 FMAIL: inspections@safemaster pet a

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location     | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|--------------|--------------------|------------|-------------------|---------------------|--------|----------|
| 67         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof    | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 68         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof    | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 69         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof    | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 70         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof    | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 71         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof    | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 72         | Purlin Fix Anchor Point     | Prevent a Fall             | Main Roof    | 1/11/2007          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 73         | Horizontal Static Line      | SAFEMASTER                 | L46          | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 74         | Harness                     | B Safe                     | BH01112      | 1/09/2011          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 75         | Lanyard                     | B Safe                     | BL01112      | 1/09/2011          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 76         | Harness                     | Spanset                    | EH0045514095 | 1/07/2011          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 77         | Lanyard                     | Spanset                    | EH0045514095 | 1/07/2011          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

### 31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

Job Ref: SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 78         | Harness                     | RIS                        | 2009-08L | 1/08/2009          | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 79         | Access Ladder (AI)          | Unknown                    | L2       | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 80         | Access Ladder (AI)          | Unknown                    | L3       | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 81         | Guardrail (Al)              | Unknown                    | L3       | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 82         | Access Ladder (AI)          | Unknown                    | L4       | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 83         | Guardrail (Al)              | Unknown                    | L4       | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 84         | Access Ladder (AI)          | Unknown                    | L8       | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 85         | Step (AI)                   | Unknown                    | L9       | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 86         | Step (AI)                   | Unknown                    | L9       | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 87         | Step (AI)                   | Unknown                    | L10      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 88         | Access Ladder (AI)          | Unknown                    | L10      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 89         | Access Ladder (AI)          | Unknown                    | L11      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 90         | Access Ladder (AI)          | Unknown                    | L12      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 91         | Access Ladder (Al)          | Unknown                    | L15      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 92         | Access Ladder (Al)          | Unknown                    | L16      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 93         | Access Stair (Galv)         | Unknown                    | L17      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 94         | Guardrail (Galv)            | Unknown                    | L17      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 95         | Access Ladder (Al)          | Unknown                    | L18      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 96         | Access Ladder (Al)          | Unknown                    | L19      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 97         | Access Ladder (AI)          | Unknown                    | L21      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 98         | Access Ladder (AI)          | Unknown                    | L22      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 99         | Step (AI)                   | Unknown                    | L22      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |

#### -33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 - MAII : inspections@safemaster net au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 100        | Access Ladder (AI)          | Unknown                    | L23      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 101        | Step (AI)                   | Unknown                    | L23      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 102        | Access Ladder (AI)          | Unknown                    | L25      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 103        | Guardrail (Galv)            | Unknown                    | L25      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 104        | Access Ladder (Al)          | Unknown                    | L25      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 105        | Step (AI)                   | Unknown                    | L25      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 106        | Step (AI)                   | Unknown                    | L26      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 107        | Access Ladder (AI)          | Unknown                    | L27      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 108        | Access Ladder (Galv)        | Unknown                    | L30      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 109        | Step (AI)                   | Unknown                    | L30      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 110        | Step (AI)                   | Unknown                    | L31      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 111        | Access Ladder (AI)          | Unknown                    | L32      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 112        | Access Stair (Galv)         | Unknown                    | L32      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 113        | Access Ladder (Galv)        | Unknown                    | L36      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 114        | Step (AI)                   | Unknown                    | L36      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 115        | Access Ladder (AI)          | Unknown                    | L38      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 116        | Access Ladder (AI)          | Unknown                    | L39      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 117        | Access Ladder (Al)          | Unknown                    | L40      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 118        | Access Ladder (Al)          | Unknown                    | L41      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 119        | Guardrail (Al)              | Unknown                    | L41      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 120        | Guardrail (Galv)            | Unknown                    | L41      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 121        | Step (AI)                   | Unknown                    | L43      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |

#### i1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII: inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 122        | Access Ladder (AI)          | Unknown                    | L45      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 123        | Access Ladder (AI)          | Unknown                    | L46      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 124        | Access Ladder (AI)          | Unknown                    | L47      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 125        | Access Ladder (AI)          | Unknown                    | L48      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 126        | Access Ladder (AI)          | Unknown                    | L49      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 127        | Guardrail (Galv)            | Unknown                    | L49      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 128        | Step (AI)                   | Unknown                    | L49      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 129        | Step (AI)                   | Unknown                    | L50      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 130        | Step (AI)                   | Unknown                    | L50      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 131        | Step (AI)                   | Unknown                    | L51      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 132        | Access Ladder (AI)          | Unknown                    | L51      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 133        | Step (AI)                   | Unknown                    | L52      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 134        | Access Ladder (AI)          | Unknown                    | L52      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 135        | Access Ladder (AI)          | Unknown                    | L54      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 136        | Access Ladder (AI)          | Unknown                    | L55      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 137        | Access Ladder (AI)          | Unknown                    | L58      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 138        | Access Ladder (AI)          | Unknown                    | L59      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 139        | Access Ladder (AI)          | Unknown                    | L60      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 140        | Access Ladder (AI)          | Unknown                    | L61      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 141        | Access Ladder (AI)          | Unknown                    | L62      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 142        | Access Ladder (AI)          | Unknown                    | L63      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 143        | Access Ladder (AI)          | Unknown                    | L64      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster net au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 144        | Handrail (Al)               | Unknown                    | L67      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 145        | Handrail (Al)               | Unknown                    | L67      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 146        | Access Ladder (AI)          | Unknown                    | L67      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 147        | Access Ladder (AI)          | Unknown                    | L69      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 148        | Handrail (Al)               | Unknown                    | L69      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 149        | Access Ladder (Galv)        | Unknown                    | L70      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 150        | Access Ladder (AI)          | Unknown                    | L72      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 151        | Handrail (Galv)             | Unknown                    | L72      | Unknown            | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 152        | Access Ladder (AI)          | Unknown                    | L73      | Unknown            | 10/10/2018 | 10/10/2019        | AS1657-2013         | Fail   |          |
| 153        | Access Ladder (AI)          | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 154        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAII : inspections@safemaster net au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre
Job Ref: SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 155        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 156        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 157        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 158        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 159        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 160        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 161        | Surfacemount Anchor Point   | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 162        | Anchor Strop                | SAFEMASTER                 | L14      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 163        | Surfacemount Anchor Point   | SAFEMASTER                 | L18      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 164        | Surfacemount Anchor Point   | SAFEMASTER                 | L18      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 165        | Surfacemount Anchor Point   | SAFEMASTER                 | L18      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

### 31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au.

### CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre
Job Ref: SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 166        | Surfacemount Anchor Point   | SAFEMASTER                 | L18      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 167        | Surfacemount Anchor Point   | SAFEMASTER                 | L28      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 168        | Surfacemount Anchor Point   | SAFEMASTER                 | L28      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 169        | Surfacemount Anchor Point   | SAFEMASTER                 | L30      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 170        | Surfacemount Anchor Point   | SAFEMASTER                 | L30      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 171        | Surfacemount Anchor Point   | SAFEMASTER                 | L30      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 172        | Surfacemount Anchor Point   | SAFEMASTER                 | L41      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 173        | Surfacemount Anchor Point   | SAFEMASTER                 | L63      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 174        | Surfacemount Anchor Point   | SAFEMASTER                 | L63      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 175        | Surfacemount Anchor Point   | SAFEMASTER                 | L63      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 176        | Surfacemount Anchor Point   | SAFEMASTER                 | L63      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAII : inspections@safemaster net au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre
Job Ref: SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 177        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 178        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 179        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 180        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 181        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 182        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 183        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 184        | Surfacemount Anchor Point   | SAFEMASTER                 | L64      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 185        | Surfacemount Anchor Point   | SAFEMASTER                 | L65      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 186        | Surfacemount Anchor Point   | SAFEMASTER                 | L65      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 187        | Surfacemount Anchor Point   | SAFEMASTER                 | L65      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### 31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster net au

### CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre
Job Ref: SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 188        | Handrail (Al)               | SAFEMASTER                 | L67      | 15/05/2018         | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 189        | Surfacemount Anchor Point   | SAFEMASTER                 | L68      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 190        | Surfacemount Anchor Point   | SAFEMASTER                 | L68      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 191        | Surfacemount Anchor Point   | SAFEMASTER                 | L69      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 192        | Surfacemount Anchor Point   | SAFEMASTER                 | L69      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 193        | Surfacemount Anchor Point   | SAFEMASTER                 | L69      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 194        | Surfacemount Anchor Point   | SAFEMASTER                 | L69      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 195        | Surfacemount Anchor Point   | SAFEMASTER                 | L69      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 196        | Surfacemount Anchor Point   | SAFEMASTER                 | L69      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 197        | Surfacemount Anchor Point   | SAFEMASTER                 | L69      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 198        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### l-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 199        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 200        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 201        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 202        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 203        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 204        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 205        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 206        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 207        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 208        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 209        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### 1-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster net au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 210        | Surfacemount Anchor Point   | SAFEMASTER                 | L70      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 211        | Surfacemount Anchor Point   | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 212        | Surfacemount Anchor Point   | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 213        | Surfacemount Anchor Point   | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 214        | Surfacemount Anchor Point   | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 215        | Surfacemount Anchor Point   | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 216        | Surfacemount Anchor Point   | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 217        | Surfacemount Anchor Point   | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 218        | Anchor Strop                | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 219        | Ladder access bracket       | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 220        | Sign                        | SAFEMASTER                 | L71      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

#### l-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 FMAII : inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 221        | Concrete Fix Anchor Point   | SAFEMASTER                 | L72      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 222        | Concrete Fix Anchor Point   | SAFEMASTER                 | L72      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 223        | Concrete Fix Anchor Point   | SAFEMASTER                 | L72      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 224        | Concrete Fix Anchor Point   | SAFEMASTER                 | L72      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 225        | Concrete Fix Anchor Point   | SAFEMASTER                 | L72      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 226        | Handrail (Al)               | SAFEMASTER                 | L75      | 15/05/2018         | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 227        | Surfacemount Anchor Point   | SAFEMASTER                 | L75      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 228        | Surfacemount Anchor Point   | SAFEMASTER                 | L75      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 229        | Surfacemount Anchor Point   | SAFEMASTER                 | L75      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 230        | Surfacemount Anchor Point   | SAFEMASTER                 | L75      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 231        | Surfacemount Anchor Point   | SAFEMASTER                 | L75      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |

### CERTIFICATE OF COMPLIANCE INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 615.

CALL US: (08) 6243 311

**Client:** Vicinity Centre

**Job Ref:** SM12182

Site: Lake Haven Cente - NSW

| Item<br>No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission<br>Date | Insp Date  | Next Insp<br>Date | Complying Standards | Status | Comments |
|------------|-----------------------------|----------------------------|----------|--------------------|------------|-------------------|---------------------|--------|----------|
| 232        | Surfacemount Anchor Point   | SAFEMASTER                 | L75      | 15/05/2018         | 10/10/2018 | 10/10/2019        | AS1891.4:2009       | Pass   |          |
| 233        | Handrail (Al)               | Unknown                    | L5       | 15/05/2018         | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 234        | Handrail (Al)               | Unknown                    | L5       | 15/05/2018         | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 235        | Handrail (Al)               | Unknown                    | L6       | 15/05/2018         | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
| 236        | Access Ladder (Al)          | Unknown                    | L6       | 15/05/2018         | 10/10/2018 | N/A               | AS1657-2013         | Pass   |          |
|            |                             |                            |          |                    |            |                   |                     |        |          |

AUTHORISED BY: JAMES TOWNSEND

DATE: 10/10/2018

SIGNATURE:

### **Lake Haven Centre, NSW 2263**

### **ADDITIONAL FINDINGS & RECOMMENDATIONS**

Table below summarises additional findings and recommendations in support of the Roof Safety Report.

| No      | Photo of Hazard   | Details of Hazard            | Details of Risk           | Existing/<br>Immediate<br>Control<br>Measure | Curren<br>t Risk<br>Level | Proposed Permanent<br>Solution  | Residu<br>al Risk<br>Assess<br>ment | Details of<br>Action<br>Taken | Status          | Reference |
|---------|---|------------------------------|---------------------------|--|---------------------------|---------------------------------|-------------------------------------|-------------------------------|-----------------|-----------|
| 22<br>7 | Building: General Stores<br>Location Reference: LO6<br>Task: Access to the ladder |                              |                           |  |                           |                                 |                                     |                               |                 |           |
|         |   | No safe access to the ladder | Trips, Slips<br>and Falls | N/A  | Low                       | Supply walkway to<br>the ladder | Low                                 | Client<br>advised             | Outsta<br>nding | _         |

EMAIL: inspections@safemaster.net.au



### **Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155 PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111 Fax: (08) 9456 5014

Email: info@safemaster.net.au Web: www.safemaster.net.au