

# Roof Safety Report

**Mildura Central Shopping  
Centre, VIC 3500**

Prepared By: Safemaster Safety Products  
Date: 4 Feb 2019

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Mildura Central Shopping Centre, VIC in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Mildura Central Shopping Centre and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)  
31-33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:



**James Townsend (Recertification Technician)**

Roof Safety Report for  
**Mildura Central Shopping Centre, VIC 3500**

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Mildura Central Shopping Centre	Corner 15th Street and Deakin Avenue, Mildura VIC 3500	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

---

**DATE OF INSPECTION**

06/12/2018

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Mildura Central buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

Product: HILTI Tester



# **Inspection Log**

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
2	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
3	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
4	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
5	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
6	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
7	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
8	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
9	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
10	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
11	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
13	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
14	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
15	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
16	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
17	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
18	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
19	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
20	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
21	Surfacemount Staticline Support Bracket	Advavnced Roof Safety	Woolworths Roof	27/01/2016	6/12/2018	6/12/2019	AS1891.4:2009	Fail	Static Line Cable Missing
22	Handrail	Unknown	Main Roof	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Surfacemount Anchor Point	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
25	Surfacemount Anchor Point	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
30	Access Ladder (AI)	Unknown	L01	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
31	Guardrail (AI)	Unknown	L01	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
32	Access Ladder (AI)	Safemaster	L01	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
33	Handrail (AI)	Safemaster	L02	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Access Ladder (Al)	Safemaster	L02	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
35	Step (Al)	Unknown	L02	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
36	Handrail (Al)	Safemaster	L03	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
37	Step (Al)	Unknown	L03	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
38	Step (Al)	Safemaster	L03	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
39	Step (Al)	Safemaster	L03	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
40	Stair (Galv)	Unknown	L04	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
41	Handrail (Al)	Safemaster	L04	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
42	Stair (Al)	Unknown	L05	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
43	Guardrail (Al)	Unknown	L05	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
44	Step (Al)	Safemaster	L06	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Step (AI)	Safemaster	L06	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
46	Access Ladder (AI)	Safemaster	L07	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
47	Step (AI)	Safemaster	L07	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
48	Handrail (AI)	Safemaster	L07	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
49	Stair (AI)	Safemaster	L08	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
50	Guardrail (AI)	Safemaster	L08	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
51	Access Ladder (AI)	Unknown	L10	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
52	Guardrail (AI)	Unknown	L10	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
53	Access Ladder (AI)	Unknown	L10	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
54	Guardrail (AI)	Unknown	L10	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
55	Step Over (AI)	Safemaster	L10	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Step Over (Al)	Safemaster	L10	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
57	Access Ladder (Al)	Unknown	L11	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
58	Guardrail (Al)	Unknown	L11	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
59	Step (Al)	Safemaster	L12	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
60	Access Ladder (Al)	Unknown	L12	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
61	Guardrail (Al)	Unknown	L12	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
62	Access Ladder (Al)	Safemaster	L13	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
63	Guardrail (Galv)	Unknown	L13	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	
64	Step (Al)	Safemaster	L13	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
65	Handrail (Al)	Safemaster	L13	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
66	Guardrail (Galv)	Unknown	L14	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Guardrail (AI)	Unknown	L16	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
68	Step (AI)	Safemaster	L17	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
69	Guardrail (AI)	Unknown	L17	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
70	Guardrail (AI)	Unknown	L17	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
71	Surfacemount Anchor Point	Safemaster	L17	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
72	Surfacemount Anchor Point	Safemaster	L17	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
73	Surfacemount Anchor Point	Safemaster	L17	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
74	Surfacemount Anchor Point	Safemaster	L17	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
75	Access Ladder (AI)	Unknown	L19	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
76	Surfacemount Anchor Point	Safemaster	L20	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
77	Surfacemount Anchor Point	Safemaster	L20	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Surfacemount Anchor Point	Safemaster	L20	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
79	Surfacemount Anchor Point	Safemaster	L20	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
80	Anchor Strop	Safemaster	L20	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
81	Access Ladder (AI)	Safemaster	L20	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
82	Step (AI)	Safemaster	L21	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
83	Step (AI)	Safemaster	L21	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
84	Step (AI)	Safemaster	L21	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
85	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
86	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
87	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
88	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
90	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
91	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
92	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
93	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
94	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
95	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
96	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
97	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
98	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
99	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
101	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
102	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
103	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
104	Surfacemount Anchor Point	Safemaster	L22	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
105	Surfacemount Anchor Point	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
106	Surfacemount Anchor Point	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
107	Surfacemount Anchor Point	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
108	Surfacemount Anchor Point	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
109	Anchor Strop	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
110	Access Ladder (AL)	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Stair (AI)	Unknown	L24	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
112	Guardrail (AI)	Safemaster	L24	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
113	Stair (AI)	Unknown	L25	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
114	Guardrail (AI)	Safemaster	L25	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
115	Stair (AI)	Unknown	L26	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
116	Step Over (AI)	Safemaster	L26	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
117	Guardrail (AI)	Safemaster	L26	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
118	Guardrail (AI)	Unknown	L27	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
119	Stair (AI)	Unknown	L28	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
120	Guardrail (AI)	Safemaster	L28	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
121	Step Over (AI)	Safemaster	L28	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Stair (AI)	Unknown	L29	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
123	Guardrail (AI)	Safemaster	L29	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
124	Stair (AI)	Unknown	L30	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
125	Stair (AI)	Unknown	L30	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
126	Guardrail (AI)	Safemaster	L30	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
127	Step (AI)	Safemaster	L30	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
128	Step Over (AI)	Safemaster	L31	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
129	Guardrail (AI)	Safemaster	L31	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
130	Step Over (AI)	Safemaster	L31	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
131	Stair (AI)	Unknown	L31	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
132	Guardrail (AI)	Safemaster	L31	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Surfacemount Anchor Point	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
134	Surfacemount Anchor Point	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
135	Surfacemount Anchor Point	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
136	Surfacemount Staticline	Safemaster	L23	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
137	Step Over (AI)	Safemaster	L34	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
138	Access Ladder (AI)	Unknown	L34	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
139	Surfacemount Anchor Point	Safemaster	L35	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
140	Surfacemount Anchor Point	Safemaster	L35	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
141	Surfacemount Anchor Point	Safemaster	L35	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
142	Surfacemount Anchor Point	Safemaster	L35	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
143	Access Ladder (AI)	Unknown	L35	Unknown	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Stair (Al)	Unknown	L36	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
145	Guardrail (Al)	Safemaster	L36	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
146	Stair (Al)	Unknown	L37	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
147	Guardrail (Al)	Safemaster	L37	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
148	Guardrail (Al)	Safemaster	L39	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
149	Guardrail (Al)	Safemaster	L40	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	
150	Surfacemount Anchor Point	Safemaster	L41	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
151	Surfacemount Anchor Point	Safemaster	L41	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
152	Surfacemount Anchor Point	Safemaster	L41	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
153	Surfacemount Anchor Point	Safemaster	L41	30/10/2018	6/12/2018	6/12/2019	AS1891.4:2009	Pass	
154	Access Ladder (Galv)	Unknown	L42	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182


**Site:** Mildura Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Access Ladder (Galv)	Unknown	L42	30/10/2018	6/12/2018	6/12/2019	AS1657:2013	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 06/12/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)