

# Roof Safety Report

**Mildura Central Shopping  
Centre, VIC 3500**

Prepared By: Safemaster Safety Products  
Date: 10-01-2020

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Mildura Central Shopping Centre, VIC in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Mildura Central Shopping Centre and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)  
31-33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:



**James Townsend (Recertification Technician)**

Roof Safety Report for  
**Mildura Central Shopping Centre, VIC 3500**

---

| CLIENT  | BUILDINGS INSPECTED                                       | SYSTEMS INSPECTED  |
|---|---|--|
| Vicinity Centres - Mildura<br>Central Shopping Centre | Corner 15th Street and Deakin<br>Avenue, Mildura VIC 3500 | Signage<br>Anchor Points<br>Ladder Bracket<br>Landings<br>Hatch<br>Guardrail<br>Ladder<br>Stair<br>Static Line<br>Mechanical Platform<br>Roof Walkway<br>A/C Safe Working Platform |

---

**DATE OF INSPECTION**

06/12/2019

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Mildura Central buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

Product: HILTI Tester





# Inspection Log

Roof Safety Report for  
**Mildura Central Shopping Centre, VIC 3500**



**ADDITIONAL FINDINGS & RECOMMENDATIONS**

Table below summarises additional findings and recommendations in support of the Roof Safety Report.

| No  | Photo of Hazard  | Details of Hazard               | Details of Risk        | Existing/<br>Immediate<br>Control<br>Measure | Current<br>Risk<br>Level | Proposed Permanent<br>Solution  | Residual<br>Risk<br>Assessment | Details of<br>Action<br>Taken | Status      | Reference |
|-----|--|---------------------------------|------------------------|--|--------------------------|---------------------------------|--------------------------------|-------------------------------|-------------|-----------|
| 121 | Building: General Stores<br>Location Reference: <a href="#">L20</a><br>Task: Access to the roof      |                                 |                        |  |                          |                                 |                                |                               |             |           |
|     |                     | No safe access to the ladder    | Trips, Slips and Falls | Awareness induction                          | Low                      | Supply walkway to the ladder    | Low                            | Client advised                | Outstanding | -         |
| 122 | Building: General Stores<br>Location Reference: <a href="#">L04</a><br>Task: Access to the A/c units |                                 |                        |  |                          |                                 |                                |                               |             |           |
|     |                    | No safe access to the A/c units | Trips, Slips and Falls | Awareness induction                          | Low                      | Supply walkway to the A/c units | Low                            | Client advised                | Outstanding | -         |




Roof Safety Report for  
**Mildura Central Shopping Centre, VIC 3500**

| No  | Photo of Hazard   | Details of Hazard                 | Details of Risk        | Existing/<br>Immediate<br>Control<br>Measure | Curren<br>t Risk<br>Level | Proposed Permanent<br>Solution               | Residu<br>al Risk<br>Assess<br>ment | Details of<br>Action<br>Taken | Status      | Reference             |
|-----|---|-----------------------------------|------------------------|--|---------------------------|--|-------------------------------------|-------------------------------|-------------|-----------------------|
| 123 | Building: General Stores<br>Location Reference: <a href="#">L23</a><br>Task: Access to the roof |                                   |                        |  |                           |  |                                     |                               |             |                       |
|     |                | No safe access to the ladder      | Trips, Slips and Falls | Awareness induction                          | Low                       | Supply walkway and step bridge to the ladder | Low                                 | Client advised                | Outstanding | -                     |
| 124 | Building: General Stores<br>Location Reference: <a href="#">L23</a><br>Task: Access to the roof |                                   |                        |  |                           |  |                                     |                               |             |                       |
|     |               | No height safety system installed | Trips, Slips and Falls | Awareness induction                          | High                      | Anchors to be installed                      | Low                                 | Client advised                | Outstanding | OH&S REGULATIONS 3.55 |

Roof Safety Report for  
**Mildura Central Shopping Centre, VIC 3500**

---

| No  | Photo of Hazard  | Details of Hazard               | Details of Risk        | Existing/<br>Immediate<br>Control<br>Measure | Curren<br>t Risk<br>Level | Proposed Permanent<br>Solution  | Residu<br>al Risk<br>Assess<br>ment | Details of<br>Action<br>Taken | Status      | Reference |
|-----|--|---------------------------------|------------------------|--|---------------------------|---------------------------------|-------------------------------------|-------------------------------|-------------|-----------|
| 125 | Building: General Stores<br>Location Reference: <a href="#">L26</a><br>Task: Access to the A/c units |                                 |                        |  |                           |                                 |                                     |                               |             |           |
|     |                     | No safe access to the A/c units | Trips, Slips and Falls | Awareness induction                          | Low                       | Supply walkway to the A/c units | Low                                 | Client advised                | Outstanding | -         |

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description             | Manufacturer/ Installer | Location        | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments                  |
|---------|---|-------------------------|-----------------|-----------------|-----------|----------------|---------------------|--------|---------------------------|
| 1       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 2       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 3       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 4       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 5       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 6       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 7       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 8       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 9       | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 10      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 11      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description             | Manufacturer/ Installer | Location        | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments                  |
|---------|---|-------------------------|-----------------|-----------------|-----------|----------------|---------------------|--------|---------------------------|
| 12      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 13      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 14      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 15      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 16      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 17      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 18      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 19      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 20      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 21      | Surfacemount Staticline Support Bracket | Advavnced Roof Safety   | Woolworths Roof | 27/01/2016      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Fail   | Static Line Cable Missing |
| 22      | Handrail                                | Unknown                 | Main Roof       | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |                           |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 23      | Surfacemount Anchor Point   | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 24      | Surfacemount Anchor Point   | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 25      | Surfacemount Anchor Point   | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 26      | Surfacemount Anchor Point   | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 27      | Surfacemount Anchor Point   | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 28      | Surfacemount Anchor Point   | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 29      | Surfacemount Anchor Point   | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 30      | Access Ladder (AI)          | Unknown                 | L01      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 31      | Guardrail (AI)              | Unknown                 | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 32      | Access Ladder (AI)          | Safemaster              | L01      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 33      | Handrail (AI)               | Safemaster              | L02      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 34      | Access Ladder (AI)          | Safemaster              | L02      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 35      | Step (AI)                   | Unknown                 | L02      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 36      | Handrail (AI)               | Safemaster              | L03      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 37      | Step (AI)                   | Unknown                 | L03      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 38      | Step (AI)                   | Safemaster              | L03      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 39      | Step (AI)                   | Safemaster              | L03      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 40      | Stair (Galv)                | Unknown                 | L04      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 41      | Handrail (AI)               | Safemaster              | L04      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 42      | Stair (AI)                  | Unknown                 | L05      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 43      | Guardrail (AI)              | Unknown                 | L05      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 44      | Step (AI)                   | Safemaster              | L06      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 45      | Step (AI)                   | Safemaster              | L06      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 46      | Access Ladder (AI)          | Safemaster              | L07      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 47      | Step (AI)                   | Safemaster              | L07      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 48      | Handrail (AI)               | Safemaster              | L07      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 49      | Stair (AI)                  | Safemaster              | L08      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 50      | Guardrail (AI)              | Safemaster              | L08      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 51      | Access Ladder (AI)          | Unknown                 | L10      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 52      | Guardrail (AI)              | Unknown                 | L10      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 53      | Access Ladder (AI)          | Unknown                 | L10      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 54      | Guardrail (AI)              | Unknown                 | L10      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 55      | Step Over (AI)              | Safemaster              | L10      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 56      | Step Over (Al)              | Safemaster              | L10      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 57      | Access Ladder (Al)          | Unknown                 | L11      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 58      | Guardrail (Al)              | Unknown                 | L11      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 59      | Step (Al)                   | Safemaster              | L12      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 60      | Access Ladder (Al)          | Unknown                 | L12      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 61      | Guardrail (Al)              | Unknown                 | L12      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 62      | Access Ladder (Al)          | Safemaster              | L13      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 63      | Guardrail (Galv)            | Unknown                 | L13      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 64      | Step (Al)                   | Safemaster              | L13      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 65      | Handrail (Al)               | Safemaster              | L13      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 66      | Guardrail (Galv)            | Unknown                 | L14      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 67      | Guardrail (AI)              | Unknown                 | L16      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 68      | Step (AI)                   | Safemaster              | L17      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 69      | Guardrail (AI)              | Unknown                 | L17      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 70      | Guardrail (AI)              | Unknown                 | L17      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 71      | Surfacemount Anchor Point   | Safemaster              | L17      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 72      | Surfacemount Anchor Point   | Safemaster              | L17      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 73      | Surfacemount Anchor Point   | Safemaster              | L17      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 74      | Surfacemount Anchor Point   | Safemaster              | L17      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 75      | Access Ladder (AI)          | Unknown                 | L19      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 76      | Surfacemount Anchor Point   | Safemaster              | L20      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 77      | Surfacemount Anchor Point   | Safemaster              | L20      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 78      | Surfacemount Anchor Point   | Safemaster              | L20      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 79      | Surfacemount Anchor Point   | Safemaster              | L20      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 80      | Anchor Strop                | Safemaster              | L20      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 81      | Access Ladder (Al)          | Safemaster              | L20      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 82      | Step (Al)                   | Safemaster              | L21      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 83      | Step (Al)                   | Safemaster              | L21      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 84      | Step (Al)                   | Safemaster              | L21      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 85      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 86      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 87      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 88      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 89      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 90      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 91      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 92      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 93      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 94      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 95      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 96      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 97      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 98      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 99      | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 100     | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 101     | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 102     | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 103     | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 104     | Surfacemount Anchor Point   | Safemaster              | L22      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 105     | Surfacemount Anchor Point   | Safemaster              | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 106     | Surfacemount Anchor Point   | Safemaster              | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 107     | Surfacemount Anchor Point   | Safemaster              | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 108     | Surfacemount Anchor Point   | Safemaster              | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 109     | Anchor Strop                | Safemaster              | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 110     | Access Ladder (Al)          | Safemaster              | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 111     | Stair (AI)                  | Unknown                 | L24      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 112     | Guardrail (AI)              | Safemaster              | L24      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 113     | Stair (AI)                  | Unknown                 | L25      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 114     | Guardrail (AI)              | Safemaster              | L25      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 115     | Stair (AI)                  | Unknown                 | L26      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 116     | Step Over (AI)              | Safemaster              | L26      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 117     | Guardrail (AI)              | Safemaster              | L26      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 118     | Guardrail (AI)              | Unknown                 | L27      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 119     | Stair (AI)                  | Unknown                 | L28      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 120     | Guardrail (AI)              | Safemaster              | L28      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 121     | Step Over (AI)              | Safemaster              | L28      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 122     | Stair (AI)                  | Unknown                 | L29      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 123     | Guardrail (AI)              | Safemaster              | L29      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 124     | Stair (AI)                  | Unknown                 | L30      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 125     | Stair (AI)                  | Unknown                 | L30      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 126     | Guardrail (AI)              | Safemaster              | L30      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 127     | Step (AI)                   | Safemaster              | L30      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 128     | Step Over (AI)              | Safemaster              | L31      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 129     | Guardrail (AI)              | Safemaster              | L31      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 130     | Step Over (AI)              | Safemaster              | L31      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 131     | Stair (AI)                  | Unknown                 | L31      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 132     | Guardrail (AI)              | Safemaster              | L31      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/<br>Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|----------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 133     | Surfacemount Anchor Point   | Safemaster                 | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 134     | Surfacemount Anchor Point   | Safemaster                 | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 135     | Surfacemount Anchor Point   | Safemaster                 | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 136     | Surfacemount Staticline     | Safemaster                 | L23      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 137     | Step Over (AI)              | Safemaster                 | L34      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 138     | Access Ladder (AI)          | Unknown                    | L34      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 139     | Surfacemount Anchor Point   | Safemaster                 | L35      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 140     | Surfacemount Anchor Point   | Safemaster                 | L35      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 141     | Surfacemount Anchor Point   | Safemaster                 | L35      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 142     | Surfacemount Anchor Point   | Safemaster                 | L35      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 143     | Access Ladder (AI)          | Unknown                    | L35      | Unknown         | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Mildura Central

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 144     | Stair (Al)                  | Unknown                 | L36      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 145     | Guardrail (Al)              | Safemaster              | L36      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 146     | Stair (Al)                  | Unknown                 | L37      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 147     | Guardrail (Al)              | Safemaster              | L37      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 148     | Guardrail (Al)              | Safemaster              | L39      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 149     | Guardrail (Al)              | Safemaster              | L40      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |
| 150     | Surfacemount Anchor Point   | Safemaster              | L41      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 151     | Surfacemount Anchor Point   | Safemaster              | L41      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 152     | Surfacemount Anchor Point   | Safemaster              | L41      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 153     | Surfacemount Anchor Point   | Safemaster              | L41      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS1891.4:2009       | Pass   |          |
| 154     | Access Ladder (Galv)        | Unknown                 | L42      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182


**Site:** Mildura Central

| Item No | Equipment Type& Description | Manufacturer/ Installer | Location | Commission Date | Insp Date | Next Insp Date | Complying Standards | Status | Comments |
|---------|-----------------------------|-------------------------|----------|-----------------|-----------|----------------|---------------------|--------|----------|
| 155     | Access Ladder (Galv)        | Unknown                 | L42      | 30/10/2018      | 6/12/2019 | 6/12/2020      | AS 1657:2018        | Pass   |          |

AUTHORISED BY: JAMES TOWNSEND

DATE: 06/12/2019

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)