

#### CONFIDENTIALITY/SECURITY

Information obtained from and about Dandalup North Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Dandalup North Primary School and not to any other source.

#### **DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

#### **CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products) 33 Catalano Road, Canning Vale 6155 PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

Trevor Harris (Recertification Technician)

EMAIL: inspections@safemaster.net.au

### Roof Safety Report for Dandalup North Primary School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Library	Anchor Points Signage

#### DATE OF INSPECTION

16/04/18

#### INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Dandalup North Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

EMAIL: inspections@safemaster.net.au



# **CERTIFICATE OF COMPLIANCE**

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

## **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

Client: BMW Bunbury
Job Ref: SM 12846

Site: Dandalup North Priary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	Safemaster	Library	1/06/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	Safemaster	Library	1/06/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	Safemaster	Library	1/06/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	Safemaster	Library	1/06/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
5	Sign	Safemaster	Library	21/04/2017	17/04/2018	17/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 16/04/2018

SIGNATURE:

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## **Compliance Requirements**

Item No	Location	Recommendations
	Library	Ladder Bracket to be installed.

 ${\it EMAIL: inspections@safemaster.net.au}$ 



Safemaster Safety Products 31-33 Catalano Road, Canning Vale WA 6155 PO Box 1373 Canning Vale WA 6970 Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au Web: www.safemaster.net.au