

Roof Safety Report

30 South Beach, North Coogee

Prepared By: Safemaster Safety Products
Date: 06/10/2017

Roof Safety Report for
30 South Beach, North Coogee

CONFIDENTIALITY/SECURITY

Information obtained from and about 30 South Beach, North Coogee in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to 30 South Beach, North Coogee and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

A handwritten signature in black ink, appearing to be 'Jb' followed by a stylized horizontal line and a vertical stroke.

James Townsend (Recertification Technician)

Roof Safety Report for
30 South Beach, North Coogee

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
City of Gosnells	30 South Beach, North Coogee	Anchor Points Signage Access Ladder Hatch Walkway

DATE OF INSPECTION

06/10/2017

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on 30 South Beach, North Coogee buildings.

The inspection is based on:

- WA OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 5869

Site: 30 South Beach, North Coogee

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 5869

Site: 30 South Beach, North Coogee

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point 21kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
17	Purlin Fix Abseil Anchor Point 15kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
18	Purlin Fix Abseil Anchor Point 15kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
19	Purlin Fix Abseil Anchor Point 15kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
20	Purlin Fix Abseil Anchor Point 15kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
21	Purlin Fix Abseil Anchor Point 15kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
22	Purlin Fix Abseil Anchor Point 15kn	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
23	Access Ladder	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1657:2013	Pass	
24	Walkway	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 5869

Site: 30 South Beach, North Coogee

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Access Hatch	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018		Pass	
26	Signage	Safemaster	Upper Roof	1/04/2012	6/10/2017	6/10/2018	AS1319:1994 AS1891.4-2009	Pass	
27	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
34	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 5869

Site: 30 South Beach, North Coogee

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
45	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
46	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
47	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	
48	Purlin Fix Anchor Point 21kn	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Logiudice

Job Ref: SM 5869


Site: 30 South Beach, North Coogee

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Access Ladder	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1657:2013	Pass	
50	Access Hatch	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018		Pass	
51	Signage	Safemaster	Lower Roof	1/04/2012	6/10/2017	6/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 06/10/2017

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Roof Safety Report for 30 South Beach, North Coogee

COMPLIANT REQUIREMENTS

There are no recommendations at this point in time.

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au