

# Roof Safety Report

**Velo Apartments** 

Prepared By: Safemaster Safety Products Date: 05/03/2019

#### **CONFIDENTIALITY/SECURITY**

Information obtained from and about Velo Apartments in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Velo Apartments and not to any other source.

#### DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

#### **CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tyron Menikides (Safemaster Safety Products) 33 Catalano Road, Canning Vale 6155 PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

Alle

Tyron Menikides (Height Safety Inspector)

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Logiudice	Velo Apartments	Anchor Points Signage Access Hatch

#### DATE OF INSPECTION

05/03/2019

#### **INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Velo Apartments buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Client:LogiudiceJob Ref:SM 10672Site:Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Roof Access Hatch 600x600	Unknown / Unknown	Main Roof	Unknown	5/03/2019	5/03/2020	AS1657:2018	Non- Complia nt	Limited clearances
2	Sign	Safemaster / Safemaster	Main Roof	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Pass	Fitted on inspection
3	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
4	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
5	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Non- Complia nt	Solar panels are obstructing the use of the anchor
6	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Non- Complia nt	Solar panels are obstructing the use of the anchor
7	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Non- Complia nt	Solar panels are obstructing the use of the anchor
8	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
9	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
10	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
11	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
12	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
13	Roof Access Hatch	Unknown / Unknown	Main Roof	Unknown	5/03/2019	5/03/2020	AS1657:2018	Fail	No way to access the hatch from bellow

### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Client:LogiudiceJob Ref:SM 10672Site:Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
14	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
15	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
16	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
17	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
18	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
19	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
20	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Fail	Anchor has been cut off for the plant equipment stands
21	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Main Roof	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
22	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
23	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
24	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
25	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
26	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	

### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155

Logiudice Client: Job Ref: SM 10672 Site:

Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
27	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
28	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
29	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
30	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
31	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
32	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
33	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
34	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
35	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
36	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
37	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
38	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
39	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	

### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155

Logiudice Client: Job Ref: SM 10672 Site:

Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
40	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
41	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
42	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
43	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
44	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
45	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
46	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
47	Abseil Anchor Point Purlin Fix -15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
48	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
49	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
50	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
51	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
52	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	

### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Client:LogiudiceJob Ref:SM 10672Site:Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
53	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
54	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
55	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
56	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
57	Abseil Anchor Point Concrete Fix-15kN	Sayfa/Skywalker	Main Roof	11/06/2018	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
58	Sign	Safemaster / Safemaster	Level 5 Floor	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Not Inspecte d	Access is required through tenancy
59	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
60	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
61	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
62	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
63	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
64	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
65	Sign	Safemaster / Safemaster	Level 5 Floor	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Not Inspecte d	Access is required through tenancy

### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Client:LogiudiceJob Ref:SM 10672Site:Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
66	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
67	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
68	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
69	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
70	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
71	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 5 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
72	Sign	Safemaster / Safemaster	Level 4 Floor	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Pass	Fitted on inspection
73	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
74	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
75	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
76	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
77	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
78	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	

### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155

Client: Logiudice Job Ref: SM 10672 Site:

Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
79	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
80	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
81	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
82	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
83	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
84	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
85	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
86	Sign	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 20	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Not Inspecte d	Access is required through tenancy
87	Ladder Bracket	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 20	5/03/2019	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
88	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 20	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
89	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 20	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
90	Sign	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 19	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Not Inspecte d	Access is required through tenancy
91	Ladder Bracket	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 20	5/03/2019	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy

### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155

Client: Logiudice Job Ref: SM 10672 Site:

Velo Apartments

ltem No	Equipment Type & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
92	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 19	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
93	Sign	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 18	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Not Inspecte d	Access is required through tenancy
94	Ladder Bracket	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 20	5/03/2019	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
95	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 18	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
96	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Level 4 Floor- Through Tenancy 18	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Not Inspecte d	Access is required through tenancy
97	Sign	Safemaster / Safemaster	Awning-Ground Level	5/03/2019	5/03/2019	5/03/2020	AS1319:1994 AS1891.4-2009	Pass	
98	Ladder Bracket	Safemaster / Safemaster	Awning-Ground Level	5/03/2019	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
99	Access Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Awning-Ground Level	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
100	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Awning-Ground Level	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
101	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Awning-Ground Level	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
102	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Awning-Ground Level	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
103	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Awning-Ground Level	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	
104	Anchor Point Surface Mount-15kN	Safemaster / Safemaster	Awning-Ground Level	1/04/2016	5/03/2019	5/03/2020	AS1891.4:2009	Pass	

#### **INSPECTION LOG RECORD - INSTALLED SYSTEMS**

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Client: Job Ref: Site:	Logiudice SM 10672 Velo Apartments								
Item Equipment T No	ype & Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments

AUTHORISED BY: TYRON MENIKIDES

DATE: 05/03/2019

SIGNATURE:

I Mart

.

#### **COMPLIANCE REQUIREMENTS**

Item No	Location	Recommendations
1	Main Roof	Replace hatch to one the correct size with grabrails or install sign advising the user of the clearance issues.
5 to 7	Main Roof	Install additional products to allow safe access.
13	Main Roof	No action required as there is another access hatch (item 1)
20	Main Roof	Install additional products to allow safe access.
58 to 71	Level 5 Floor	Access is required through 2x tenancies to inspect systems.
86 to 96	Level 4 Floor	Access is required through 3x tenancies to inspect systems.
	4	



#### Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155 PO Box 1373 Canning Vale WA 6970 Ph: (08) 6243 3111 Fax: (08) 9456 5014 Email: info@safemaster.net.au Web: www.safemaster.net.au