

CONFIDENTIALITY/SECURITY

Information obtained from and about Harvey Agricultural College in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Harvey Agricultural College and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products) 33 Catalano Road, Canning Vale 6155 PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

Trevor Harris (Recertification Technician)

EMAIL: inspections@safemaster.net.au

Roof Safety Report for Harvey Agricultural College

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Admin Library Gym Bus Shed Wood/BC Auto TTC	Anchor Points Signage Ladder Ladder Bracket

DATE OF INSPECTION

13/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Harvey Agricultural College buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

EMAIL: inspections@safemaster.net.au



31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
8	Ladder Bracket	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
9	Sign	Safemaster	Admin	1/04/2011	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
10	Purlin Fix Anchor Point	Safemaster	Academic	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point	Safemaster	Academic	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point	Safemaster	Academic	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor Point	Safemaster	Academic	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point	Safemaster	Academic	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point	Safemaster	Academic	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point	Safemaster	Academic	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
23	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
25	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
27	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
34	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
37	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
39	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
45	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
46	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
47	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
48	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
49	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
51	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
52	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
53	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
54	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
56	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
57	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
58	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
59	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
60	Purlin Fix Anchor Point	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
61	Ladder	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1657:2013	Pass	
62	Walkway	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1657:2013	Pass	

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
63	Ladder Bracket	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
64	Ladder Bracket	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
65	Ladder Bracket	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
66	Sign	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
67	Sign	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
68	Sign	Safemaster	Gym	1/04/2011	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
69	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
70	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
71	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
72	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
73	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
74	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
75	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
76	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
77	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
78	Purlin Fix Anchor Point	Unknown	Bus Shed	Unknown	13/04/2018	13/10/2018	AS1891.4:2009	N/A	No access - not inspected
79	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
80	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
81	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
82	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
83	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
84	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
85	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
86	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
NO		mstallel		Date					
87	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
88	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
89	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
90	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
91	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
92	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
93	Purlin Fix Anchor Point	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
94	Ladder	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1657:2013	Pass	
95	Ladder	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1657:2013	Pass	
96	Ladder Bracket	Safemaster	Wood/BC	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
97	Sign	Safemaster	Wood/BC	31/10/2016	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
98	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
99	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
100	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
101	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
102	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
103	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
104	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
105	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
106	Purlin Fix Anchor Point	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
107	Ladder	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1657:2013	Pass	
108	Ladder	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1657:2013	Pass	
109	Ladder Bracket	Safemaster	Auto	1/09/2012	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
110	Sign	Safemaster	Auto	31/10/2016	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
112	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
113	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
114	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
115	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
116	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
117	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
118	Purlin Fix Anchor Point	RIS	ТТС	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
119	Purlin Fix Anchor Point	RIS	ТТС	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
120	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
121	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
122	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
123	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
124	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
125	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
126	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
127	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
128	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
129	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
130	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
131	Purlin Fix Anchor Point	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
132	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
133	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
134	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 6318

Site: Harvey Agricultural College

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
135	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
136	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
137	Purlin Fix Anchor Point	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
138	Ladder Bracket plus Platform	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
139	Ladder Bracket plus Platform	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
140	Ladder Bracket	RIS	TTC	1/02/2011	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
141	Sign	RIS	ттс	1/02/2011	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris DATE: 13/04/2018 SIGNATURE:

Compliance Requirements

Location	Recommendations
Bus Shed	Vertical access ladder to be installed.
Academic Block	Ladder Bracket and sign to be installed.
Trade	1.5mt portable should be installed on roof to be used in conjunction with the existing ladder brackets and platforms.
	Bus Shed Academic Block

 ${\sf EMAIL: inspections@safemaster.net.au}$



Safemaster Safety Products 31-33 Catalano Road, Canning Vale WA 6155 PO Box 1373 Canning Vale WA 6970 Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au Web: www.safemaster.net.au