

Roof Safety Report

Manjimup Education Support Centre

Prepared By: Safemaster Safety Products Date: 10/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about Manjimup Education Support in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Bunbury BMW and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products) 33 Catalano Road, Canning Vale 6155 PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

Trevor Harris (Recertification Technician)

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED		
BMW Bunbury	Ed Support Stand Alone	Anchor Points		

DATE OF INSPECTION 10/04/18

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Manjimup Education Support buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT N/A

Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155 CALL US: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client:BMW Bunbury

Job Ref: SM7176

Site: Manjimup Education Support Centre

ltem No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Ed Support Stand Alone	1/02/2011	10/04/2018	10/10/2018	AS1891.4:2009	Pass	In Working Order
2	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Ed Support Stand Alone	1/02/2011	10/04/2018	10/10/2018	AS1891.4:2009	Pass	In Working Order
3	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Ed Support Stand Alone	1/02/2011	10/04/2018	10/10/2018	AS1891.4:2009	Pass	In Working Order
4	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Ed Support Stand Alone	1/02/2011	10/04/2018	10/10/2018	AS1891.4:2009	Pass	In Working Order

AUTHORISED BY: TREVOR HARRIS

DATE: 10/04/2018

SIGNATURE:

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Roof Safety Report for Manjimup Education Support Centre

Compliance Requirements

Item No	Location	Recommendations
	Stand Alone at Senior High Campus	Ladder Bracket and Sign have been removed during building of covered area. A new ladder bracket and sign should be installed.
	L	



Safemaster Safety Products 31-33 Catalano Road, Canning Vale WA 6155 PO Box 1373 Canning Vale WA 6970 Ph: (08) 6243 3111 Fax: (08) 9456 5014 Email: info@safemaster.net.au Web: www.safemaster.net.au