

Roof Safety Report

**South Metro TAFE-Aerospace
Training Facility-Hanger**

Prepared By: Safemaster Safety Products
Date: 20/04/2018

Roof Safety Report for
South Metro TAFE-Aerospace Training Facility-Hanger

CONFIDENTIALITY/SECURITY

Information obtained from and about South Metro TAFE-Aerospace Training Facility-Hanger in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to South Metro TAFE-Aerospace Training Facility-Hanger and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

A handwritten signature in black ink, appearing to read 'Jb' followed by a stylized horizontal line and a vertical stroke.

James Townsend (Recertification Technician)

Roof Safety Report for
South Metro TAFE-Aerospace Training Facility-Hanger

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Programmed	South Metro TAFE-Aerospace Training Facility-Hanger	

DATE OF INSPECTION

20/04/2018

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on South Metro TAFE-Aerospace Training Facility-Hanger buildings.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

Roof Safety Report for South Metro TAFE-Aerospace Training Facility-Hanger

Compliant Requirements

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au