

# Roof Safety Report

Adam Road Primary School

Prepared By: Safemaster Safety Products  
Date: 27/04/18

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Adam Road Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Adam Road Primary School and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Trevor Harris (Recertification Technician)**

Roof Safety Report for  
Adam Road Primary School

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	PP1-PP2/K1-K4/1-3 Room 4-6 Room 7-9 Room 10-13 Room 14 Room 15-17 Room 18-21 Admin Library Dental Unit Music/Art	Anchor Points Signage Ladder Bracket

DATE OF INSPECTION

27/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Adam Road Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
12	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
14	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
15	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
16	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
17	Ladder Bracket	Safemaster	Admin	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
18	Sign	Safemaster	Admin	1/10/2015	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
19	Timber Fix Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
20	Timber Fix Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
21	Timber Fix Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
22	Timber Fix Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
23	Timber Fix Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
31	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
32	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
33	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
34	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
35	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
36	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
38	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
39	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
40	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
41	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
42	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
43	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
44	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
45	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
47	Surfacemount Anchor Point	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
48	Ladder Bracket	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Ladder Bracket	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
50	Ladder Bracket	Safemaster	PP1/PP2/K1-K4/1-3	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
51	Sign	Safemaster	PP1/PP2/K1-K4/1-3	1/10/2015	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
52	Surfacemount Anchor Point	Safemaster	Room 4-6	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
53	Surfacemount Anchor Point	Safemaster	Room 4-6	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
54	Surfacemount Anchor Point	Safemaster	Room 4-6	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
55	Surfacemount Anchor Point	Safemaster	Room 4-6	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
56	Surfacemount Anchor Point	Safemaster	Room 4-6	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
57	Surfacemount Anchor Point	Safemaster	Room 4-6	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
58	Ladder Bracket	Safemaster	Room 4-6	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
59	Sign	Safemaster	Room 4-6	1/10/2015	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
60	Purlin Fix Anchor Point	Safemaster	Room 7-9	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Fail	Anchor is damaged..Out of Service

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Purlin Fix Anchor Point	Safemaster	Room 7-9	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
62	Purlin Fix Anchor Point	Safemaster	Room 7-9	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
63	Purlin Fix Anchor Point	Safemaster	Room 7-9	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
64	Purlin Fix Anchor Point	Safemaster	Room 7-9	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
65	Ladder Bracket	Safemaster	Room 7-9	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
66	Sign	Safemaster	Room 7-9	1/10/2015	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
67	Timber Fix Anchor Point	Safemaster	Room 10-13	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
68	Timber Fix Anchor Point	Safemaster	Room 10-13	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
69	Timber Fix Anchor Point	Safemaster	Room 10-13	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
70	Timber Fix Anchor Point	Safemaster	Room 10-13	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
71	Timber Fix Anchor Point	Safemaster	Room 10-13	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
72	Timber Fix Anchor Point	Safemaster	Room 10-13	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
74	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
75	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
76	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
77	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
78	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
79	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
80	Timber Fix Anchor Point	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
81	Ladder Bracket	Safemaster	Room 14	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
82	Sign	Safemaster	Room 14	1/10/2015	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
83	Timber Fix Anchor Point	Safemaster	Room 15-17	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
84	Timber Fix Anchor Point	Safemaster	Room 15-17	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Timber Fix Anchor Point	Safemaster	Room 15-17	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
86	Timber Fix Anchor Point	Safemaster	Room 15-17	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
87	Timber Fix Anchor Point	Safemaster	Room 15-17	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
88	Ladder Bracket	Safemaster	Room 15-17	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
89	Sign	Safemaster	Room 15-17	1/10/2015	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
90	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
91	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
92	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
93	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
94	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
95	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
96	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
98	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
99	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
100	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
101	Purlin Fix Anchor Point	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
102	Ladder Bracket	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
103	Sign	RSS	Room 18-21	1/01/2010	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
104	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
105	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
106	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
107	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
108	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
110	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
111	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
112	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
113	Purlin Fix Anchor Point	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
114	Ladder Bracket	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
115	Sign	RSS	Library	1/01/2010	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
116	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
117	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
118	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
119	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
120	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7143

**Site:** Adam Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
122	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
123	Surfacemount Anchor Point	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
124	Ladder Bracket	Safemaster	Music/Art	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
125	Sign	Safemaster	Music/Art	1/10/2015	27/04/2018	27/10/2018	AS1319:1994 AS1891.4-2009	Pass	
126	Timber Fix Anchor Point	Safemaster	Dental Unit	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
127	Timber Fix Anchor Point	Safemaster	Dental Unit	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
128	Timber Fix Anchor Point	Safemaster	Dental Unit	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	
129	Timber Fix Anchor Point	Safemaster	Dental Unit	1/01/2012	27/04/2018	27/10/2018	AS1891.4:2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 27/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)