

Roof Safety Report

BLUE WATER APARTMENTS

Prepared By: Safemaster Safety Products
Date: 19/9/2017

CONFIDENTIALITY/SECURITY

Information obtained from and about Blue water apartments in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Blue water apartments and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tony Pennington (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Tony Pennington (Recertification Technician)

Roof Safety Report for
BLUE WATER APARTMENTS

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Legiudice	Blue water apartments	Anchor Points Signage Hatches

DATE OF INSPECTION

19/9/2017

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Blue water apartments building.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: LOGIUDICE

Job Ref: SM 7044

Site: BLUE WATER APARTMENTS

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
2	Sign	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
3	Hatch	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	N/A	Pass	In Working Order
4	Hatch	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	N/A	Pass	In Working Order
5	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
6	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
7	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
8	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
9	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
10	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
11	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
12	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: LOGIUDICE

Job Ref: SM 7044

Site: BLUE WATER APARTMENTS

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
14	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
15	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
16	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
17	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
18	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
19	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
20	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
21	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
22	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
23	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
24	Abseil Anchor Point-Purlin Fix -15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: LOGIUDICE

Job Ref: SM 7044

Site: BLUE WATER APARTMENTS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
26	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
27	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
28	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
29	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
30	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
31	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
32	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
33	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
34	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
35	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
36	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: LOGIUDICE

Job Ref: SM 7044

Site: BLUE WATER APARTMENTS

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
38	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
39	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
40	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
41	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Top Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
42	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
43	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
44	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
45	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
46	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
47	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
48	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: LOGIUDICE

Job Ref: SM 7044

Site: BLUE WATER APARTMENTS

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
50	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
51	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	7 Th Floor Bolconys	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
52	Sign	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
53	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
54	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
55	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
56	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
57	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
58	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order
59	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Gym Roof	1/11/2013	19/09/2017	19/09/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: LOGIUDICE

Job Ref: SM 7044

Site: BLUE WATER APARTMENTS

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
---------	-----------------------------	-------------------------	----------	-----------------	-----------	----------------	---------------------	--------	----------

AUTHORISED BY: TONY PENNINGTON

DATE: 19/9/2017

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

RECOMMENDATIONS

There are no recommendations at this point in time.

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au