

# Roof Safety Report

**Box Hill Central (South  
Precinct), VIC 3128**

Prepared By: Safemaster Safety Products  
Date: 14 Feb 2019

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Box Hill Central (South Precinct), VIC in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Vicinity Centres and Box Hill Central (South Precinct), VIC and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)  
31-33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:



**James Townsend (Recertification Technician)**

Roof Safety Report for  
**Box Hill Central (South Precinct), VIC 3128**

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres	Box Hill Central (South Precinct) 1 Main Street, Box Hill VIC 3128	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

---

**DATE OF INSPECTION**

01/02/2019

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Box Hill Central (South Precinct) buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

Product: HILTI Tester



# Inspection Log

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
13	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
14	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
15	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
16	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
17	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
18	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
19	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
20	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
21	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
22	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
25	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
31	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
32	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
33	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
35	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
36	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
37	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
38	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
39	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
40	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
41	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
42	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
43	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
44	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
47	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
48	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
49	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
50	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
51	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
52	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
53	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
54	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
55	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
57	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
58	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
59	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
60	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
61	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
62	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
63	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
64	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
65	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
66	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
 CALL US: (08) 6243 3111  
 EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
68	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
69	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
70	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
71	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
72	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
73	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
74	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
75	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
76	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
77	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
79	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
80	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
81	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
82	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
83	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
84	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
85	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
86	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
87	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
88	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
90	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
91	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
92	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
93	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
94	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
95	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
96	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
97	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
98	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
99	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
101	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
102	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
103	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
104	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
105	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
106	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
107	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
108	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
109	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
110	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
112	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
113	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
114	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
115	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
116	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
117	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
118	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
119	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
120	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
121	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
 CALL US: (08) 6243 3111  
 EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
123	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
124	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
125	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
126	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
127	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
128	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
129	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
130	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
131	Surfacemount Anchor Point	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
132	Horizontal Static Line	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Horizontal Static Line	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
134	Horizontal Static Line	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
135	Horizontal Static Line	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
136	Horizontal Static Line	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
137	Horizontal Static Line	CARE	Box Hill South	1/09/2013	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
138	Access Ladder (Al)	Safemaster	L1	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
139	Guardrail (Al)	Unknown	L1	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
140	Access Ladder (Al)	Unknown	L2	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
141	Guardrail (Al)	Unknown	L2	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
142	Guardrail (Al)	Unknown	L3	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
143	Access Ladder (Al)	Unknown	L4	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
145	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
146	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
147	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
148	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
149	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
150	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
151	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
152	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
153	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
154	Surfacemount Anchor Point	Safemaster	L6	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Step (AI)	Unknown	L9	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
156	Guardrail (AI)	Unknown	L9	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
157	Step Bridge (AI)	Safemaster	L12	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
158	Access Ladder (AI)	Safemaster	L13	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
159	Access Ladder (AI)	Safemaster	L13	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
160	Guardrail (AI)	Safemaster	L13	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
161	Guardrail (AI)	Unknown	L14	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
162	Guardrail (AI)	Safemaster	L15	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
163	Static Line	Unknown	L17	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
164	Surfacemount Anchor Point	Safemaster	L18	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
165	Surfacemount Anchor Point	Safemaster	L18	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Surfacemount Anchor Point	Safemaster	L18	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
167	Surfacemount Anchor Point	Safemaster	L19	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
168	Surfacemount Anchor Point	Safemaster	L19	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
169	Anchor Strop	Safemaster	L19	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
170	Ladder Access Bracket	Safemaster	L19	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
171	Surfacemount Anchor Point	Safemaster	L20	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
172	Surfacemount Anchor Point	Safemaster	L20	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
173	Surfacemount Anchor Point	Safemaster	L20	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
174	Surfacemount Anchor Point	Safemaster	L20	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
175	Anchor Strop	Safemaster	L20	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
176	Ladder Access Bracket	Safemaster	L20	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
177	Surfacemount Anchor Point	Safemaster	L21	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
178	Surfacemount Anchor Point	Safemaster	L21	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
179	Surfacemount Anchor Point	Safemaster	L21	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
180	Surfacemount Anchor Point	Safemaster	L21	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
181	Anchor Strop	Safemaster	L21	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
182	Ladder Access Bracket	Safemaster	L21	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
183	Surfacemount Anchor Point	Safemaster	L22	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
184	Surfacemount Anchor Point	Safemaster	L22	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
185	Surfacemount Anchor Point	Safemaster	L22	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
186	Surfacemount Anchor Point	Safemaster	L22	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
187	Anchor Strop	Safemaster	L22	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
188	Ladder Access Bracket	Safemaster	L22	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
189	Surfacemount Anchor Point	Safemaster	L23	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
190	Surfacemount Anchor Point	Safemaster	L23	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
191	Surfacemount Anchor Point	Safemaster	L23	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
192	Surfacemount Anchor Point	Safemaster	L23	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
193	Anchor Strop	Safemaster	L23	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
194	Ladder Access Bracket	Safemaster	L23	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
195	Surfacemount Anchor Point	Safemaster	L24	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
196	Surfacemount Anchor Point	Safemaster	L24	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
197	Surfacemount Anchor Point	Safemaster	L24	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
198	Surfacemount Anchor Point	Safemaster	L24	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
199	Access Ladder (Al)	Unknown	L27	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
200	Access Ladder (Al)	Unknown	L28	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
201	Access Ladder (Al)	Unknown	L29	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
202	Guardrail (Galv)	Unknown	L29	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
203	Access Ladder (Al)	Unknown	L30	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
204	Static Line	Unknown	L32	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
205	Access Ladder (Al)	Unknown	L33	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
206	Guardrail (Al)	Unknown	L33	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
207	Access Ladder (Al)	Unknown	L34	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
208	Guardrail (Al)	Unknown	L34	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
209	Access Ladder (Al)	Unknown	L35	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
210	Guardrail (AI)	Unknown	L35	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
211	Access Ladder (AI)	Unknown	L36	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
212	Guardrail (AI)	Unknown	L36	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
213	Access Ladder (AI)	Unknown	L37	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
214	Guardrail (AI)	Unknown	L37	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
215	Access Ladder (AI)	Unknown	L38	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
216	Access Ladder (AI)	Safemaster	L39	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
217	Guardrail (AI)	Unknown	L39	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
218	Access Ladder (AI)	Unknown	L40	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
219	Guardrail (AI)	Unknown	L40	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
220	Guardrail (AI)	Unknown	L41	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
221	Access Ladder (Al)	Unknown	L41	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
222	Guardrail (Al)	Unknown	L42	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
223	Access Ladder (Al)	Unknown	L43	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
224	Guardrail (Galv)	Unknown	L43	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
225	Access Ladder (Al)	Unknown	L44	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
226	Guardrail (Al)	Unknown	L44	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
227	Static Line	Unknown	L45	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
228	Access Ladder (Al)	Unknown	L47	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
229	Guardrail (Al)	Unknown	L47	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
230	Access Ladder (Al)	Unknown	L48	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
231	Guardrail (Al)	Unknown	L48	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
232	Access Ladder (Al)	Unknown	L49	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
233	Access Ladder (Al)	Unknown	L50	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
234	Guardrail (Al)	Unknown	L50	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
235	Access Ladder (Al)	Unknown	L51	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
236	Guardrail (Al)	Unknown	L51	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
237	Guardrail (Al)	Unknown	L52	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
238	Access Ladder (Al)	Unknown	L53	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
239	Static Line	Unknown	L54	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
240	Surfacemount Anchor Point	Safemaster	L55	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
241	Surfacemount Anchor Point	Safemaster	L55	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
242	Surfacemount Anchor Point	Safemaster	L55	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
243	Surfacemount Anchor Point	Safemaster	L55	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
244	Ladder Access Bracket	Safemaster	L56	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
245	Anchor Strop	Safemaster	L56	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
246	Surfacemount Anchor Point	Safemaster	L56	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
247	Surfacemount Anchor Point	Safemaster	L56	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
248	Ladder Access Bracket	Safemaster	L57	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
249	Anchor Strop	Safemaster	L57	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
250	Surfacemount Anchor Point	Safemaster	L57	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
251	Surfacemount Anchor Point	Safemaster	L57	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
252	Surfacemount Anchor Point	Safemaster	L57	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
253	Surfacemount Anchor Point	Safemaster	L57	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
254	Surfacemount Anchor Point	Safemaster	L57	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
255	Ladder Access Bracket	Safemaster	L58	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
256	Anchor Strop	Safemaster	L58	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
257	Surfacemount Anchor Point	Safemaster	L58	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
258	Surfacemount Anchor Point	Safemaster	L58	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
259	Surfacemount Anchor Point	Safemaster	L58	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
260	Surfacemount Anchor Point	Safemaster	L58	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
261	Surfacemount Anchor Point	Safemaster	L58	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
262	Ladder Access Bracket	Safemaster	L59	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
263	Anchor Strop	Safemaster	L59	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
264	Surfacemount Anchor Point	Safemaster	L59	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Surfacemount Anchor Point	Safemaster	L59	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
266	Surfacemount Anchor Point	Safemaster	L59	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
267	Surfacemount Anchor Point	Safemaster	L59	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
268	Surfacemount Anchor Point	Safemaster	L59	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
269	Ladder Access Bracket	Safemaster	L60	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
270	Anchor Strop	Safemaster	L60	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
271	Surfacemount Anchor Point	Safemaster	L60	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
272	Surfacemount Anchor Point	Safemaster	L60	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
273	Surfacemount Anchor Point	Safemaster	L60	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
274	Surfacemount Anchor Point	Safemaster	L60	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
275	Surfacemount Anchor Point	Safemaster	L60	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
276	Surfacemount Anchor Point	Safemaster	L61	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
277	Surfacemount Anchor Point	Safemaster	L61	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
278	Surfacemount Anchor Point	Safemaster	L61	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
279	Access Ladder (Al)	Unknown	L64	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
280	Guardrail (Al)	Unknown	L64	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
281	Guardrail (Al)	Unknown	L67 - Roof	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
282	Access Ladder (Al)	Unknown	L67	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
283	Guardrail (Al)	Unknown	L67 - Plant Deck	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
284	Surfacemount Anchor Point	Safemaster	L70	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
285	Surfacemount Anchor Point	Safemaster	L70	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
286	Surfacemount Anchor Point	Safemaster	L70	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
287	Surfacemount Anchor Point	Safemaster	L70	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
288	Access Ladder (Al)	Unknown	L71	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
289	Guardrail (Al)	Unknown	L71	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
290	Access Ladder (Al)	Unknown	L72	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
291	Surfacemount Anchor Point	Safemaster	L75	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
292	Surfacemount Anchor Point	Safemaster	L75	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
293	Surfacemount Anchor Point	Safemaster	L75	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
294	Surfacemount Anchor Point	Safemaster	L75	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
295	Surfacemount Anchor Point	Safemaster	L75	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
296	Surfacemount Anchor Point	Safemaster	L75	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
297	Surfacemount Anchor Point	Safemaster	L75	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
298	Access Ladder (Al)	Unknown	L76	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
299	Guardrail (Al)	Unknown	L76	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
300	Access Ladder (Al)	Unknown	L77	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
301	Access Ladder (Al)	Unknown	L79	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Fail	Out of Service - Sign installed
302	Step (Al)	Unknown	L80	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
303	Guardrail (Galv)	Unknown	L80	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
304	Access Ladder (Al)	Safemaster	L81	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
305	Guardrail (Galv)	Unknown	L81	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
306	Access Ladder (Al)	Safemaster	L82	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
307	Access Ladder (Al)	Unknown	L83	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
308	Guardrail (Galv)	Unknown	L83	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
309	Anchor Strop	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
310	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
311	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
312	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
313	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
314	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
315	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
316	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
317	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
318	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
319	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
320	Surfacemount Anchor Point	Safemaster	L87	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
321	Access Ladder (Al)	Unknown	L88	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
322	Guardrail (Galv)	Unknown	L88	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
323	Access Ladder (Al)	Safemaster	L89	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
324	Guardrail (Al)	Unknown	L89	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
325	Access Ladder (Al)	Safemaster	L91	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
326	Guardrail (Al)	Unknown	L91	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
327	Access Ladder (Al)	Safemaster	L92	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
328	Guardrail (Al)	Unknown	L92	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
329	Guardrail (Al)	Unknown	L93	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
330	Access Ladder (Al)	Unknown	L94	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
331	Guardrail (Al)	Unknown	L94	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
332	Stair (Galv)	Unknown	L95	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
333	Guardrail (Galv)	Unknown	L95	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
334	Surfacemount Anchor Point	Safemaster	L96	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
335	Surfacemount Anchor Point	Safemaster	L96	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
336	Surfacemount Anchor Point	Safemaster	L96	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
337	Static Line	Safemaster	L98	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
338	Surfacemount Anchor Point	Safemaster	L98	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
339	Surfacemount Anchor Point	Safemaster	L98	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
340	Surfacemount Anchor Point	Safemaster	L98	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
341	Surfacemount Anchor Point	Safemaster	L98	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
342	Access Ladder (Al)	Safemaster	L98	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
343	Ladder Access Bracket	Safemaster	L99	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
344	Sign	Safemaster	L99	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
345	Anchor Strop	Safemaster	L99	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
346	Static Line	Safemaster	L99	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
347	Surfacemount Anchor Point	Safemaster	L99	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
348	Access Ladder (Al)	Safemaster	L100	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
349	Surfacemount Anchor Point	Safemaster	L101	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
350	Step Bridge (Al)	Safemaster	L102	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
351	Access Ladder (Al)	Safemaster	L103	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
352	Guardrail (Galv)	Unknown	L103	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
353	Access Ladder (Al)	Safemaster	L103	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
354	Surfacemount Anchor Point	Safemaster	L104	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
355	Surfacemount Anchor Point	Safemaster	L104	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
356	Surfacemount Anchor Point	Safemaster	L104	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
357	Surfacemount Anchor Point	Safemaster	L104	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
358	Surfacemount Anchor Point	Safemaster	L104	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
359	Surfacemount Anchor Point	Safemaster	L104	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
360	Access Ladder (Al)	Unknown	L105	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
361	Access Ladder (Al)	Safemaster	L106	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
362	Access Ladder (Galv)	Unknown	L107	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
363	Guardrail (Galv)	Unknown	L107	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres  
**Job Ref:** SM12182  
**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
364	Access Ladder (AI)	Unknown	L108	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
365	Guardrail (AI)	Safemaster	L108	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
366	Surfacemount Anchor Point	Safemaster	L108	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
367	Surfacemount Anchor Point	Safemaster	L109	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
368	Surfacemount Anchor Point	Safemaster	L109	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
369	Surfacemount Anchor Point	Safemaster	L109	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
370	Surfacemount Anchor Point	Safemaster	L109	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
371	Surfacemount Anchor Point	Safemaster	L109	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
372	Step Bridge (AI)	Safemaster	L109	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
373	Static Line	Unknown	L110	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
374	Access Ladder (AI)	Unknown	L112	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
375	Access Ladder (Al)	Unknown	L113	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
376	Step Bridge (Al)	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
377	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
378	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
379	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
380	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
381	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
382	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
383	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
384	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
385	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centres

**Job Ref:** SM12182


**Site:** Box Hill Central (South Precinct)

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
386	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
387	Surfacemount Anchor Point	Safemaster	L114	27/04/2018	1/02/2019	1/02/2020	AS1891.4:2009	Pass	
388	Access Ladder (Al)	Unknown	L118	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
389	Step Bridge (Al)	Safemaster	L118	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
390	Access Ladder (Al)	Safemaster	L119	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
391	Access Ladder (Al)	Unknown	L120	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
392	Roof Access Hatch	Unknown	L120	Unknown	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	
393	Guardrail (Al)	Unknown	L120	27/04/2018	1/02/2019	1/02/2020	AS/NZS 1657-2013	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 01-02-2019

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)