

Roof Safety Report

Brunswick Junction Primary
School

Prepared By: Safemaster Safety Products
Date: 13/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about Brunswick Junction Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Brunswick Junction Primary School and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Trevor Harris (Recertification Technician)

Roof Safety Report for
Brunswick Junction Primary School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Library Undercover Area Senior Junior Admin	Anchor Points Signage Ladder Bracket

DATE OF INSPECTION

13/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Brunswick Junction Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7148

Site: Brunswick Junction Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
11	Ladder Bracket	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
12	Sign	RSS	Library	1/09/2010	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7148

Site: Brunswick Junction Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Ladder Bracket	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
14	Sign	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
15	Access Strop	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
16	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
17	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
18	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
19	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
20	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
21	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
22	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
23	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
24	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7148

Site: Brunswick Junction Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
26	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
27	Surface Mount Anchor Point	Safe Roof Access	Senior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
28	Ladder Bracket	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
29	Sign	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
30	Access Strop	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
31	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
32	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
33	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
34	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
35	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
36	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7148

Site: Brunswick Junction Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
38	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
39	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
40	Surface Mount Anchor Point	Safe Roof Access	Junior	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
41	Ladder Bracket	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
42	Sign	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1319:1994 AS1891.4-2009	Pass	
43	Access Strop	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
44	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
45	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
46	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
47	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
48	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7148

Site: Brunswick Junction Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
50	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
51	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
52	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
53	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
54	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
55	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
56	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
57	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
58	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
59	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
60	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7148

Site: Brunswick Junction Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Surface Mount Anchor Point	Safe Roof Access	Admin	6/08/2017	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
62	Purlin Fix Anchor Point	RSS	Undercover	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
63	Purlin Fix Anchor Point	RSS	Undercover	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	
64	Purlin Fix Anchor Point	RSS	Undercover	1/09/2010	13/04/2018	13/10/2018	AS1891.4:2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 13/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6218 5158

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au