

# Roof Safety Report

Australind Primary School

Prepared By: Safemaster Safety Products  
Date: 26/04/18

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Australind Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Australind Primary School and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Trevor Harris (Recertification Technician)**

Roof Safety Report for  
Australind Primary School

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Admin ECH1 Junior Middle Library Arts ECH2/ECH3	Anchor Points Signage Ladder Bracket

**DATE OF INSPECTION**

26/04/18

**INSPECTION METHODOLOGY**

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Australind Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7146

**Site:** Australind Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
11	Ladder Bracker	Safemaster	Admin	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
12	Sign	Safemaster	Admin	1/10/2014	26/04/2018	26/10/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7146

**Site:** Australind Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Surfacemount Anchor Point	Safemaster	ECH 1	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
14	Ladder Bracker	Safemaster	ECH 1	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
15	Sign	Safemaster	ECH 1	1/10/2014	26/04/2018	26/10/2018	AS1319:1994 AS1891.4-2009	Pass	
16	Surfacemount Anchor Point	Safemaster	Junior	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
17	Surfacemount Anchor Point	Safemaster	Junior	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
18	Surfacemount Anchor Point	Safemaster	Junior	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
19	Surfacemount Anchor Point	Safemaster	Junior	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
20	Ladder Bracker	Safemaster	Junior	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
21	Sign	Safemaster	Junior	1/10/2014	26/04/2018	26/10/2018	AS1319:1994 AS1891.4-2009	Pass	
22	Surfacemount Anchor Point	Safemaster	Middle	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
23	Surfacemount Anchor Point	Safemaster	Middle	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point	Safemaster	Middle	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7146

**Site:** Australind Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Surfacemount Anchor Point	Safemaster	Middle	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
26	Ladder Bracker	Safemaster	Middle	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
27	Sign	Safemaster	Middle	1/10/2014	26/04/2018	26/10/2018	AS1319:1994 AS1891.4-2009	Pass	
28	Surfacemount Anchor Point	Safemaster	Library	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point	Safemaster	Library	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point	Safemaster	Library	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
31	Surfacemount Anchor Point	Safemaster	Library	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
32	Ladder Bracker	Safemaster	Library	1/01/2012	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
33	Sign	Safemaster	Library	1/10/2014	26/04/2018	26/10/2018	AS1319:1994 AS1891.4-2009	Pass	
34	Purlin Fix Anchor Point	Safemaster	Arts	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point	Safemaster	Arts	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point	Safemaster	Arts	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7146

**Site:** Australind Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor Point	Safemaster	Arts	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point	Safemaster	Arts	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point	Safemaster	Arts	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
40	Ladder Bracker	Safemaster	Arts	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
41	Sign	Safemaster	Arts	1/10/2014	26/04/2018	26/10/2018	AS1319:1994 AS1891.4-2009	Pass	
42	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
45	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
46	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
47	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
48	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7146

**Site:** Australind Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
51	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
52	Purlin Fix Anchor Point	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
53	Ladder Bracker	Safemaster	ECH2/ECH3	1/02/2010	26/04/2018	26/10/2018	AS1891.4:2009	Pass	
54	Sign	Safemaster	ECH2/ECH3	1/10/2014	26/04/2018	26/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 26/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Compliance Requirements

There are no recommendations at this point in time.

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)