

# Roof Safety Report

Bunbury Senior High School

Prepared By: Safemaster Safety Products  
Date: 2/05/18

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Bunbury Senior High School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Bunbury Senior High School and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Trevor Harris (Recertification Technician)**

Roof Safety Report for  
Bunbury Senior High School

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Room 1-4 Amphitheatre Room 5-9 Room 10/Student Services Admin/Room 13-44 Kitchen Staff Toilets Library Gardener Shed Gym/Performing Arts Change Rooms Workshop D&T	Anchor Points Signage Ladder Bracket Ladders

---

DATE OF INSPECTION

2/05/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Bunbury Senior High School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
17	Access Strop	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
18	Parapet Ladder	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1657-2013	Pass	
19	Ladder Bracket	Safemaster	Room 1-4	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
20	Sign	Safemaster	Room 1-4	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
21	Surfacemount Anchor Point	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
22	Surfacemount Anchor Point	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
23	Surfacemount Anchor Point	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Surfacemount Anchor Point	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
28	Ladder Bracket	Safemaster	Amphitheatre	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
29	Sign	Safemaster	Amphitheatre	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
30	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
31	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
32	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
33	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
34	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
35	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
36	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
38	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
39	Timber Fix Anchor Point	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
40	Ladder Bracket	Safemaster	Room 5-9	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
41	Sign	Safemaster	Room 5-9	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
42	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
43	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
44	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
45	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
46	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
47	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
48	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
50	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
51	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
52	Timber Fix Anchor Point	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
53	Ladder Bracket	Safemaster	Room 10/Student Services	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
54	Sign	Safemaster	Room 10/Student Services	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
55	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
56	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
57	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
58	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
59	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
60	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
62	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
63	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
64	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
65	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
66	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
67	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
68	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
69	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
70	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
71	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
72	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
74	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
75	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
76	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
77	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
78	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
79	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
80	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
81	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
82	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
83	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
84	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
86	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
87	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
88	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
89	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
90	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
91	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
92	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
93	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
94	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
95	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
96	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
98	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
99	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
100	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
101	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
102	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
103	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
104	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
105	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
106	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
107	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
108	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
110	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
111	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
112	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
113	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
114	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
115	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
116	Timber Fix Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
117	Surfacemount Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
118	Surfacemount Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
119	Surfacemount Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
120	Surfacemount Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Surfacemount Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
122	Surfacemount Anchor Point	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
123	Ladder Bracket	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
124	Ladder Bracket	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
125	Ladder Bracket	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
126	Ladder Bracket	Safemaster	Admin/Room 13-44	1/11/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
127	Sign	Safemaster	Admin/Room 13-44	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
128	Sign	Safemaster	Admin/Room 13-44	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
129	Sign	Safemaster	Admin/Room 13-44	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
130	Sign	Safemaster	Admin/Room 13-44	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
131	Surfacemount Anchor Point	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
132	Surfacemount Anchor Point	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Surfacemount Anchor Point	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
134	Surfacemount Anchor Point	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
135	Surfacemount Anchor Point	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
136	Access Strop	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
137	Ladder Bracket	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
138	Sign	Safemaster	Kitchen	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
139	Timber Fix Anchor Point	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
140	Timber Fix Anchor Point	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
141	Timber Fix Anchor Point	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
142	Timber Fix Anchor Point	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
143	Timber Fix Anchor Point	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
144	Timber Fix Anchor Point	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Timber Fix Anchor Point	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
146	Access Strop	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
147	Ladder Bracket	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
148	Sign	Safemaster	Staff Toilets	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
149	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
150	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
151	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
152	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
153	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
154	Purlin Fix Anchor Point	Safemaster	Library	41244	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
155	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
156	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
158	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
159	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
160	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
161	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
162	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
163	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
164	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
165	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
166	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
167	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
168	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
170	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
171	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
172	Purlin Fix Anchor Point	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
173	Access Strop	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
174	Permanent Incline Ladder	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1657-2013	Pass	
175	Ladder Bracket	Safemaster	Library	1/12/2012	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
176	Sign	Safemaster	Library	1/10/2014	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
177	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
178	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
179	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
180	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
182	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
183	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
184	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
185	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
186	Surfacemount Anchor Point	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
187	Ladder Bracket	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
188	Ladder Bracket	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
189	Sign	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
190	Sign	Safemaster	Gardener Shed	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
191	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
192	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
194	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
195	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
196	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
197	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
198	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
199	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
200	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
201	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
202	Surfacemount Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
203	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
204	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
205	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
206	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
207	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
208	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
209	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
210	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
211	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
212	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
213	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
214	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
215	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
216	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Timber Fix Anchor Point	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
218	Access Strop	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
219	Ladder Bracket	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
220	Ladder Bracket	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
221	Ladder Bracket	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
222	Sign	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
223	Sign	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
224	Sign	Safemaster	Gym/Performing Arts	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
225	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
226	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
227	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
228	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
230	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
231	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
232	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
233	Timber Fix Anchor Point	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
234	Ladder Bracket	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
235	Sign	Safemaster	Change Rooms	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
236	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
237	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
238	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
239	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
240	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
241	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
242	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
243	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
244	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
245	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
246	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
247	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
248	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
249	Timber Fix Anchor Point	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
250	Access Strop	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
251	Ladder Bracket	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
252	Sign	Safemaster	Workshop	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
253	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
254	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
255	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
256	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
257	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
258	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
259	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
260	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
261	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
262	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
263	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
264	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
266	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
267	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
268	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
269	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
270	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
271	Surfacemount Anchor Point	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
272	Access Strop	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
273	Access Strop	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
274	Access Strop	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
275	Ladder Bracket	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
276	Ladder Bracket	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7853

**Site:** Bunbury Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
277	Ladder Bracket	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1891.4:2009	Pass	
278	Sign	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
279	Sign	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	
280	Sign	Safemaster	D&T	1/01/2016	2/05/2018	2/11/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 02/05/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Compliance Requirements

[illegible]





Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)