

# Roof Safety Report

Chadstone Shopping Centre,

VIC 3148

Prepared By: Safemaster Safety Products

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Chadstone Shopping Centre, VIC in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Chadstone Shopping Centre, VIC and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)  
31-33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:



**James Townsend (Recertification Technician)**

Roof Safety Report for  
Chadstone Shopping Centre, VIC 3148

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Chadstone Shopping Centre	Chadstone Shopping Centre, VIC 3148	Signage Anchor Points Ladder Bracket Static Line Davit Base

---

**DATE OF INSPECTION**

24-04-2020 & 05-06-2020

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Chadstone Shopping Centre buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

Product: HILTI Tester



Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
2	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
3	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
4	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
5	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
6	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
7	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
8	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
9	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
10	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
11	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
12	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
14	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
15	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
16	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
17	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
18	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
19	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
20	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
21	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
22	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
23	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
24	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
26	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
27	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
28	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
29	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
30	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
31	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
32	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
33	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
34	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
35	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
36	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
38	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
39	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
40	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
41	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
42	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
43	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
44	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
45	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
46	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
47	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
48	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
50	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
51	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
52	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
53	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
54	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
55	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
56	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
57	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
58	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
59	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
60	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
62	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
63	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
64	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
65	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
66	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
67	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
68	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
69	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
70	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
71	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
72	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
74	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
75	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
76	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
77	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
78	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
79	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
80	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
81	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
82	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
83	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
84	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
86	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
87	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
88	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
89	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
90	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
91	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
92	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
93	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
94	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
95	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
96	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
98	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
99	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
100	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
101	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
102	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
103	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
104	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
105	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
106	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
107	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
108	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
110	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
111	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
112	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
113	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
114	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
115	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
116	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
117	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
118	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
119	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
120	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
122	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
123	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
124	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
125	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
126	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
127	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
128	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
129	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
130	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
131	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
132	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
134	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
135	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
136	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
137	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
138	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
139	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
140	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
141	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
142	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
143	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
144	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
146	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
147	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
148	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
149	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
150	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
151	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
152	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
153	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
154	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
155	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
156	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
158	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
159	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
160	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
161	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
162	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
163	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
164	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
165	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
166	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
167	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
168	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
170	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
171	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
172	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
173	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
174	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
175	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
176	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
177	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
178	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
179	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
180	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
182	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
183	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
184	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
185	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
186	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
187	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
188	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
189	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
190	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
191	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
192	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
194	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
195	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
196	Abseil Purlin Fix 15 kN	Quantum Access	Glass Dome Cleaning Anchors	1/05/2016	5/06/2020	5/06/2021	AS1891.4:2009	Pass	
197	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
198	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
199	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
200	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
201	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
202	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
203	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
204	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
205	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
206	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
207	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
208	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
209	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
210	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
211	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
212	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
213	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
214	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
215	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
216	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
218	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
219	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
220	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
221	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
222	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
223	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
224	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
225	Structure mount Abseil Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
226	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
227	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
228	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
230	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
231	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
232	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
233	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
234	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
235	Structure mount Anchor 15 kN	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
236	Purlin Fix Anchor Point 15 kN	Pro Build	David Jones Stair well 1	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
237	Purlin Fix Anchor Point 15 kN	Pro Build	David Jones Stair well 1	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
238	Purlin Fix Anchor Point 15 kN	Pro Build	David Jones Stair well 2	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
239	Purlin Fix Anchor Point 15 kN	Pro Build	David Jones Stair well 2	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
240	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
241	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
242	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
243	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
244	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
245	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
246	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
247	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
248	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
249	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
250	Horizontal Static Line	Pro Build	David Jones	1/06/2003	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Incorrect End assemblys/Over 10 years old
251	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknowwn	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
252	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknowwn	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
253	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknounwn	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
254	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknounwn	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
255	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknounwn	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
256	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknounwn	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
257	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknounwn	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
258	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknounwn	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Rusted Screws
259	Surfacemount Anchor Point 15 kN	Quantum Access	David Jones Car Park Awning	Unknounwn	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Rusted Screws
260	Purlin Fix Anchor Point	Unknown	Carpark A Entrance Glass roof	Unknounwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
261	Purlin Fix Anchor Point	Unknown	Carpark A Entrance Glass roof	Unknounwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
262	Purlin Fix Anchor Point	Unknown	Carpark A Entrance Glass roof	Unknounwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
263	Purlin Fix Anchor Point	Unknown	Carpark A Entrance Glass roof	Unknounwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
264	Purlin Fix Anchor Point	Unknown	Carpark A Entrance Glass roof	Unknounwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Purlin Fix Anchor Point	Unknown	Carpark A Entrance Glass roof	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
266	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
267	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
268	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
269	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
270	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
271	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
272	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
273	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
274	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
275	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
276	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
277	Purlin Fix Anchor Point	Unknown	Glass Roof between David Jones & Myer	Unknowwn	5/06/2020	5/06/2021	AS1891.4:2009	Fail	Unknown type anchor
278	Horizontal Static Line 21 kN	Quantum Access	Car Park E entrance	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
279	Surfacemount Anchor Point 15 kN	Quantum Access	Car Park E entrance	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
280	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
281	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
282	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
283	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
284	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
285	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
286	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
287	Concrete Fix Anchor	Unknown	Car Park E entrance	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Unknown type anchor/No safe access
288	Purlin Fix nchor Point 15kN	Unknown	Grilled	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
289	Purlin Fix nchor Point 15kN	Unknown	Grilled	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
290	Purlin Fix nchor Point 15kN	Unknown	Grilled	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
291	Purlin Fix nchor Point 15kN	Unknown	Grilled	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
292	Purlin Fix nchor Point 15kN	Unknown	Grilled	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
293	Purlin Fix nchor Point 15kN	Unknown	Grilled	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
294	Surfacemount Anchor Point 15 kN	Unknown	Grilled	Unknown	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
295	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
296	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
297	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
298	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
299	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
300	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
301	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
302	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
303	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
304	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
305	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
306	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
307	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
308	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
309	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
310	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
311	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
312	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
313	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
314	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
315	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
316	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
317	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
318	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
319	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
320	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
321	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
322	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
323	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
324	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
325	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
326	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
327	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
328	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
329	Davit Base 15 kN	Probuild	Central Tower	1/02/2001	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
330	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
331	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
332	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
333	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
334	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
335	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
336	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
337	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
338	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
339	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
340	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
341	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
342	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
343	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
344	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
345	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
346	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
347	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
348	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
349	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
350	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
351	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
352	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
353	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
354	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
355	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
356	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
357	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
358	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
359	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
360	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
361	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
362	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
363	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
364	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
365	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
366	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
367	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
368	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
369	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
370	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
371	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
372	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
373	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
374	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
375	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
376	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
377	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
378	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
379	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
380	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
381	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
382	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
383	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
384	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
385	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
386	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
387	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
388	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
389	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
390	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
391	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
392	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
393	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
394	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
395	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
396	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
397	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
398	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
399	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
400	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
401	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
402	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
403	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
404	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
405	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
406	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
407	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
408	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
409	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
410	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Thread not extend past nut
411	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Thread not extend past nut
412	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Thread not extend past nut
413	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Thread not extend past nut
414	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Thread not extend past nut
415	Davit Base 15 kN	Vertigo	Tower 1	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	Thread not extend past nut
416	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
417	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
418	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
419	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
420	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
421	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
422	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
423	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
424	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
425	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
426	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
427	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
428	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
429	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
430	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
431	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
432	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
433	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
434	Surfacemount Anchor Point 15 kN	Vertigo	Tower 1 Upper Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
435	Horizontal Static Line	Vertigo	Tower 1 Awning Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	-	Need abesil down to access
436	Horizontal Static Line	Vertigo	Tower 1 Awning Roof	1/05/2016	24/04/2020	24/04/2021	AS1891.4:2009	-	Need abesil down to access
437	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
438	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
439	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
440	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
441	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
442	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
443	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
444	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
445	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
446	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
447	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
448	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
449	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
450	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
451	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
452	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
453	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
454	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
455	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
456	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
457	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
458	Abseil Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
459	Abseil Purlin Fix 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
460	Abseil Purlin Fix 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
461	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
462	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
463	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
464	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
465	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
466	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
467	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
468	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
469	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
470	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
471	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
472	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
473	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
474	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
475	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
476	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
477	Surfacemount Anchor Point 15 kN	Accesnt Safety	Tower 2	1/02/2013	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
478	Horizontal Static Line 21 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
479	Horizontal Static Line 21 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
480	Horizontal Static Line 21 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	-	Need boom lift to reach awning from carpark

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
481	Horizontal Static Line 21 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	-	Need boom lift to reac awning from carpark
482	Structure Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
483	Structure Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
484	Structure Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
485	Structure Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
486	Structure Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
487	Structure Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
488	Structure Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
489	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
490	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
491	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
492	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
493	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
494	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
495	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
496	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
497	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
498	Surface Mount Anchor Point 15 kN	Signal & Hobbs	Legoland/Hoyts	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
499	Access Ladder (Al)	Unknown	L1	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
500	Handrail (Al)	Unknown	L1	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
501	Access Ladder (Al)	Unknown	L2	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
502	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
503	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
504	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
505	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
506	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
507	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
508	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
509	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
510	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
511	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
512	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
513	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
514	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
515	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
516	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
517	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
518	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
519	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
520	Surfacemount Anchor Point 15 kN	Unknown	L3	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
521	Handrail (Al)	Unknown	L4	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
522	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
523	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
524	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
525	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
526	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
527	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
528	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
529	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
530	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
531	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
532	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
533	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
534	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
535	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
536	Surfacemount Anchor Point 15 kN	Unknown	L5	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
537	Access Ladder (Al)	Unknown	L5	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
538	Handrail (Al)	Unknown	L5	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
539	Handrail (Al)	Unknown	L5	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
540	Access Ladder (Al)	Unknown	L6	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
541	Access Stair (AI)	Unknown	L7	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
542	Access Ladder (AI)	Unknown	L8	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
543	Access Ladder (AI)	Unknown	L8	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
544	Handrail (AI)	Unknown	L8	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
545	Access Stair (AI)	Unknown	L9	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
546	Access Ladder (AI)	Unknown	L10	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
547	Access Ladder (AI)	Unknown	L13	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
548	Handrail (AI)	Unknown	L13	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
549	Access Ladder (AI)	Unknown	L14	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
550	Handrail (AI)	Unknown	L14	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
551	Access Ladder (AI)	Unknown	L15	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
552	Handrail (AI)	Unknown	L15	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
553	Handrail (Galv)	Unknown	L15	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
554	Access Ladder (Al)	Unknown	L16	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
555	Access Ladder (Al)	Unknown	L16	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
556	Access Ladder (Al)	Unknown	L17	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
557	Handrail (Al)	Unknown	L17	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
558	Access Ladder (Al)	Unknown	L18	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
559	Handrail (Al)	Unknown	L18	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
560	Handrail (Al)	Unknown	L19	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
561	Surfacemount Anchor Point 15 kN	Unknown	L19	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
562	Surfacemount Anchor Point 15 kN	Unknown	L19	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
563	Surfacemount Anchor Point 15 kN	Unknown	L19	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
564	Surfacemount Anchor Point 15 kN	Unknown	L19	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
565	Surfacemount Anchor Point 15 kN	Unknown	L19	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
566	Surfacemount Anchor Point 15 kN	Unknown	L19	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
567	Access Ladder (Al)	Unknown	L19	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
568	Handrail (Al)	Unknown	L19	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
569	Access Ladder (Al)	Unknown	L19	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
570	Handrail (Al)	Unknown	L19	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
571	Access Ladder (Al)	Unknown	L21	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
572	Access Ladder (Al)	Unknown	L21	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
573	Handrail (Al)	Unknown	L21	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
574	Access Ladder (Al)	Unknown	L21	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
575	Access Ladder (Al)	Unknown	L22	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
576	Access Ladder (Al)	Unknown	L23	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
577	Access Ladder (Al)	Unknown	L24	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
578	Surfacemount Anchor Point 15 kN	Unknown	L25	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
579	Surfacemount Anchor Point 15 kN	Unknown	L25	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
580	Surfacemount Anchor Point 15 kN	Unknown	L25	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
581	Surfacemount Anchor Point 15 kN	Unknown	L25	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
582	Surfacemount Anchor Point 15 kN	Unknown	L25	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
583	Surfacemount Anchor Point 15 kN	Unknown	L25	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
584	Surfacemount Anchor Point 15 kN	Unknown	L25	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
585	Access Ladder (Al)	Unknown	L26	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
586	Handrail (Galv)	Unknown	L26	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
587	Access Ladder (Al)	Unknown	L29	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
588	Access Ladder (Al)	Unknown	L29	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
589	Handrail (Galv)	Unknown	L29	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
590	Access Ladder (Al)	Unknown	L30	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
591	Surfacemount Anchor Point 15 kN	Unknown	L31	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
592	Surfacemount Anchor Point 15 kN	Unknown	L31	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
593	Surfacemount Anchor Point 15 kN	Unknown	L31	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
594	Surfacemount Anchor Point 15 kN	Unknown	L31	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
595	Access Ladder (Al)	Unknown	L33	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
596	Handrail (Galv)	Unknown	L33	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
597	Access Ladder (Al)	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
598	Access Ladder (Al)	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
599	Surfacemount Anchor Point 15 kN	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
600	Surfacemount Anchor Point 15 kN	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
601	Surfacemount Anchor Point 15 kN	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
602	Surfacemount Anchor Point 15 kN	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
603	Surfacemount Anchor Point 15 kN	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
604	Surfacemount Anchor Point 15 kN	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
605	Surfacemount Anchor Point 15 kN	Unknown	L34	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
606	Ladder access bracket	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
607	Sign	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
608	Anchor Strop	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
609	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
610	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
611	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
612	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
613	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
614	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
615	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
616	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
617	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
618	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
619	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
620	Surfacemount Anchor Point 15 kN	Unknown	L36	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
621	Access Ladder (Galv)	Unknown	L38	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
622	Handrail (Galv)	Unknown	L38	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
623	Access Ladder (Galv)	Unknown	L38	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
624	Access Ladder (Al)	Unknown	L39	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
625	Step (Al)	Unknown	L40	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
626	Access Ladder (Al)	Unknown	L41	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
627	Access Ladder (Al)	Unknown	L42	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
628	Ladder access bracket	Unknown	L43	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
629	Sign	Unknown	L43	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
630	Anchor Strop	Unknown	L43	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
631	Surfacemount Static line	Unknown	L43	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
632	Ladder access bracket	Unknown	L44	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
633	Sign	Unknown	L44	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
634	Anchor Strop	Unknown	L44	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
635	Surfacemount Static line	Unknown	L44	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
636	Surfacemount Static line	Unknown	L45	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
637	Static Line	Unknown	L45	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
638	Access Ladder (Al)	Unknown	L48	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
639	Handrail (Galv)	Unknown	L48	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
640	Access Ladder (Al)	Unknown	L49	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
641	Anchor Strop	Unknown	L49	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
642	Surfacemount Anchor Point 15 kN	Unknown	L49	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
643	Surfacemount Anchor Point 15 kN	Unknown	L49	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
644	Surfacemount Anchor Point 15 kN	Unknown	L49	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
645	Access Ladder (Al)	Unknown	L49	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
646	Handrail (Galv)	Unknown	L49	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
647	Handrail (Al)	Unknown	L50	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
648	Access Ladder (Al)	Unknown	L51	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
649	Surfacemount Anchor Point 15 kN	Unknown	L52	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
650	Surfacemount Anchor Point 15 kN	Unknown	L52	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
651	Surfacemount Anchor Point 15 kN	Unknown	L52	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
652	Access Stair (Galv)	Unknown	L52	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
653	Access Ladder (Al)	Unknown	L53	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
654	Surfacemount Anchor Point 15 kN	Unknown	L53	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
655	Surfacemount Anchor Point 15 kN	Unknown	L53	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
656	Surfacemount Anchor Point 15 kN	Unknown	L53	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
657	Access Ladder (Al)	Unknown	L54	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
658	Access Ladder (Al)	Unknown	L54	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
659	Surfacemount Anchor Point 15 kN	Unknown	L54	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
660	Surfacemount Anchor Point 15 kN	Unknown	L54	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
661	Surfacemount Anchor Point 15 kN	Unknown	L54	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
662	Surfacemount Anchor Point 15 kN	Unknown	L54	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
663	Access Ladder (Galv)	Unknown	L55	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
664	Handrail (Galv)	Unknown	L55	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
665	Step (Al)	Unknown	L55	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
666	Step (Al)	Unknown	L55	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
667	Step (Al)	Unknown	L55	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
668	Access Ladder (Al)	Unknown	L56	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Fail	
669	Handrail (Galv)	Unknown	L56	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
670	Step (Al)	Unknown	L56	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
671	Access Ladder (Al)	Unknown	L56	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
672	Access Ladder (Galv)	Unknown	L57	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
673	Handrail (Galv)	Unknown	L57	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
674	Access Ladder (Al)	Unknown	L57	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
675	Handrail (Al)	Unknown	L57	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
676	Step (Al)	Unknown	L58	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
677	Step (Al)	Unknown	L59	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
678	Step (Al)	Unknown	L59	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
679	Step (Al)	Unknown	L59	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
680	Step (Al)	Unknown	L59	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
681	Access Ladder (Al)	Unknown	L59	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
682	Handrail (Galv)	Unknown	L59	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
683	Access Ladder (Al)	Unknown	L59	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
684	Access Ladder (Al)	Unknown	L60	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
685	Anchor Strop	Unknown	L60	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
686	Surfacemount Anchor Point 15 kN	Unknown	L60	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
687	Surfacemount Anchor Point 15 kN	Unknown	L60	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
688	Surfacemount Anchor Point 15 kN	Unknown	L60	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
689	Surfacemount Anchor Point 15 kN	Unknown	L60	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
690	Access Ladder (Al)	Unknown	L62	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
691	Step (Al)	Unknown	L62	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
692	Access Ladder (Al)	Unknown	L63	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
693	Handrail (Galv)	Unknown	L63	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
694	Access Ladder (Al)	Unknown	L63	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
695	Access Stair (Al)	Unknown	L63	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
696	Access Ladder (Al)	Unknown	L64	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
697	Access Ladder (Al)	Unknown	L64	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
698	Step (Al)	Unknown	L64	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
699	Access Ladder (Al)	Unknown	L64	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
700	Access Ladder (Al)	Unknown	L65	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
701	Access Ladder (Al)	Unknown	L65	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
702	Access Ladder (Al)	Unknown	L66	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
703	Handrail (Galv)	Unknown	L66	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
704	Step (Al)	Unknown	L67	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
705	Step (Al)	Unknown	L68	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
706	Access Ladder (Al)	Unknown	L69	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
707	Access Ladder (Al)	Unknown	L70	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
708	Access Ladder (Al)	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
709	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
710	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
711	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
712	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
713	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
714	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
715	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
716	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
717	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
718	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
719	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
720	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
721	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
722	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
723	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
724	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
725	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
726	Surfacemount Anchor Point 15 kN	Unknown	L70	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
727	Access Ladder (Al)	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
728	Access Ladder (Al)	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
729	Handrail (Al)	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
730	Surfacemount Anchor Point 15 kN	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
731	Surfacemount Anchor Point 15 kN	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
732	Surfacemount Anchor Point 15 kN	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
733	Surfacemount Anchor Point 15 kN	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
734	Surfacemount Anchor Point 15 kN	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
735	Surfacemount Anchor Point 15 kN	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
736	Surfacemount Anchor Point 15 kN	Unknown	L71	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
737	Access Ladder (Al)	Unknown	L73	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
738	Surfacemount Anchor Point 15 kN	Unknown	L73	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
739	Surfacemount Anchor Point 15 kN	Unknown	L73	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
740	Surfacemount Anchor Point 15 kN	Unknown	L73	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
741	Surfacemount Anchor Point 15 kN	Unknown	L73	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
742	Surfacemount Anchor Point 15 kN	Unknown	L73	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
743	Surfacemount Anchor Point 15 kN	Unknown	L73	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
744	Surfacemount Anchor Point 15 kN	Unknown	L73	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
745	Access Ladder (Al)	Unknown	L74	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
746	Access Ladder (Al)	Unknown	L74	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
747	Step (Al)	Unknown	L75	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
748	Access Ladder (Galv)	Unknown	L75	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
749	Step (Al)	Unknown	L75	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
750	Handrail (Al)	Unknown	L75	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
751	Access Ladder (Galv)	Unknown	L77	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
752	Handrail (Galv)	Unknown	L77	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
753	Access Ladder (Al)	Unknown	L79	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
754	Handrail (Al)	Unknown	L80	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
755	Access Ladder (Al)	Unknown	L81	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
756	Handrail (Galv)	Unknown	L81	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
757	Handrail (AI)	Unknown	L84	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
758	Access Ladder (AI)	Unknown	L85	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
759	Access Ladder (AI)	Unknown	L85	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
760	Handrail (AI)	Unknown	L86	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
761	Surfacemount Anchor Point 15 kN	Unknown	L87	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
762	Surfacemount Anchor Point 15 kN	Unknown	L87	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
763	Surfacemount Anchor Point 15 kN	Unknown	L87	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
764	Surfacemount Anchor Point 15 kN	Unknown	L87	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
765	Surfacemount Anchor Point 15 kN	Unknown	L87	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
766	Surfacemount Anchor Point 15 kN	Unknown	L88	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
767	Surfacemount Anchor Point 15 kN	Unknown	L88	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
768	Surfacemount Anchor Point 15 kN	Unknown	L88	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
769	Surfacemount Anchor Point 15 kN	Unknown	L88	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
770	Access Ladder (Al)	Unknown	L88	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
771	Handrail (Galv)	Unknown	L88	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
772	Access Stair (Galv)	Unknown	L88	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
773	Access Ladder (Al)	Unknown	L89	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
774	Handrail (Galv)	Unknown	L89	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
775	Access Ladder (Al)	Unknown	L90	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
776	Handrail (Galv)	Unknown	L90	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
777	Access Ladder (Al)	Unknown	L92	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
778	Handrail (Galv)	Unknown	L92	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
779	Access Ladder (Al)	Unknown	L92	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
780	Access Ladder (Al)	Unknown	L92	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
781	Step (Al)	Unknown	L92	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
782	Step (Al)	Unknown	L92	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
783	Surfacemount Static line	Unknown	L93	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
784	Access Ladder (Al)	Unknown	L93	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
785	Access Ladder (Al)	Unknown	L94	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
786	Access Ladder (Al)	Unknown	L94	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
787	Access Ladder (Al)	Unknown	L96	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
788	Access Ladder (Al)	Unknown	L97	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
789	Access Ladder (Al)	Unknown	L97	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
790	Handrail (Galv)	Unknown	L97	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
791	Access Ladder (Al)	Unknown	L98	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
792	Access Ladder (Al)	Unknown	L98	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
793	Handrail (Galv)	Unknown	L98	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
794	Access Ladder (Al)	Unknown	L98	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
795	Access Ladder (Al)	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
796	Access Ladder (Al)	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
797	Access Ladder (Al)	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
798	Access Stair (Al)	Unknown	L99	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
799	Handrail (Galv)	Unknown	L99	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
800	Access Ladder (Al)	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
801	Anchor Strop	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
802	Surfacemount Anchor Point 15 kN	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
803	Surfacemount Anchor Point 15 kN	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
804	Surfacemount Anchor Point 15 kN	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
805	Surfacemount Anchor Point 15 kN	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
806	Surfacemount Anchor Point 15 kN	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
807	Surfacemount Anchor Point 15 kN	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
808	Surfacemount Anchor Point 15 kN	Unknown	L99	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
809	Access Ladder (Al)	Unknown	L100	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
810	Handrail (Al)	Unknown	L100	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
811	Handrail (Galv)	Unknown	L100	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
812	Step (Al)	Unknown	L100	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
813	Access Ladder (Al)	Unknown	L101	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
814	Access Ladder (Al)	Unknown	L102	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
815	Access Stair (Al)	Unknown	L103	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
816	Handrail (Galv)	Unknown	L103	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
817	Access Stair (AI)	Unknown	L103	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
818	Access Ladder (AI)	Unknown	L103	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
819	Access Ladder (AI)	Unknown	L104	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
820	Access Ladder (AI)	Unknown	L107	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
821	Access Stair (AI)	Unknown	L108	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
822	Access Ladder (AI)	Unknown	L109	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
823	Step (AI)	Unknown	L109	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
824	Access Ladder (AI)	Unknown	L110	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
825	Access Ladder (AI)	Unknown	L110	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
826	Step (AI)	Unknown	L110	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
827	Access Ladder (AI)	Unknown	L111	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
828	Step (AI)	Unknown	L111	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
829	Access Stair (Al)	Unknown	L111	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
830	Handrail (Galv)	Unknown	L111	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
831	Handrail (Al)	Unknown	L111	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
832	Access Stair (Al)	Unknown	L112	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
833	Access Ladder (Al)	Unknown	L112	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
834	Handrail (Al)	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
835	Step (Al)	Unknown	L112	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
836	Access Ladder (Al)	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
837	Anchor Strop	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
838	Surfacemount Anchor Point 15 kN	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
839	Surfacemount Anchor Point 15 kN	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
840	Surfacemount Anchor Point 15 kN	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
841	Surfacemount Anchor Point 15 kN	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
842	Surfacemount Anchor Point 15 kN	Unknown	L112	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
843	Access Ladder (Al)	Unknown	L113	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
844	Access Stair (Al)	Unknown	L114	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
845	Handrail (Al)	Unknown	L114	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
846	Handrail (Al)	Unknown	L115	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
847	Access Ladder (Al)	Unknown	L116	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
848	Handrail (Galv)	Unknown	L117	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
849	Access Stair (Al)	Unknown	L117	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
850	Access Ladder (Al)	Unknown	L117	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
851	Handrail (Al)	Unknown	L117	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
852	Access Ladder (Galv)	Unknown	L118	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
853	Access Ladder (Galv)	Unknown	L118	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
854	Access Ladder (Galv)	Unknown	L118	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
855	Access Ladder (Galv)	Unknown	L118	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
856	Handrail (Galv)	Unknown	L118	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
857	Access Stair (Al)	Unknown	L118	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
858	Surfacemount Anchor Point 15 kN	Unknown	L119	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
859	Surfacemount Anchor Point 15 kN	Unknown	L119	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
860	Access Ladder (Al)	Unknown	L119	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
861	Handrail (Galv)	Unknown	L119	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
862	Access Ladder (Al)	Unknown	L119	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
863	Surfacemount Anchor Point 15 kN	Unknown	L120	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
864	Surfacemount Anchor Point 15 kN	Unknown	L120	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
865	Surfacemount Anchor Point 15 kN	Unknown	L120	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
866	Surfacemount Anchor Point 15 kN	Unknown	L120	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
867	Handrail (Al)	Unknown	L120	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
868	Access Ladder (Al)	Unknown	L121	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
869	Handrail (Al)	Unknown	L121	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
870	Access Ladder (Al)	Unknown	L121	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
871	Access Ladder (Al)	Unknown	L122	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
872	Handrail (Galv)	Unknown	L122	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
873	Access Stair (Al)	Unknown	L123	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
874	Access Stair (Al)	Unknown	L123	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
875	Access Ladder (Al)	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
876	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
877	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
878	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
879	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
880	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
881	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
882	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
883	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
884	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
885	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
886	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
887	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
888	Handrail (Al)	Unknown	L124	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
889	Access Ladder (Al)	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
890	Access Ladder (Al)	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
891	Access Ladder (Al)	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
892	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
893	Surfacemount Anchor Point 15 kN	Unknown	L124	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
894	Access Ladder (Al)	Unknown	L125	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
895	Handrail (Al)	Unknown	L125	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
896	Access Ladder (Al)	Unknown	L125	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
897	Handrail (Galv)	Unknown	L125	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
898	Access Ladder (Al)	Unknown	L125	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
899	Access Ladder (Al)	Unknown	L125	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
900	Access Ladder (Al)	Unknown	L126	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
901	Access Stair (Al)	Unknown	L126	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
902	Access Ladder (Al)	Unknown	L126	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
903	Access Ladder (Al)	Unknown	L126	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
904	Access Ladder (Al)	Unknown	L126	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
905	Access Ladder (Galv)	Unknown	L127	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
906	Handrail (Galv)	Unknown	L127	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
907	Access Stair (Galv)	Unknown	L127	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
908	Access Ladder (Galv)	Unknown	L127	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
909	Handrail (Galv)	Unknown	L127	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
910	Access Ladder (Al)	Unknown	L127	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
911	Handrail (Al)	Unknown	L127	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
912	Surfacemount Anchor Point 15 kN	Unknown	L125	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
913	Surfacemount Anchor Point 15 kN	Unknown	L125	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
914	Surfacemount Anchor Point 15 kN	Unknown	L125	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
915	Surfacemount Anchor Point 15 kN	Unknown	L125	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
916	Surfacemount Anchor Point 15 kN	Unknown	L125	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
917	Access Stair (Galv)	Unknown	L128	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
918	Handrail (Galv)	Unknown	L128	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
919	Access Stair (Galv)	Unknown	L128	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
920	Handrail (Galv)	Unknown	L128	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
921	Access Stair (Al)	Unknown	L129	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
922	Access Ladder (Galv)	Unknown	L129	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
923	Handrail (Galv)	Unknown	L129	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
924	Access Ladder (Al)	Unknown	L129	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
925	Access Stair (Galv)	Unknown	L129	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
926	Access Ladder (Galv)	Unknown	L129	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
927	Handrail (Galv)	Unknown	L129	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
928	Access Ladder (Al)	Unknown	L130	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
929	Access Stair (Al)	Unknown	L130	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
930	Access Ladder (Al)	Unknown	L130	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
931	Handrail (Al)	Unknown	L130	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
932	Access Stair (Al)	Unknown	L131	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
933	Handrail (Al)	Unknown	L131	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
934	Access Stair (Al)	Unknown	L132	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
935	Handrail (Al)	Unknown	L132	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
936	Access Ladder (Al)	Unknown	L132	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
937	Access Stair (Al)	Unknown	L133	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
938	Handrail (Al)	Unknown	L133	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
939	Access Ladder (Al)	Unknown	L134	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
940	Surfacemount anchor Point 15 kN	Unknown	L134	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
941	Surfacemount anchor Point 15 kN	Unknown	L139	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
942	Surfacemount anchor Point 15 kN	Unknown	L139	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
943	Surfacemount anchor Point 15 kN	Unknown	L139	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
944	Surfacemount anchor Point 15 kN	Unknown	L139	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
945	Handrail (Galv)	Unknown	L139	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
946	Access Ladder (Al)	Unknown	L140	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
947	Anchor Strop	Unknown	L140	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
948	Surfacemount Anchor Point 15 kN	Unknown	L140	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
949	Surfacemount Anchor Point 15 kN	Unknown	L140	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
950	Access Stair (Galv)	Unknown	L142	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
951	Access Stair (Galv)	Unknown	L142	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
952	Handrail (Galv)	Unknown	L142	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
953	Ladder access bracket	Unknown	L142	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
954	Anchor Strop	Unknown	L142	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
955	Surfacemount Anchor Point 15 kN	Unknown	L142	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
956	Surfacemount Anchor Point 15 kN	Unknown	L142	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
957	Surfacemount Anchor Point 15 kN	Unknown	L142	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
958	Surfacemount Anchor Point 15 kN	Unknown	L142	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
959	Surfacemount Anchor Point 15 kN	Unknown	L142	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
960	Access Ladder (Al)	Unknown	L143	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
961	Surfacemount Anchor Point 15 kN	Unknown	L143	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
962	Surfacemount Anchor Point 15 kN	Unknown	L143	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
963	Surfacemount Anchor Point 15 kN	Unknown	L143	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
964	Surfacemount Anchor Point 15 kN	Unknown	L143	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
965	Surfacemount Anchor Point 15 kN	Unknown	L143	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
966	Surfacemount Anchor Point 15 kN	Unknown	L144	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
967	Surfacemount Anchor Point 15 kN	Unknown	L144	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
968	Surfacemount Anchor Point 15 kN	Unknown	L144	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
969	Access Ladder (Al)	Unknown	L145	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
970	Anchor Strop	Unknown	L145	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
971	Surfacemount Anchor Point 15 kN	Unknown	L145	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
972	Surfacemount Anchor Point 15 kN	Unknown	L145	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
973	Ladder access bracket	Unknown	L146	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
974	Anchor Strop	Unknown	L146	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
975	Surfacemount Anchor Point 15 kN	Unknown	L146	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
976	Surfacemount Anchor Point 15 kN	Unknown	L146	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
977	Surfacemount Anchor Point 15 kN	Unknown	L146	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
978	Surfacemount Anchor Point 15 kN	Unknown	L146	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
979	Surfacemount Anchor Point 15 kN	Unknown	L146	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
980	Step (Al)	Unknown	L146	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
981	Access Ladder (Al)	Unknown	L147	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
982	Access Ladder (Al)	Unknown	L148	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
983	Access Ladder (Al)	Unknown	L149	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
984	Handrail (Galv)	Unknown	L149	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
985	Step (Al)	Unknown	L149	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
986	Access Ladder (Al)	Unknown	L150	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
987	Access Ladder (Galv)	Unknown	L151	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
988	Handrail (Galv)	Unknown	L151	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
989	Step (Al)	Unknown	L151	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
990	Access Ladder (Al)	Unknown	L151	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
991	Handrail (Galv)	Unknown	L151	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
992	Access Ladder (Galv)	Unknown	L151	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
993	Handrail (Galv)	Unknown	L151	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
994	Access Ladder (Al)	Unknown	L152	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
995	Access Ladder (Al)	Unknown	L153	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
996	Handrail (Galv)	Unknown	L153	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
997	Access Ladder (Al)	Unknown	L154	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
998	Access Stair (Galv)	Unknown	L155	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
999	Step (Al)	Unknown	L155	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1000	Access Ladder (Al)	Unknown	L155	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1001	Step (W)	Unknown	L155	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1002	Handrail (Galv)	Unknown	L155	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
1003	Handrail (Galv)	Unknown	L157	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1004	Handrail (Galv)	Unknown	L158	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1005	Access Ladder (Al)	Unknown	L158	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
1006	Step (Al)	Unknown	L158	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1007	Access Ladder (Al)	Unknown	L160	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
1008	Handrail (Galv)	Unknown	L160	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1009	Access Ladder (Al)	Unknown	L160	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1010	Handrail (Galv)	Unknown	L160	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1011	Access Ladder (Al)	Unknown	L161	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1012	Step (Al)	Unknown	L162	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1013	Access Ladder (Galv)	Unknown	L162	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1014	Handrail (Galv)	Unknown	L162	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1015	Access Ladder (Galv)	Unknown	L162	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1016	Step (Al)	Unknown	L162	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1017	Access Ladder (Al)	Unknown	L164	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1018	Handrail (Galv)	Unknown	L164	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1019	Handrail (Al)	Unknown	L164	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1020	Step (Al)	Unknown	L164	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1021	Step (Al)	Unknown	L164	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1022	Access Ladder (Al)	Unknown	L165	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1023	Handrail (Al)	Unknown	L165	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1024	Step (Al)	Unknown	L166	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1025	Handrail (Galv)	Unknown	L166	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1026	Access Ladder (Al)	Unknown	L167	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1027	Step (Galv)	Unknown	L168	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1028	Step (Galv)	Unknown	L169	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1029	Step (Al)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1030	Access Ladder (Galv)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1031	Handrail (Galv)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1032	Access Ladder (Galv)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1033	Access Ladder (Galv)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1034	Access Ladder (Galv)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1035	Step (Al)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1036	Step (Al)	Unknown	L170	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1037	Access Ladder (Al)	Unknown	L171	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
1038	Anchor Strop	Unknown	L171	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1039	Purlinfix anchor point	Unknown	L171	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1040	Step (Al)	Unknown	L171	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1041	Access Ladder (Al)	Unknown	L173	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1042	Handrail (Galv)	Unknown	L173	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1043	Static Line	Unknown	L175	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	
1044	Static Line	Unknown	L175	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1045	Static Line	Unknown	L175	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	
1046	Static Line	Unknown	L175	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1047	Static Line	Unknown	L176	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	
1048	Static Line	Unknown	L176	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	
1049	Static Line	Unknown	L176	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	
1050	Access Ladder (Galv)	Unknown	L178	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1051	Handrail (Galv)	Unknown	L178	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1052	Access Stair (Galv)	Unknown	L179	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1053	Surfacemount Anchor Point 15 kN	Unknown	L179	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1054	Surfacemount Anchor Point 15 kN	Unknown	L179	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1055	Surfacemount Anchor Point 15 kN	Unknown	L179	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1056	Handrail (Al)	Unknown	L179	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1057	Access Ladder (Galv)	Unknown	L180	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	Tagged as "Out of Service"
1058	Access Ladder (Al)	Unknown	L181	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
1059	Anchor Strop	Unknown	L181	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1060	Surfacemount Anchor Point 15 kN	Unknown	L181	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1061	Surfacemount Anchor Point 15 kN	Unknown	L181	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1062	Surfacemount Anchor Point 15 kN	Unknown	L181	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1063	Surfacemount Anchor Point 15 kN	Unknown	L181	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1064	Static Line	Unknown	L181	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	
1065	Static Line	Unknown	L181	1/10/2016	24/04/2020	24/04/2021	AS1891.4:2009	Fail	
1066	Access Ladder (Al)	Unknown	L183	1/05/2019	24/04/2020	24/04/2021	AS1657:2018	Pass	
1067	Anchor Strop	Unknown	L183	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1068	Surfacemount Anchor Point 15 kN	Unknown	L183	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1069	Access Ladder (Al)	Unknown	L184	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1070	Handrail (Galv)	Unknown	L184	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1071	Access Ladder (Al)	Unknown	L184	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1072	Handrail (Galv)	Unknown	L184	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1073	Step (Al)	Unknown	L184	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1074	Step (Al)	Unknown	L184	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1075	Step (Al)	Unknown	L184	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1076	Access Ladder (Al)	Unknown	L185	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1077	Handrail (Galv)	Unknown	L185	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1078	Step (Al)	Unknown	L185	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Pass	
1079	Access Ladder (Al)	Unknown	L185	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	
1080	Access Ladder (Al)	Unknown	L185	1/10/2016	24/04/2020	24/04/2021	AS1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182

**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1081	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1082	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1083	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1084	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1085	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1086	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1087	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1088	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1089	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1090	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1091	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1092	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Vicinity Centres

**Job Ref:** SM12182


**Site:** Chadstone

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1093	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	
1094	Surfacemount Anchor Point 15 kN	Unknown	L187	1/05/2019	24/04/2020	24/04/2021	AS1891.4:2009	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 24-04-2020

SIGNATURE:





All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



Roof Safety Report for  
Site Name Here

**ADDITIONAL FINDINGS & RECOMMENDATIONS**

Table below summarises additional findings and recommendations in support of the Roof Safety Report.

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
54 4	Building: General Stores Location Reference: <a href="#">L188</a> Task: Access to the roof									
		No height safety system installed	Trips, Slips and Falls	Awareness induction	High	Access ladder, anchor stop and anchors to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7  AS 1657-2018 3.1.4
54 5	Building: General Stores Location Reference: <a href="#">L10</a> Task: Access to the roof									
		No height safety system installed	Trips, Slips and Falls	Awareness induction	High	Anchors to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7  AS 1657-2018 3.1.4



**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)