

# Roof Safety Report

Claisbrook Heights

Prepared By: Safemaster Safety Products  
Date: 04/09/2018

## Roof Safety Report for Claisbrook Heights

### **CONFIDENTIALITY/SECURITY**

Information obtained from and about Claisbrook Heights in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Claisbrook Heights and not to any other source.

### **DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

### **CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.

If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Glenn Kinsey (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:

**Glenn Kinsey (Recertification Technician)**

Roof Safety Report for  
Claisbrook Heights

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Logiudice	Claisbrook Heights	Anchor Points Signage Ladder

---

**DATE OF INSPECTION**

15/08/2018

**INSPECTION METHODOLOGY**

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Claisbrook Heights buildings.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Logiudice

**Job Ref:** SM 9078

**Site:** Claisbrook Heights

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Logiudice

**Job Ref:** SM 9078

**Site:** Claisbrook Heights

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point 21 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
22	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
23	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
24	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Logiudice

**Job Ref:** SM 9078

**Site:** Claisbrook Heights

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
26	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
27	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
28	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
29	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
30	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
31	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
32	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
33	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
34	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
35	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
36	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Logiudice

**Job Ref:** SM 9078

**Site:** Claisbrook Heights

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
38	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
39	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
40	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
41	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
42	Frog Link Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
43	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
44	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
45	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
46	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
47	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
48	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Logiudice

**Job Ref:** SM 9078

**Site:** Claisbrook Heights

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
50	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
51	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
52	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
53	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
54	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
55	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
56	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
57	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
58	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
59	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
60	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** Logiudice

**Job Ref:** SM 9078

**Site:** Claisbrook Heights

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
62	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
63	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
64	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
65	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009	Pass	
66	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009		Need access to balconys to test anchors before use at this level.
67	Surfacemount Abseil Anchor Point 15 kn	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1891.4:2009		Need access to balconys to test anchors before use at this level.
68	Access Ladder	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1657:2013	Pass	
69	Access Ladder	Safemaster	Claisbrook Heights	1/07/2014	15/08/2018	15/08/2019	AS1657:2013	Pass	
70	Access Sign	Safemaster	Claisbrook Heights	1/07/2015	15/08/2018	15/08/2019	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: GLENN KINSEY

DATE: 04/09/2018

SIGNATURE:

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# Roof Safety Report for Claisbrook Heights

## COMPLIANT REQUIREMENTS

There are no recommendations at this point in time.

[illegible]



**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)