

# Roof Safety Report

Collie Senior High School

Prepared By: Safemaster Safety Products  
Date: 12/04/18

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Collie SHS in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Bunbury BMW and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Trevor Harris (Recertification Technician)**

Roof Safety Report for  
**Collie SHS**

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Collie Senior High School	Anchor Points Signage Ladder Bracket

---

**DATE OF INSPECTION**

12/04/18

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Collie SHS buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

N/A



# Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM7161

**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
2	Ladder Bracket	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
3	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
4	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
5	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
6	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
7	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
8	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
9	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
10	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
11	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
12	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
13	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
14	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
15	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
16	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
17	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
18	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
19	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
20	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
21	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
22	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
23	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
24	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
25	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
26	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
27	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
28	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
29	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
30	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Admin / Rooms 6/7/8 Art 1/2 & Foyer	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
31	Sign	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
32	Ladder Bracket	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
33	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
34	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
35	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
36	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
37	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
38	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
39	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
40	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
41	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
42	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
43	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
44	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
45	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
46	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
47	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
48	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
49	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
50	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
51	Anchor Point-Surface Mount-15kN	R.S.S	Performing Arts Centre	29/04/2013	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
52	Sign	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
53	Ladder Bracket	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
54	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
55	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
56	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
57	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
58	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
59	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
60	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
61	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
62	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
63	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
64	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
65	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
66	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
67	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
68	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
69	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 1-5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
70	Sign	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
71	Ladder Bracket	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
72	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
73	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
74	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
75	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
76	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
77	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
78	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
79	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
80	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
81	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
82	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
83	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
84	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
86	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
87	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
88	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
89	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
90	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
91	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
92	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
93	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
94	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
95	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
96	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 14/15/25/T2	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
97	Sign	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
98	Ladder Bracket	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
99	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
100	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
101	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
102	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
103	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
104	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
105	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
106	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
107	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
108	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
109	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
110	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
111	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
112	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
113	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
114	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
115	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
116	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lab 1/2/3/4/5	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
117	Sign	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
118	Ladder Bracket	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
119	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
120	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
121	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
122	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
123	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
124	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
125	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
126	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Canteen	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
127	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Cante en	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
128	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Cante en	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
129	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Undercroft/Cante en	19/05/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
130	Sign	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
131	Ladder Bracket	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
132	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
133	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
134	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
135	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
136	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
137	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
138	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
139	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
140	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
141	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
142	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
143	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 16-20	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
144	Sign	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
145	Ladder Bracket	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
146	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
147	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
148	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
149	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
150	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
151	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
152	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
153	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
154	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
156	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
157	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Library	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
158	Sign	Safemaster / Safemaster	Rooms21-24	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
159	Ladder Bracket	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
160	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
161	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
162	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
163	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
164	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
165	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
166	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
167	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
168	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
170	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
171	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
172	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
173	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
174	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Rooms 21-24	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
175	Sign	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
176	Ladder Bracket	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
177	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
178	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
179	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
180	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
181	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
182	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
183	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
184	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
185	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
186	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
187	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
188	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
189	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
190	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
191	Anchor Point-Surface Mount-15kN	RSS	SS Admin	12/02/2013	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
192	Sign	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
193	Ladder Bracket	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
194	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
195	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
196	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
197	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
198	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
199	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
200	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
201	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
202	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
203	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
204	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
205	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
206	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
207	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
208	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
209	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
210	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Design & Tech	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
211	Sign	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
212	Ladder Bracket	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
213	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
214	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
215	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
216	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
217	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
218	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
219	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
220	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
221	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
222	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
223	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
224	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
225	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
226	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
227	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
228	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM7161  
**Site:** Collie Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
230	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
231	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
232	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
233	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
234	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
235	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
236	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
237	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
238	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access
239	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Gym	1/03/2011	12/04/2018	12/10/2018	AS1891.4:2009	Not Certified	No Access

AUTHORISED BY: TREVOR HARRIS

DATE: 12/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM7161

**Site:** Collie SHS

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
2	Sign	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
3	Ladder Bracket	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
4	Ladder Bracket	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
5	Anchor Point-Purlin Fix-21kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
6	Anchor Point-Purlin Fix-21kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
7	Anchor Point-Purlin Fix-21kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
8	Anchor Point-Purlin Fix-21kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
9	Anchor Point-Purlin Fix-21kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
10	Anchor Point-Purlin Fix-21kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
11	Anchor Point-Surface Mount-15kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
12	Anchor Point-Surface Mount-15kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM7161

**Site:** Collie SHS

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Anchor Point-Surface Mount-15kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
14	Anchor Point-Surface Mount-15kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
15	Anchor Point-Surface Mount-15kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order
16	Anchor Point-Surface Mount-15kN	RSS	W1/2/3	Unknown	12/04/2018	12/10/2018	AS1891.4:2009	Pass	In Working Order

AUTHORISED BY: TREVOR HARRIS

DATE: 12/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)