

Roof Safety Report

DFO Brisbane, QLD 4008

Prepared By: Safemaster Safety Products
Date: 13-02-2020

CONFIDENTIALITY/SECURITY

Information obtained from and about DFO Brisbane Shopping Centre, QLD in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to DFO Brisbane Shopping Centre, QLD and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
31-33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



James Townsend (Recertification Technician)

Roof Safety Report for
DFO Brisbane, QLD 4008

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
DFO Brisbane	18th Avenue, Brisbane Airport QLD 4008	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

13-02-2020

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on DFO Brisbane buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
13	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
25	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
27	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
37	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
47	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
48	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
49	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
51	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
52	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
53	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
54	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
57	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
58	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
59	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
60	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
61	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
62	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
63	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
64	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
65	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
66	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
68	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
69	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
70	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
71	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
72	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
73	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
74	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
75	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
76	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
77	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
79	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
80	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
81	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
82	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
83	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
84	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
85	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
86	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
87	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
88	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
90	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
91	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
92	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
93	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
94	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
95	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
96	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
97	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
98	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
99	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
101	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
102	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
103	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
104	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
105	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
106	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
107	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
108	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
109	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
110	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
112	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
113	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
114	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
115	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
116	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
117	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
118	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
119	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
120	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
121	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
123	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
124	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
125	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
126	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
127	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
128	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
129	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
130	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	13/02/2020	13/02/2021	AS1891.4:2009	Pass	
131	Surfacemount Anchor Point 15 Kn	Unknown	L1	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
132	Surfacemount Anchor Point 15 Kn	Unknown	L1	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Surfacemount Anchor Point 15 Kn	Unknown	L1	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
134	Surfacemount Anchor Point 15 Kn	Unknown	L1	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
135	Surfacemount Anchor Point 15 Kn	Unknown	L1	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
136	Access Ladder (Al)	Unknown	L1	10/01/2019	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
137	Access Ladder (Al)	Unknown	L2	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	
138	Handrail (Al)	Unknown	L2	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
139	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
140	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
141	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
142	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
143	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
145	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
146	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
147	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
148	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
149	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
150	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
151	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
152	Surfacemount Anchor Point 15 Kn	Unknown	L3	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
153	Access Ladder (Al)	Unknown	L4	10/01/2019	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
154	Access Ladder (Al)	Unknown	L5	10/01/2019	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Access Ladder (Al)	Unknown	L6	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
156	Access Ladder (Al)	Unknown	L6	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	
157	Access Ladder (Al)	Unknown	L7	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
158	Surfacemount Anchor Point 15 Kn	Unknown	L8	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
159	Surfacemount Anchor Point 15 Kn	Unknown	L8	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
160	Surfacemount Anchor Point 15 Kn	Unknown	L8	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
161	Surfacemount Anchor Point 15 Kn	Unknown	L8	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
162	Surfacemount Anchor Point 15 Kn	Unknown	L8	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
163	Surfacemount Anchor Point 15 Kn	Unknown	L8	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
164	Surfacemount Anchor Point 15 Kn	Unknown	L8	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
165	Access Ladder (Al)	Unknown	L9	10/01/2019	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Surfacemount Anchor Point 15 Kn	Unknown	L9	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
167	Anchor Strop	Unknown	L9	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
168	Surfacemount Anchor Point 15 Kn	Unknown	L10	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
169	Surfacemount Anchor Point 15 Kn	Unknown	L10	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
170	Access Ladder (Al)	Unknown	L11	10/01/2019	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
171	Access Ladder (Galv)	Unknown	L12	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
172	Access Ladder (Galv)	Unknown	L12	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
173	Handrail (Galv)	Unknown	L12	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
174	Access Ladder (Al)	Unknown	L13	10/01/2019	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
175	Surfacemount Anchor Point 15 Kn	Unknown	L13	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
176	Surfacemount Anchor Point 15 Kn	Unknown	L13	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
177	Surfacemount Anchor Point 15 Kn	Unknown	L13	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
178	Surfacemount Anchor Point 15 Kn	Unknown	L13	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
179	Access Ladder (Galv)	Unknown	L14	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
180	Access Ladder (Galv)	Unknown	L14	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
181	Handrail (Galv)	Unknown	L14	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
182	Access Ladder (Al)	Unknown	L16	10/01/2019	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
183	Surfacemount Anchor Point 15 Kn	Unknown	L16	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
184	Access Ladder (Galv)	Unknown	L18	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
185	Access Ladder (Galv)	Unknown	L18	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
186	Handrail (Galv)	Unknown	L18	8/08/2015	13/02/2020	13/02/2021	AS1657:2013	Pass	New Install
187	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182


Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
188	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
189	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
190	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
191	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
192	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
193	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install
194	Surfacemount Anchor Point 15 Kn	Unknown	L19	10/01/2019	13/02/2020	13/02/2021	AS1891.4:2009	Pass	New Install

AUTHORISED BY: JAMES TOWNSEND

DATE: 13-02-2020

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au