

Safemaster®
SAFETY PRODUCTS PTY LTD

Roof Safety Report

DFO Brisbane, QLD 4008

Prepared By: Safemaster Safety Products
Date: 31 Jan 2019

CONFIDENTIALITY/SECURITY

Information obtained from and about DFO Brisbane Shopping Centre, QLD in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to DFO Brisbane Shopping Centre, QLD and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
31-33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



James Townsend (Recertification Technician)

Roof Safety Report for

DFO Brisbane, QLD 4008

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
DFO Brisbane	18th Avenue, Brisbane Airport QLD 4008	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

10/01/2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on DFO Brisbane buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester

Safemaster Safety Products
PH: (08) 6243 3111
Fax: (08) 9456 5014
EMAIL: inspections@safemaster.net.au





Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
13	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
25	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
27	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
37	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point 15 Kn	Aegis	DFO1	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
47	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
48	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO1	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
49	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
51	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
52	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
53	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
54	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
57	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
58	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
59	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
60	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
61	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
62	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
63	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
64	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
65	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
66	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
68	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
69	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
70	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
71	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
72	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
73	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
74	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
75	Purlin Fix Anchor Point 15 Kn	Aegis	DFO2	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
76	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
77	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
79	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
80	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
81	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
82	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
83	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
84	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
85	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
86	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
87	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
88	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
90	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
91	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
92	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
93	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
94	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
95	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
96	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
97	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
98	Purlin Fix Anchor Point 15 Kn	Aegis	DFO3	1/11/2005	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
99	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
101	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
102	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
103	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
104	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
105	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
106	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
107	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
108	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
109	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
110	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
112	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
113	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
114	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
115	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
116	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
117	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
118	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
119	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
120	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
121	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
123	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
124	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
125	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
126	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
127	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
128	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
129	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
130	Surfacemount Anchor Point 15 Kn	Aussie Height Safety	DFO4	8/08/2015	10/01/2019	10/01/2020	AS1891.4:2009	Pass	
131	Access Ladder (Al)	Unknown	L2	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Pass	
132	Handrail (Al)	Unknown	L2	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Access Ladder (Al)	Unknown	L6	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	
134	Access Ladder (Al)	Unknown	L6	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Pass	
135	Access Ladder (Al)	Unknown	L7	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	
136	Access Ladder (Galv)	Unknown	L12	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	
137	Access Ladder (Galv)	Unknown	L12	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	
138	Handrail (Galv)	Unknown	L12	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Pass	
139	Access Ladder (Galv)	Unknown	L14	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	
140	Access Ladder (Galv)	Unknown	L14	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	
141	Handrail (Galv)	Unknown	L14	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Pass	
142	Access Ladder (Galv)	Unknown	L18	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	
143	Access Ladder (Galv)	Unknown	L18	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au


Client: Vicinity Centres
Job Ref: SM12182
Site: DFO Brisbane

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Handrail (Galv)	Unknown	L18	8/08/2015	10/01/2019	10/01/2020	AS1657:2013	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 10/01/2019

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Safemaster Safety Products
31-33 Catalano Road, Canning Vale WA 6155
PO Box 1373 Canning Vale WA 6970
Ph: (08) 6243 3111
Fax: (08) 9456 5014
Email: info@safemaster.net.au
Web: www.safemaster.net.au