

Roof Safety Report

Dianella Plaza, WA 6059

Prepared By: Safemaster Safety Products
Date: 07-08-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Dianella Plaza in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Dianella Plaza and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Brandon Vitek (Safemaster Safety Products)
31-33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Brandon Vitek (Recertification Technician)

Roof Safety Report for
Dianella Plaza, WA 6059

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres- Dianella Plaza	Dianella Plaza	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

18-06-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Dianella Plaza buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	RIS	Main Roof	1/03/2011	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	Safemaster	Main Roof	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	Safemaster	Main Roof	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	Safemaster	Main Roof	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	Safemaster	Main Roof	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	Safemaster	Main Roof	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	Safemaster	Main Roof	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
13	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
14	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
15	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
16	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
17	Surfacemount Anchor Point	Safemaster	Main Roof	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
18	Horizontal Static Line	Safemaster	Main Roof	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
25	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
27	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
37	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point	Safemaster	Woolworths	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Purlin Fix Anchor Point	Safemaster	L1	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
46	Purlin Fix Anchor Point	Safemaster	L1	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
47	Purlin Fix Anchor Point	Safemaster	L1	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
48	Permanent Incline Ladder (Alu) with Paraprt Crossover and Return Ladder	Safemaster	L1	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
49	Access Ladder (Al)	Safemaster	L1	19/03/2018			AS1657:2018	Pass	
50	Ladder access bracket	Safemaster	L1	19/03/2018			AS1891.4:2009	Pass	
51	Sign	Safemaster	L1	19/03/2018			AS1891.4:2009	Pass	
52	Anchor Strop	Safemaster	L1	19/03/2018			AS1891.4:2009	Pass	
53	Purlin Fix Anchor Point	Safemaster	L1	19/03/2018			AS1891.4:2009	Pass	
54	Purlin Fix Anchor Point	Safemaster	L2	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point	Safemaster	L2	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Purlin Fix Anchor Point	Safemaster	L2	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
57	Ladder Bracket	Safemaster	L2	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
58	Access Sign	Safemaster	L2	1/04/2014	18/06/2019	18/06/2020	AS1319:1994 AS1891.4-2009	Pass	
59	Access Ladder (AI)	Safemaster	L3	19/03/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
60	Access Sign	Safemaster	L3	1/04/2014	18/06/2019	18/06/2020	AS1319:1994 AS1891.4-2009	Pass	
61	Roof Walkway	Unknown	L5	Unknown	18/06/2019	18/06/2020	AS1657:2018	Pass	
62	Steps	Safemaster	L7	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Fail	Non-compliant
63	Purlin Fix Anchor Point	Safemaster	L8	19/03/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
64	Purlin Fix Anchor Point	Safemaster	L8	19/03/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
65	Purlin Fix Anchor Point	Safemaster	L8	19/03/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
66	Step over (AI)	Safemaster	L9	19/03/2018			AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Step (Al)	Safemaster	L9	19/03/2018			AS1657:2018	Pass	
68	Access Ladder	Safemaster	L14	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Fail	Non-compliant
69	Step over (Al)	Safemaster	L14	19/03/2018			AS1657:2018	Pass	
70	Guardrail	Unknown	L20	Unknown	18/06/2019	18/06/2020	AS1657:2018	Pass	
71	Step over (Al)	Safemaster	L20	19/03/2018			AS1657:2018	Pass	
72	Access Ladder	Safemaster	L21	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	Requires caps to sharp edges on bolts
73	Access Ladder	Safemaster	L22	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	Requires caps to sharp edges on bolts
74	Access Ladder	Safemaster	L23	Unknown	18/06/2019	18/06/2020	AS1657:2018	Fail	Parapet platform too small, insufficient landing at top of ladder
75	Sign-Harness Must Be Worn	Safemaster	L24	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
76	Sign-No Roof Access	Safemaster	L 25	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
77	Sign-No Roof Access	Safemaster	L 25	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L26	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
79	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L26	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
80	Step (Al)	Safemaster	L28	19/03/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
81	Sign-Fragile and Brittle Surface	Safemaster	L30	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
82	Sign-Fragile and Brittle Surface	Safemaster	L30	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
83	Sign-Fragile and Brittle Surface	Safemaster	L30	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
84	Sign-Fragile and Brittle Surface	Safemaster	L30	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
85	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L31	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
86	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L31	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
87	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L31	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
88	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L31	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Permanent Step Ladder (Alu) with Top Platform	Safemaster	L32 Ground Level	1/07/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
90	Permanent Step Ladder (Alu)	Safemaster	L32 Mid Level	1/07/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
91	Roof Access Hatch	Safemaster	L32	1/07/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
92	Access Sign	RIS	L32	1/03/2011	18/06/2019	18/06/2020	AS1891.4:2009	N/A	Sign is redundant but left for original system information
93	Access Sign	Safemaster	L32	1/04/2016	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
94	Sign-Harness Must Be Worn	Safemaster	L33	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
95	Steps	Safemaster	L34	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Fail	Non-compliant
96	Steps	Safemaster	L34	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Fail	Non-compliant
97	Steps	Safemaster	L35	1/04/2014	18/06/2019	18/06/2020	AS1657:2013	Fail	Non-compliant
98	Access Ladder	Safemaster	L38	1/07/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
99	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L38	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Ladder Bracket	Safemaster	L38	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Fail	Bottom landing required
101	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L38	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
102	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L38	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
103	Horizontal Static Line	Safemaster	L39	1/12/2005	18/06/2019	18/06/2020	AS1891.4:2009	Fail	Over 10 years old
104	Access Ladder (Al)	Safemaster	L39	19/03/2018			AS1657:2018	Pass	
105	Sign-Fragile and Brittle Surface	Safemaster	L39	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
106	Sign-Fragile and Brittle Surface	Safemaster	L39	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
107	Sign-Fragile and Brittle Surface	Safemaster	L39	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
108	Permanent Step Ladder	Safemaster	L40	1/07/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
109	Stairs	Safemaster	L40	1/07/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
110	Sign-Fragile and Brittle Surface	Safemaster	L40	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Sign-Fragile and Brittle Surface	Safemaster	L40	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
112	Sign-Fragile and Brittle Surface	Safemaster	L40	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
113	Sign-Fragile and Brittle Surface	Safemaster	L40	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
114	Sign-Fragile and Brittle Surface	Safemaster	L40	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
115	Steps	Safemaster	L41	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	
116	Steps	Safemaster	L41	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	
117	Step over (Al)	Safemaster	L41	19/03/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
118	Step over (Al)	Safemaster	L41	19/03/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
119	Access Ladder	Safemaster	L42	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	
120	Guardrail	Safemaster	L42	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	
121	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L43	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Access Ladder	Safemaster	L44	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	
123	Guardrail	Safemaster	L44	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	
124	Access Ladder	Safemaster	L45	19/03/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
125	Purlin Fix Anchor Point	Safemaster	L45	19/03/2018			AS1891.4:2009	Pass	
126	Purlin Fix Anchor Point	Safemaster	L45	19/03/2018			AS1891.4:2009	Pass	
127	Guardrail (Al)	Safemaster	L45	19/03/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
128	Access Ladder	Safemaster	L46 Ground Level	1/07/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
129	Access Hatch	Workplace Access and Safety	L46	Unknown	18/06/2019	18/06/2020	AS1657:2018	Pass	
130	Guardrail	Workplace Access and Safety	L46	Unknown	18/06/2019	18/06/2020	AS1657:2018	Pass	
131	Access Ladder	Safemaster	L47	1/04/2014	18/06/2019	18/06/2020	AS1657:2018	Pass	
132	Guardrail	Unknown	L47	Unknown	18/06/2019	18/06/2020	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L51	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
134	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L51	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
135	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L51	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
136	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L51	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
137	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L54	1/07/2018	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
138	Sign-EWP Access Only	Safemaster	L52	1/07/2018	18/06/2019	18/06/2020	AS1319:1994	Pass	
139	Access Ladder	Unknown	L55	Unknown	18/06/2019	18/06/2020	AS1657:2018	Pass	
140	Wall Mountd Portable Ladder	Safemaster	L55	1/08/2018	18/06/2019	18/06/2020	AS1657:2018	Pass	
141	Purlin Fix Anchor Point	Safemaster	L56	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
142	Purlin Fix Anchor Point	Safemaster	L56	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	
143	Ladder Bracket	Safemaster	L56	1/04/2014	18/06/2019	18/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Dianella Plaza

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Access Sign	Safemaster	L56	1/04/2016	18/06/2019	18/06/2020	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Brandon Vitek

DATE: 07/08/2019

SIGNATURE:

B. Vitek

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155
PO Box 1373 Canning Vale WA 6970
Ph: (08) 6243 3111
Fax: (08) 9456 5014
Email: info@safemaster.net.au
Web: www.safemaster.net.au