

Roof Safety Report

Emmanuel Christian Community School
Casserley Campus

Prepared By: Safemaster Safety Products
Date: 1/02/2018

CONFIDENTIALITY/SECURITY

Information obtained from and about ECCS Casserley Campus in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Emmanuel Christian Community School and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.

If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Andrew Treen (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Andrew Treen (Recertification Technician)

Roof Safety Report for
Emmanuel Christian Community School – Casserley Campus

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Emmanuel Christian Community School	ECCS Casserley Campus	Anchor Points Signage Ladder Bracket Ladder

DATE OF INSPECTION

22/01/2018

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on ECCS Casserley Campus buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

N/A



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Emmanuel Christian Community School

Job Ref: SM12133

Site: Casserley Campus - 50 Casserley Ave, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1319:1994 AS1891.4-2009	Pass	
2	Ladder Access Bracket	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
3	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
4	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
5	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
6	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
7	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
8	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
9	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
10	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
11	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
12	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Emmanuel Christian Community School

Job Ref: SM12133

Site: Casserley Campus - 50 Casserley Ave, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Inclined Rung Ladder	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1657:2013	Pass	
14	Inclined Rung Ladder	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1657:2013	Pass	
15	Sign	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1319:1994 AS1891.4-2009	Pass	
16	Ladder Access Bracket	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
17	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
18	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
19	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
20	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
21	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
22	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
23	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
24	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Emmanuel Christian Community School

Job Ref: SM12133

Site: Casserley Campus - 50 Casserley Ave, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
26	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
27	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
28	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
29	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	
30	Anchor Point-Surfacemount-15kN	Safemaster / Safemaster	Main Roof	7/10/2016	22/01/2018	22/01/2019	AS1891.4:2009	Pass	

AUTHORISED BY: ANDREW TREEN

DATE: 1/02/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Roof Safety Report for Emmanuel Christian Community School – Casserley Campus

COMPLIANCE REQUIREMENTS

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au