

Roof Safety Report

Galleria, WA 6062

Prepared By: Safemaster Safety Products
Date: 28-08-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Galleria in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Galleria and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.

If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Brandon Vitek (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Brandon Vitek (Recertification Technician)

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres - Galleria	Galleria	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

03-07-2019 & 25-09-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Galleria buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
2	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
3	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
4	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
5	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
6	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
7	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
8	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
9	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
10	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
11	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
12	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
14	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
15	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
16	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
17	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
18	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
19	Purlin Fix Anchor point	Safemaster	L1 - Cinema	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
20	Purlin Fix Anchor point	Sayfa / Access Infrastructure	L1 - Cinema	15/11/2011	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
21	Purlin Fix Anchor point	Sayfa / Access Infrastructure	L1 - Cinema	15/11/2011	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
22	Purlin Fix Anchor point	Sayfa / Access Infrastructure	L1 - Cinema	15/11/2011	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
23	Purlin Fix Anchor point	Sayfa / Access Infrastructure	L1 - Cinema	15/11/2011	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
24	Purlin Fix Anchor point	Safemaster	L4	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Purlin Fix Anchor point	Safemaster	L4	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
26	Purlin Fix Anchor point	Safemaster	L4	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
27	Purlin Fix Anchor point	Safemaster	L5	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
28	Purlin Fix Anchor point	Safemaster	L5	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
29	Purlin Fix Anchor point	Safemaster	L5	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
30	Purlin Fix Anchor point	Safemaster	L5	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
31	Purlin Fix Anchor point	Safemaster	L5	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
32	Anchor Point-Surface Mount-15kN	Safemaster	L5	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
33	Anchor Point-Surface Mount-15kN	Safemaster	L5	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
34	Anchor Point-Surface Mount-15kN	Safemaster	L5	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
35	Anchor Point-Surface Mount-15kN	Safemaster	L5	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
36	Anchor Point-Surface Mount-15kN	Safemaster	L5	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor point	Safemaster	L6	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
38	Purlin Fix Anchor point	Safemaster	L6	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
39	Purlin Fix Anchor point	Safemaster	L6	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
40	Access Strop	Safemaster	L6	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
41	Anchor Point-Purlin Fix-21kN	Safemaster	L7	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
42	Anchor Point-Purlin Fix-21kN	Safemaster	L7	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
43	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L7	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
44	Anchor Point-Purlin Fix-21kN	Safemaster	L8	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
45	Anchor Point-Purlin Fix-21kN	Safemaster	L8	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
46	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L9	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
47	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L9	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
48	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L9	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Anchor Point-Purlin Fix-21kN	Safemaster	L10	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
50	Anchor Point-Purlin Fix-21kN	Safemaster	L10	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
51	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
52	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
53	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
54	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
55	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
56	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
57	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
58	Anchor Point-Purlin Fix-21kN	Safemaster	L12	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor stem is bent
59	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L13	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
60	Anchor Point-Purlin Fix-21kN	Safemaster	L13	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L13	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
62	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L13	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
63	Anchor Point-Purlin Fix-21kN	Safemaster	L13	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
64	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L13	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
65	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
66	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
67	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
68	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
69	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
70	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
71	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
72	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Anchor Point-Purlin Fix-21kN	Safemaster	L14	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
74	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L15	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
75	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L15	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
76	Anchor Point-Surface Mount-15kN	Safemaster	L15	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
77	Anchor Point-Surface Mount-15kN	Safemaster	L15	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
78	Anchor Point-Surface Mount-15kN	Safemaster	L15	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
79	Anchor Point-Purlin Fix-21kN	Safemaster	L16	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
80	Anchor Point-Purlin Fix-21kN	Safemaster	L16	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
81	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L16	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
82	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L16	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
83	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L16	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
84	Purlin Fix Anchor point	Safemaster	L32	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Purlin Fix Anchor point	Safemaster	L32	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
86	Purlin Fix Anchor point	Safemaster	L32	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
87	Purlin Fix Anchor point	Safemaster	L32	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
88	Purlin Fix Anchor point	Safemaster	L33	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
89	Purlin Fix Anchor point	Safemaster	L33	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
90	Purlin Fix Anchor point	Safemaster	L33	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
91	Purlin Fix Anchor point	Safemaster	L33	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
92	Anchor Point-Surface Mount-15kN	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
93	Anchor Point-Surface Mount-15kN	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
94	Anchor Point-Surface Mount-15kN	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
95	Anchor Point-Surface Mount-15kN	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
96	Anchor Point-Surface Mount-15kN	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Anchor Point-Surface Mount-15kN	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
98	Anchor Point-Surface Mount-15kN	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
99	Purlin Fix Anchor point	Safemaster	L48	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
100	Purlin Fix Anchor point	Safemaster	L48	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
101	Purlin Fix Anchor point	Safemaster	L48	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
102	Purlin Fix Anchor point	Safemaster	L49	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
103	Purlin Fix Anchor point	Safemaster	L49	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
104	Purlin Fix Anchor point	Safemaster	L49	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
105	Purlin Fix Anchor point	Safemaster	L49	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
106	Purlin Fix Anchor point	Safemaster	L54	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
107	Purlin Fix Anchor point	Safemaster	L54	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
108	Purlin Fix Anchor point	Safemaster	L54	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Purlin Fix Anchor point	Safemaster	L54	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
110	Purlin Fix Anchor point	Safemaster	L47	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
111	Purlin Fix Anchor point	Safemaster	L47	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
112	Purlin Fix Anchor point	Safemaster	L47	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
113	Purlin Fix Anchor point	Safemaster	L47	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
114	Anchor Point-Surface Mount-15kN	Safemaster	L43	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
115	Anchor Point-Surface Mount-15kN	Safemaster	L43	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
116	Anchor Point-Surface Mount-15kN	Safemaster	L43	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
117	Anchor Point-Surface Mount-15kN	Safemaster	L44	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
118	Anchor Point-Surface Mount-15kN	Safemaster	L44	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
119	Purlin Fix Anchor point	Safemaster	L45	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
120	Purlin Fix Anchor point	Safemaster	L45	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Purlin Fix Anchor point	Safemaster	L45	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
122	Purlin Fix Anchor point	Safemaster	L45	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
123	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
124	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
125	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
126	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
127	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
128	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
129	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
130	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
131	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
132	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
134	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
135	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
136	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
137	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
138	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
139	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
140	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
141	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
142	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
143	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
144	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
146	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
147	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
148	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
149	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
150	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
151	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
152	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
153	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
154	Purlin Fix Anchor point	Safemaster	L73 - 78	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
155	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
156	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
158	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
159	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
160	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
161	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
162	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
163	Anchor Point-Purlin Fix-21kN	Safemaster	L90	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
164	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
165	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
166	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
167	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
168	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
170	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
171	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
172	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
173	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
174	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
175	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L91	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
176	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L91	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
177	Purlin Fix Anchor point	Safemaster	L91	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
178	Purlin Fix Anchor point	Safemaster	L91	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
179	Purlin Fix Anchor point	Safemaster	L91	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
180	Purlin Fix Anchor point	Safemaster	L92	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L95	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
182	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L95	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
183	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L95	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
184	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L95	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
185	Anchor Point-Purlin Fix-21kN	Safemaster	L94	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
186	Anchor Point-Purlin Fix-21kN	Safemaster	L94	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
187	Anchor Point-Purlin Fix-21kN	Safemaster	L94	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
188	Anchor Point-Purlin Fix-21kN	Safemaster	L94	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
189	Anchor Point-Purlin Fix-21kN	Safemaster	L96	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
190	Anchor Point-Purlin Fix-21kN	Safemaster	L96	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
191	Anchor Point-Purlin Fix-21kN	Safemaster	L97	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
192	Anchor Point-Purlin Fix-21kN	Safemaster	L97	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Anchor Point-Purlin Fix-21kN	Safemaster	L97	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
194	Anchor Point-Purlin Fix-21kN	Safemaster	L97	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
195	Anchor Point-Purlin Fix-21kN	Safemaster	L97	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
196	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L97	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
197	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L97	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
198	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L97	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
199	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L97	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
200	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
201	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
202	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
203	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
204	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
205	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
206	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
207	Anchor Point-Purlin Fix-21kN	Safemaster	L98	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
208	Anchor Point-Purlin Fix-21kN	Safemaster	L101	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
209	Anchor Point-Purlin Fix-21kN	Safemaster	L101	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
210	Anchor Point-Purlin Fix-21kN	Safemaster	L101	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
211	Anchor Point-Purlin Fix-21kN	Safemaster	L101	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
212	Anchor Point-Purlin Fix-21kN	Safemaster	L101	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor stem is bent
213	Anchor Point-Purlin Fix-21kN	Safemaster	L101	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor stem is bent
214	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
215	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
216	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
218	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
219	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
220	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
221	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
222	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
223	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L104	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
224	Anchor Point-Purlin Fix-21kN	Safemaster	L105	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
225	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L106	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
226	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L106	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
227	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L106	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
228	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L106	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L106	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
230	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L107	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
231	Anchor Point-Purlin Fix-21kN	Safemaster	L108	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
232	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L109	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
233	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor stem is bent
234	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
235	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
236	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
237	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
238	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
239	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
240	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
241	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
242	Anchor Point-Purlin Fix-21kN	Safemaster	L110	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor stem is bent
243	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L110	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
244	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L110	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
245	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L110	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
246	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L110	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
247	Anchor Point-Purlin Fix-21kN	Safemaster	L110 - Awning	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
248	Anchor Point-Purlin Fix-21kN	Safemaster	L110 - Awning	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
249	Anchor Point-Purlin Fix-21kN	Safemaster	L110 - Awning	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
250	Anchor Point-Purlin Fix-21kN	Safemaster	L111	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
251	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L113	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
252	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L113	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
253	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L13	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
254	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L116	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
255	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L116	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
256	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L116	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
257	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L118	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
258	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L118	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
259	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L118	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
260	Anchor Point-Purlin Fix-21kN	Safemaster	L88	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor is bent
261	Anchor Point-Surface Mount-15kN	Safemaster	L88	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
262	Anchor Point-Purlin Fix-21kN	Safemaster	L88	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor is bent
263	Anchor Point-Surface Mount-15kN	Safemaster	L88	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
264	Anchor Point-Purlin Fix-21kN	Safemaster	L88	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Anchor Point-Surface Mount-15kN	Safemaster	L88	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
266	Anchor Point-Purlin Fix-21kN	Safemaster	L88	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
267	Anchor Point-Surface Mount-15kN	Safemaster	L88	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
268	Anchor Point-Purlin Fix-21kN	Safemaster	L88	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
269	Anchor Point-Surface Mount-15kN	Safemaster	L88	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
270	Anchor Point-Surface Mount-15kN	Safemaster	L83	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
271	Access Strop	Safemaster	L83	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
272	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
273	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
274	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
275	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
276	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
277	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
278	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
279	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
280	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
281	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
282	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
283	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L70	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
284	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
285	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
286	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
287	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
288	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
289	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
290	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
291	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
292	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
293	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
294	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
295	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
296	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
297	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
298	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
299	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
300	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
301	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
302	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
303	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
304	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
305	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
306	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
307	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
308	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
309	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
310	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
311	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
312	Anchor Point-Purlin Fix-21kN	Safemaster	L70	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
313	Anchor Point-Purlin Fix-21kN	Safemaster	L71	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
314	Anchor Point-Purlin Fix-21kN	Safemaster	L71	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
315	Anchor Point-Purlin Fix-21kN	Safemaster	L71	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
316	Anchor Point-Purlin Fix-21kN	Safemaster	L71	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
317	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
318	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
319	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
320	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
321	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
322	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
323	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
324	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
325	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
326	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
327	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
328	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
329	Anchor Point-Purlin Fix-21kN	Safemaster	L67	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
330	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
331	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
332	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
333	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
334	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
335	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
336	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
337	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
338	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
339	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
340	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
341	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
342	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
343	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
344	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
345	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
346	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
347	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
348	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
349	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
350	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
351	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
352	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L35 - 40	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
353	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
354	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
355	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
356	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
357	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
358	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
359	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
360	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
361	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
362	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
363	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
364	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
365	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
366	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
367	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
368	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
369	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
370	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
371	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
372	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
373	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
374	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
375	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
376	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
377	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
378	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
379	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
380	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
381	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
382	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
383	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
384	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
385	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
386	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
387	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
388	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
389	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
390	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
391	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
392	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
393	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
394	Anchor Point-Purlin Fix-21kN	Safemaster	L35 - 40	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
395	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
396	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
397	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
398	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
399	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
400	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
401	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
402	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
403	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
404	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
405	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
406	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
407	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
408	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
409	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
410	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
411	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
412	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
413	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
414	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
415	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
416	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
417	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
418	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
419	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
420	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
421	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
422	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
423	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
424	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
425	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L56 - 60 & 63	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
426	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
427	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
428	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
429	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
430	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
431	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
432	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
433	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
434	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
435	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
436	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
437	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	25/09/2019	25/09/2020	AS1891.4:2009	Pass	Two man required
438	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Fail	Anchor stem is bent
439	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
440	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
441	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
442	Anchor Point-Purlin Fix-15kN (LowPro)	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
443	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
444	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
445	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
446	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
447	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
448	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
449	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
450	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
451	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
452	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
453	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
454	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
455	Anchor Point-Purlin Fix-21kN	Safemaster	L56 - 60 & 63	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
456	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
457	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
458	Anchor Point-Surface Mount-15kN	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
459	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
460	Anchor Point-Surface Mount-15kN	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
461	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
462	Anchor Point-Surface Mount-15kN	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
463	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
464	Anchor Point-Surface Mount-15kN	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
465	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
466	Anchor Point-Surface Mount-15kN	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
467	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
468	Anchor Point-Surface Mount-15kN	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
469	Anchor Point-Purlin Fix-21kN	Safemaster	L57	1/04/2014	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
470	Anchor Point-Surface Mount-15kN	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
471	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
472	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
473	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
474	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
475	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
476	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
477	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
478	Anchor Point-Surface Mount-15kN	Safemaster	L120	1/02/2018	25/09/2019	25/09/2020	AS1891.4:2009	Pass	EWP Access required
479	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
480	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
481	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
482	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
483	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
484	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
485	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
486	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
487	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
488	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
489	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
490	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
491	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
492	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
493	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
494	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
495	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
496	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
497	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
498	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
499	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
500	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
501	Anchor Point-Surface Mount-15kN	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
502	Steel Step Ladder	Unknown	L1 - Ground Floor	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	
503	Roof Access Hatch	Unknown	L1	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	
504	Guardrail (Al)	Unknown	L1 - Roof Level	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
505	Access Stair (Galv)	Unknown	L2	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	Not able to make it complaint
506	Access Ladder (Galv)	Unknown	L2	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	
507	Guardrail (Galv)	Unknown	L2	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	
508	Single step (Al)	Unknown	L3	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Pass	
509	Access Stair (Al)	Unknown	L4	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	
510	Access Stair (Galv)	Unknown	L5	Unknown	3/07/2019	3/07/2020	AS/NZS 1657:2018	Fail	
511	Roof Access Hatch	Unknown	L5	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	N/A	Tagged as "Out of Service"
512	Ladder Access Bracket	Unknown	L6	Unknown	3/07/2019	3/07/2020	AS/NZS 1891.4	Pass	
513	Access Strop	Safemaster	L6	1/02/2018	3/07/2019	3/07/2020	AS1891.4:2009	Pass	
514	Guardrail (Al)	Safemaster	L8	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
515	Access Ladder (Al)	Unknown	L11	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
516	Access Ladder (Al)	Unknown	L12	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
517	Access Ladder (Al)	Unknown	L13	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
518	Access Ladder (Steel)	Unknown	L13	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
519	Access Ladder (Al)	Unknown	L15	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
520	Access Ladder (Al)	Unknown	L17	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
521	Guardrail (Al)	Unknown	L20	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
522	Guardrail (Al)	Safemaster	L26		3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
523	Access Stair (Al)	Unknown	L30	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
524	Access Stair (Al)	Unknown	L31	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
525	Access Stair (Al)	Unknown	L32	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
526	Access Stair (Al)	Unknown	L32	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
527	Access Stair (Al)	Unknown	L33	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
528	Access Stair (Al)	Unknown	L33	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
529	Access Ladder (AI)	Unknown	L34	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Top landing not level with rung
530	Sign-Fragile and Brittle Surface	Safemaster	L35	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
531	Sign-Fragile and Brittle Surface	Safemaster	L35	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
532	Sign-Fragile and Brittle Surface	Safemaster	L35	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
533	Access Stair (AI)	Unknown	L36	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
534	Sign-Roof Access	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994 AS/NZS 1891.4:2009	Pass	
535	Ladder Access Bracket	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1891.4:2009	Pass	
536	Access Strop	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1891.4:2009	Pass	
537	Sign-Fragile and Brittle Surface	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
538	Sign-Fragile and Brittle Surface	Safemaster	L37	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
539	Sign-Fragile and Brittle Surface	Safemaster	L38	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
540	Sign-Fragile and Brittle Surface	Safemaster	L38	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
541	Sign-Fragile and Brittle Surface	Safemaster	L40	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
542	Access Stair (AI)	Unknown	L41	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Non-compliant
543	Incline Walkway	Unknown	L41	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
544	Access Stair (AI)	Unknown	L42	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Non-compliant
545	Incline Walkway	Unknown	L42	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
546	Sign-Roof Access	Safemaster	L43	Unknown	3/07/2019	3/07/2020	AS/NZS 1319:1994 AS/NZS 1891.4:2009	Pass	
547	Landing Platform	Unknown	L43	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
548	Ladder Access Bracket	Safemaster	L43	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1891.4:2009	Pass	
549	Access Strop	Safemaster	L43	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1891.4:2009	Pass	
550	Access Ladder (AI)	Unknown	L44	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
551	Walkway	Unknown	L47	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Pitch of cross slope exceeds allowable maximum
552	Vertical Access Ladder (AI) with Static Line	Unknown	L47	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Top landing is too short

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
553	Sign-Roof Access	Safemaster	L48	Unknown	3/07/2019	3/07/2020	AS/NZS 1319:1994 AS/NZS 1891.4:2009	Pass	
554	Ladder Access Bracket	Unknown	L48	Unknown	3/07/2019	3/07/2020	AS/NZS 1891.4	Pass	
555	Access Ladder (Al)	Unknown	L49	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
556	Access Ladder (Al)	Unknown	L50	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
557	Guardrail (Galv)	Unknown	L50	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
558	Sign-Fragile and Brittle Surface	Safemaster	L50	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
559	Sign-Fragile and Brittle Surface	Safemaster	L50	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
560	Sign-Fragile and Brittle Surface	Safemaster	L50	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
561	Sign-Fragile and Brittle Surface	Safemaster	L50	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
562	Access Ladder (Al)	Unknown	L51	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
563	Guardrail (Galv)	Unknown	L51	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
564	Access Ladder (Galv)	Unknown	L53	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
565	Handrail (Galv)	Unknown	L53	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
566	Access Stair (Galv)	Unknown	L53	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
567	Access Ladder (Al)	Unknown	L54	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
568	Access Ladder (Galv)	Unknown	L57	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
569	Incline Walkway (Galv)	Unknown	L57	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Angle too great for walkway - require stairs with change of directions
570	Caged Access Ladder (Al)	Safemaster	L57	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
571	Access Stair (Al)	Unknown	L60	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
572	Landing Platform	Unknown	L61	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail and yellow safety nosings
573	Access Ladder (Al)	Unknown	L62	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
574	Roof Access Hatch	Unknown	L62	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Fits criteria for confined space
575	Access Ladder (Al)	Unknown	L63	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
576	Access Stair (Al)	Unknown	L64 - Lower Level	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
577	Access Stair (Al)	Unknown	L64 - Upper Level	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
578	Access Ladder (Galv)	Unknown	L66	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Ladder is redundant - to be removed
579	Access Stair (Al)	Unknown	L66	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
580	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
581	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
582	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
583	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
584	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
585	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
586	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
587	Sign-Fragile and Brittle Surfsce	Safemaster	L67	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
588	Access Ladder (Al)	Unknown	L68	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
589	Access Ladder (Al)	Unknown	L69	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
590	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
591	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
592	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
593	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
594	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
595	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
596	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
597	Sign-Fragile and Brittle Surfsce	Safemaster	L70	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
598	Step (Steel)	Unknown	L72	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Clear width of walking surface does not meet the required minimum
599	Guardrail (Al)	Unknown	L72	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Guardrail not high enough when using steps
600	Sign-Fragile and Brittle Surfsce	Safemaster	L73	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
601	Sign-Fragile and Brittle Surfsce	Safemaster	L73	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
602	Sign-Fragile and Brittle Surfsce	Safemaster	L73	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
603	Sign-Fragile and Brittle Surfsce	Safemaster	L73	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
604	Sign-EWP Access Only	Safemaster	L76	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
605	Sign-EWP Access Only	Safemaster	L76	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
606	Guardrail (Galv)	Unknown	L80	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires toe boards
607	Access Ladder (Al)	Unknown	L81	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Landings are non-compliant. New ladder required
608	Access Stair (Galv)	Unknown	L82	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
609	Vertical Access Ladder (Al) with Static Line	Unknown	L83	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Landings are non-compliant. D bars require lowering
610	Guardrail (Galv)	Unknown	L84	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Corner pieces are too low
611	Caged Access Ladder (Galv)	Unknown	L85	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Bottom rung spacing is too small
612	Guardrail (Galv)	Unknown	L85	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Non-compliant spacing of rails

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
613	Caged Access Ladder (Galv)	Unknown	L86	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Bottom rung spacing is too small
614	Guardrail (Galv)	Unknown	L86	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Non-compliant spacing of rails
615	Access Ladder (Al)	Unknown	L87	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Multiple non-compliances
616	Guardrail (Galv)	Unknown	L87	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Space between midrail and floor is greater then allow maximum
617	Access Ladder (Al)	Unknown	L88	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Multiple non-compliances
618	Access Stair (Galv)	Unknown	L89	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires guardrail to both sides
619	Sign-Fragile and Brittle Surfsce	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
620	Sign-Fragile and Brittle Surfsce	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
621	Sign-Fragile and Brittle Surfsce	Safemaster	L90	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
622	Access Ladder (Al)	Unknown	L91 - Ground Level	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	To be tagged as "Out of Service"
623	Roof Access Hatch	Unknown	L91	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	To be tagged as "Out of Service"
624	Access Ladder (Al)	Unknown	L92	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Bottom rung spacing too small and top rung not level with landing.

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
625	Access Ladder (AI)	Unknown	L93	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Incorrect angle of ladder and top rung is not level with landing
626	Roof Access Hatch	Unknown	L94	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	To be tagged as "Out of Service"
627	Access Ladder (AI)	Unknown	L96	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Bottom rung spacing too small, top landing too small and not level with rung
628	Access Ladder (AI)	Safemaster	L97	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
629	Access Ladder (AI)	Unknown	L98	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	No top landing installed and bottom rung spacing too small
630	Vertical Ladder (AI) with Static Line	Unknown	L99	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Top landing is too small
631	Guardrail (AI)	Unknown	L99	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Guardrails are too low when user is on ladder landing
632	Mechanical Plant Platform	Unknown	L100	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires step to provide safe access
633	Guardrail (Galv)	Unknown	L100	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
634	Step (AI)	Unknown	L102	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Walking surface out of line and allowed height for a single step exceeded
635	Step (AI)	Unknown	L103	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Walking surface out of line and allowed height for a single step exceeded
636	Access Ladder (AI)	Unknown	L104	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Bottom rung spacings too small, top landing too small and not level with rung

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
637	Roof Access Hatch	Unknown	L105	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	To be signed as "Out of Service"
638	Guardrail (Al)	Unknown	L105	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Requires re-installation and bracing
639	Access Ladder (Galv)	Unknown	L105	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Non-compliant
640	Sign-Fragile and Brittle Surfsce	Safemaster	L106	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
641	Sign-Fragile and Brittle Surfsce	Safemaster	L106	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
642	Sign-Harness Must Be Worn	Safemaster	L107	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
643	Guardrail (Al)	Unknown	L108	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Too low due to walkway thickness
644	Access Ladder (Al)	Unknown	L108	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Non Compliant
645	Sign-Harness Must Be Worn	Safemaster	L109	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
646	Access Ladder (Al)	Unknown	L110	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Bottom rung spacings too small, top landng too small and not level with rung
647	Mechanical Plant Platform	Unknown	L110	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Gap between platform and chillers exceeds allowable maximum
648	Guardrail (Galv)	Unknown	L110	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
649	Roof Access Hatch	Unknown	L110	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	To be signed as "Out of Service"
650	Access Ladder (Galv)	Unknown	L110	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	To be signed as "Out of Service"
651	Access Stair (Galv)	Unknown	L110	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	To be signed as "Out of Service"
652	Step (Al)	Unknown	L111	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Allowed height for a single step exceeded
653	Roof Access Hatch	Unknown	L114	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	Tagged as "Out of Service"
654	Access Ladder (Galv)	Unknown	L115	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
655	Access Ladder (Galv)	Unknown	L116 (Cooling Tower)	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	
656	Parapet Crossover Ladder (Al)	Unknown	L116	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
657	Access Ladder (Al)	Safemaster	L118	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
658	Sign-Fragile and Brittle Surface	Safemaster	L119	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994	Pass	
659	Access Ladder (Al)	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	
660	Access Ladder (Al)	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Galleria

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
661	Sign-Roof Access	Safemaster	L121	1/02/2018	3/07/2019	3/07/2020	AS/NZS 1319:1994 AS/NZS 1891.4:2009	Pass	
662	Ladder Access Bracket	RIS	L122	Unknown	3/07/2019	3/07/2020	AS/NZS 1657-2018	Fail	No safe access to/egress from ladder

AUTHORISED BY: Brandon Vitek

DATE: 03-07-2019

SIGNATURE:

Butch

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au