

PPE INSPECTION LOG RECORD

Client: Gate Aviation

Address: Tarlton Crescent

Attn: Karl Brown

Job Ref: SM13444



98 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

No	Equipment Description	Batch/Model No.	Serial No.	Manufacturer	D.O.M	Out of Service Date	Insp. Date	Next Insp. Date	Pass/Fail	Comments
1	Harness	10034812	155882010	MSA	1/01/2014	1/01/2024	30/04/2018	30/10/2018	Pass	
2	Harness	1100Ergo	133775005	Spanset	1/01/2016	1/01/2026	30/04/2018	30/10/2018	Pass	
3	Harness	1100Ergo	8920330	Spanset	1/04/2016	1/04/2026	30/04/2018	30/10/2018	Pass	
4	Harness	1104Ergo	57890972	Spanset	1/10/2012	1/10/2022	30/04/2018	30/10/2018	Pass	
5	Harness	1104Ergo	59180850	Spanset	1/12/2012	1/12/2022	30/04/2018	30/10/2018	N/A	Not inspected
6	Harness	10034810	141224010	MSA	1/08/2011	1/08/2021	30/04/2018	30/10/2018	Pass	
7	Harness	10034811	154058010	MSA	1/07/2013	1/07/2023	30/04/2018	30/10/2018	Pass	
8	Harness	1100 Ergo	92460361	Spanset	1/09/2016	1/09/2026	30/04/2018	30/10/2018	Pass	
9	Harness	10034812	153870010	MSA	1/07/2013	1/07/2023	30/04/2018	30/10/2018	Pass	
10	Harness	10034812	146543010	MSA	1/05/2012	1/05/2022	30/04/2018	30/10/2018	Pass	
11	Harness	1100 Ergo	92460304	Spanset	1/09/2016	1/09/2026	30/04/2018	30/10/2018	Pass	
12	Harness	10034811	153869010	MSA	1/07/2013	1/07/2023	30/04/2018	30/10/2018	Pass	
13	Harness	1100Ergo	136709006	Spanset	1/04/2016	1/04/2026	30/04/2018	30/10/2018	Pass	
14	Harness	1100 Ergo	93570964	Spanset	1/11/2016	1/11/2026	30/04/2018	30/10/2018	Pass	
15	Harness	1100 Ergo	93400408	Spanset	1/11/2016	1/11/2026	30/04/2018	30/10/2018	Pass	
16	Harness		159267010	MSA	1/07/2013	1/07/2023	30/04/2018	30/10/2018	Pass	
17	Harness		145945010	MSA	1/05/2012	1/05/2022	30/04/2018	30/10/2018		
18	Inertia Reel	3100448	250	Protector	1/01/2016	1/01/2026	30/04/2018	30/10/2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection.

PPE INSPECTION LOG RECORD

Client: Gate Aviation

Address: Tarlton Crescent

Attn: Karl Brown

Job Ref: SM13444



98 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

No	Equipment Description	Batch/Model No.	Serial No.	Manufacturer	D.O.M	Out of Service Date	Insp. Date	Next Insp. Date	Pass/Fail	Comments
19	Inertia Reel	3100448	229	Protector	1/01/2016	1/01/2026	30/04/2018	30/10/2018	Pass	
20	Inertia Reel	1016796	20484025	Miller	1/10/2013	1/10/2023	30/04/2018	30/10/2018	Pass	
21	Inertia Reel	1016796	20545124	Miller	2/02/2014	2/02/2024	30/04/2018	30/10/2018	Pass	
AUTHORISED BY: Trevor Harris				DATE: 30/04/2018						

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection.