

Roof Safety Report

Geographe Primary School

Prepared By: Safemaster Safety Products
Date: 18/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about Geographe Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to BMW Bunbury and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Trevor Harris (Recertification Technician)

Roof Safety Report for
Geographe Primary School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Admin Early Learning Specialist Learning Library Undercover Area Middle Learning Senior Learning	Anchor Points Signage Ladder Bracket

DATE OF INSPECTION

18/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Geographe Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
2	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
3	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
4	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
5	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
6	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
7	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
8	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
9	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
10	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
11	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
12	Low Pro Anchor Point	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Ladder Bracket	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
14	Sign	Safemaster	Admin	1/04/2016	18/04/2018	18/10/2018	AS1319:1994 AS1891.4-2009	Pass	
15	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
16	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
17	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
18	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
19	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
20	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
21	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
22	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
23	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
24	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
26	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
27	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
28	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
29	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
30	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
31	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
32	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
33	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
34	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
35	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
36	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
38	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
39	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
40	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
41	Low Pro Anchor Point	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
42	Ladder Bracket	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
43	Sign	Safemaster	Early Learning	1/04/2016	18/04/2018	18/10/2018	AS1319:1994 AS1891.4-2009	Pass	
44	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
45	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
46	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
47	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
48	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
50	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
51	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
52	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
53	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
54	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
55	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
56	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
57	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
58	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
59	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
60	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
62	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
63	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
64	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
65	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
66	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
67	Low Pro Anchor Point	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Fail	Not properly installed...tagged Out Of Service.
68	Ladder Bracket	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
69	Sign	Safemaster	Specialist Learning	1/04/2016	18/04/2018	18/10/2018	AS1319:1994 AS1891.4-2009	Pass	
70	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
71	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
72	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
74	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
75	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
76	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
77	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
78	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
79	Low Pro Anchor Point	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
80	Ladder Bracket	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
81	Sign	Safemaster	Library	1/04/2016	18/04/2018	18/10/2018	AS1319:1994 AS1891.4-2009	Pass	
82	Low Pro Anchor Point	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
83	Low Pro Anchor Point	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
84	Low Pro Anchor Point	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Low Pro Anchor Point	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
86	Low Pro Anchor Point	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
87	Low Pro Anchor Point	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
88	Ladder Bracket	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
89	Sign	Safemaster	Undercover Area	1/04/2016	18/04/2018	18/10/2018	AS1319:1994 AS1891.4-2009	Pass	
90	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
91	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
92	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
93	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
94	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
95	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
96	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
98	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
99	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
100	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
101	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
102	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
103	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
104	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
105	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
106	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
107	Low Pro Anchor Point	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
108	Ladder Bracket	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Sign	Safemaster	Middle Learning	1/04/2016	18/04/2018	18/10/2018	AS1319:1994 AS1891.4:2009	Pass	
110	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
111	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
112	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
113	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
114	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
115	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
116	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
117	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
118	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
119	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
120	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 7174

Site: Geographe Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
122	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
123	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
124	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
125	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
126	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
127	Low Pro Anchor Point	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
128	Ladder Bracket	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1891.4:2009	Pass	
129	Sign	Safemaster	Senior Learning	1/04/2016	18/04/2018	18/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 18/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au