

Roof Safety Report

Girrawheen Senior High School

Prepared By: Safemaster Safety Products
Date: 27/3/2018

CONFIDENTIALITY/SECURITY

Information obtained from and about Girrawheen SHS in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Girrawheen SHS and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tony Pennington (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Tony Pennington (Recertification Technician)

Roof Safety Report for
Girrawheen Senior High School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Programmed Facility Management	Design & Tech Dance, Canteen & Performance Art Art & Craft Administration Business & Social Science Murdoch Library Technical Trade Home Economics Durack Science Senior School	Anchor Points Signage Ladder Brackets Static Line

DATE OF INSPECTION

27/3/2018

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Girrawheen Senior High School buildings.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
2	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
3	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
4	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
5	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
6	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
7	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
8	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
9	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
10	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
11	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
12	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
14	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
15	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
16	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
17	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
18	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
19	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
20	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
21	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
22	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
23	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
24	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
26	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
27	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
28	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
29	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
30	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
31	Anchor Point-Surfacemount-21kN	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
32	Sign	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
33	Ladder Access Bracket	Safemaster/ Safemaster	Design & Tech	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Fail	Obstruction at access. Remove obstructions or relocate ladder access bracket.
34	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
35	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
36	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
38	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
39	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
40	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
41	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
42	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
43	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
44	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
45	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
46	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
47	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
48	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
50	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
51	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
52	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
53	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
54	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
55	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
56	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
57	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
58	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
59	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
60	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
62	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
63	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
64	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
65	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
66	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
67	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
68	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
69	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
70	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
71	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
72	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Ladder Access Bracket	Safemaster/ Safemaster	Dance, Canteen, Performance Arts	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
74	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
75	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
76	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
77	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
78	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
79	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
80	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
81	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
82	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
83	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
84	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
86	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
87	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
88	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
89	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
90	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
91	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
92	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
93	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
94	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
95	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
96	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
98	Sign	Safemaster/ Safemaster	Art & Craft	27/03/2017	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
99	Ladder Access Bracket	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
100	Ladder Access Bracket	Safemaster/ Safemaster	Art & Craft	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
101	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
102	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
103	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
104	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
105	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
106	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
107	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
108	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
110	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
111	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
112	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
113	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
114	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
115	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
116	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
117	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
118	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
119	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
120	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
122	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
123	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
124	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
125	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
126	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
127	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
128	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
129	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
130	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
131	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
132	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
134	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
135	Ladder Access Bracket	Safemaster/ Safemaster	Admin Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
136	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
137	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
138	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
139	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
140	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
141	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
142	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
143	Ladder Access Bracket	Safemaster/ Safemaster	Business & Social Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	Requires safer way to access the upper level
144	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
146	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
147	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
148	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
149	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
150	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
151	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
152	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
153	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
154	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
155	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
156	Ladder Access Bracket	Safemaster/ Safemaster	Murdoch	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	Potential fall hazard. Relocation recommended.

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
158	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
159	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
160	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
161	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
162	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
163	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
164	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
165	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
166	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
167	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
168	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Library	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
170	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
171	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
172	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
173	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
174	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
175	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
176	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
177	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
178	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
179	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
180	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
182	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
183	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
184	Ladder Access Bracket	Safemaster/ Safemaster	Covered Walkway	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
185	Sign	Safemaster/ Safemaster	Covered Walkway	27/03/2017	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
186	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
187	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
188	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
189	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
190	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
191	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
192	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
194	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
195	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
196	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
197	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
198	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
199	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
200	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
201	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
202	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
203	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
204	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
205	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
206	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
207	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
208	Static Line-Surfacemount-21kN	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
209	Sign	Safemaster/ Safemaster	Technical Trade	27/03/2018	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
210	Ladder Access Bracket	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
211	Sign	Safemaster/ Safemaster	Technical Trade	27/03/2018	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
212	Ladder Access Bracket	Safemaster/ Safemaster	Technical Trade	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
213	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
214	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
215	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
216	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
218	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
219	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
220	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
221	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
222	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
223	Sign	Safemaster/ Safemaster	Home Economics	27/03/2017	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
224	Ladder Access Bracket	Safemaster/ Safemaster	Home Economics	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
225	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
226	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
227	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
228	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
230	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
231	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
232	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
233	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
234	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
235	Sign	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
236	Ladder Access Bracket	Safemaster/ Safemaster	Durack	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
237	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
238	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
239	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
240	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
241	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
242	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
243	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
244	Sign	Safemaster/ Safemaster	Science	27/03/2017	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
245	Ladder Access Bracket	Safemaster/ Safemaster	Science	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
246	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
247	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
248	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
249	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
250	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
251	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
252	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
253	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
254	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
255	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
256	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
257	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
258	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
259	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
260	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
261	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
262	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
263	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
264	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Girrawheen Senior High School - 39 Calvert Way, Girrawheen

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
266	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
267	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
268	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
269	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
270	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
271	Anchor Point-Purlin Fix-21kN	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	
272	Sign	Safemaster/ Safemaster	Senior School Block	27/03/2018	27/03/2018	27/09/2018	AS1319:1994 AS1891.4-2009	Pass	
273	Ladder Access Bracket	Safemaster/ Safemaster	Senior School Block	1/07/2012	27/03/2018	27/09/2018	AS1891.4:2009	Pass	

AUTHORISED BY: Tony Pennington

DATE: 27/3/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

COMPLIANT REQUIREMENTS

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au