

# Roof Safety Report

Glen Huon Primary School

Prepared By: Safemaster Safety Products  
Date: 19/04/18

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Glen Huon Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Glen Huon Primary School and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Trevor Harris (Recertification Technician)**

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Teaching Block 1 Teaching Block 2 Admin/Dental Pre-Primary Kindy Music/Art Library Covered Assembly	Anchor Points Signage Ladder Bracket Stanchion Post

#### DATE OF INSPECTION

19/04/18

#### INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Glen Huon Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
13	Purlin Fix Anchor Point	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
14	Ladder Bracket	RSS	Kindy	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
15	Sign	RSS	Kindy	1/10/2014	19/04/2018	19/10/2018	AS1319:1994 AS1891.4-2009	Pass	
16	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
23	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
25	Ladder Bracket	RSS	Music/Art	1/05/2010	19/04/2018	19/10/2018	AS1891.4:2009	Pass	
26	Sign	RSS	Music/Art	1/10/2014	19/04/2018	19/10/2018	AS1319:1994 AS1891.4-2009	Pass	
27	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
28	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
29	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
30	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
31	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
32	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
33	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
34	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
35	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
36	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
37	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
38	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
39	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
40	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
41	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
42	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7158

**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
43	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
44	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
45	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
46	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
47	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
48	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
49	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
50	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
51	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
52	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
53	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
54	Stanchion Post	Unknown	Teaching Block 1	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
55	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
56	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7158

**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
57	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
58	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
59	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
60	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
61	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
62	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
63	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
64	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
65	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
66	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
67	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
68	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
69	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
70	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
71	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
72	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
73	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
74	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
75	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
76	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
77	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
78	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
79	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
80	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
81	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
82	Stanchion Post	Unknown	Teaching Block 2	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
83	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
84	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury

**Job Ref:** SM 7158

**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
86	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
87	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
88	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
89	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
90	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
91	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
92	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
93	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
94	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
95	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
96	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
97	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
98	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
99	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
100	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
101	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
102	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
103	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
104	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
105	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
106	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
107	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
108	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
109	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
110	Stanchion Post	Unknown	Pre-Primary	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
111	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
112	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
113	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
114	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
115	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
116	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
117	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
118	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
119	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
120	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
121	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
122	Stanchion Post	Unknown	Admin/Dental	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
123	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
124	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
125	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
126	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
127	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
128	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
129	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
130	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
131	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
132	Stanchion Post	Unknown	Library	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7158  
**Site:** Glen Huon Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
134	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
135	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
136	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
137	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
138	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
139	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
140	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
141	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system
142	Stanchion Post	Unknown	Covered Assembly	Unknown	19/04/2018	19/10/2018	AS1891.4:2009	Fail	Uncertifiable to be replaced with certifiable system

AUTHORISED BY: Trevor Harris

DATE: 19/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)