

Roof Safety Report

Karratha City, WA 6714

Prepared By: Safemaster Safety Products
Date: 25-06-2020

CONFIDENTIALITY/SECURITY

Information obtained from and about Karratha City in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Karratha City and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tyron Menikides (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Tyron Menikides (Height Safety Inspector)

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres - Karratha City Shopping Centre	Karratha City Shopping Centre	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

25-06-2020

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Karratha City buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
2	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
3	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
4	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
5	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
6	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
7	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
8	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
9	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
10	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
11	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
12	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
13	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
14	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
15	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
16	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
17	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
18	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
19	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
20	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
21	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
22	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
23	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
24	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
25	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
26	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
27	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
28	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
29	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
30	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
31	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
32	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
33	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
34	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
35	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
36	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
38	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
39	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
40	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
41	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
42	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
43	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
44	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
45	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
46	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
47	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
48	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
49	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
50	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
51	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
52	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
53	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
54	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
55	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
56	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
57	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
58	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
59	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
60	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
61	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
62	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
63	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
64	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
65	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
66	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
67	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
68	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
69	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
70	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
71	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
72	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
74	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
75	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
76	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
77	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
78	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
79	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
80	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
81	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
82	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
83	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
84	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
85	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
86	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
87	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
88	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
89	Access Ladder (Al)	Unknown	L1 - Ground Floor	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
90	Roof Access Hatch-1	Unknown	L1 - Roof Level	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
91	Handrail	SAFEMASTER WA	L1	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
92	Roof Walkway	Unknown	Roof	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
93	Handrail (AI)	SAFEMASTER WA	L3	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
94	Access Stair/Step(AI)	SAFEMASTER WA	L4	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
95	Access Ladder - 1 (AI)	Unknown	L6	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
96	Access Ladder - 2 (AI)	SAFEMASTER WA	L7	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
97	Step (AI)	SAFEMASTER WA	L8	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
98	Galvanized Guardrail	Unknown	L8	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
99	Handrail (AI)	SAFEMASTER WA	L8	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
100	Handrail (AI)	SAFEMASTER WA	L9	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
101	Step (AI)	SAFEMASTER WA	L9	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
102	Galvanized Guardrail	Unknown	L9	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
103	Step (AI)	SAFEMASTER WA	L10	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
104	Steps	SAFEMASTER WA	L11	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
105	Access Ladder - 6 (AI)	Unknown	L12	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
106	Roof Access Hatch-2	Unknown	L12	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
107	Handrail	SAFEMASTER WA	L12	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
108	Access Ladder (AI)	SAFEMASTER WA	L13	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Surfacemount Anchor	SAFEMASTER WA	L14	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
110	Surfacemount Anchor	SAFEMASTER WA	L14	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
111	Surfacemount Anchor	SAFEMASTER WA	L14	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
112	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
113	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
114	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
115	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
116	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
117	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
118	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
119	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
120	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
121	Surfacemount Anchor	SAFEMASTER WA	L18	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
122	Surfacemount Anchor	SAFEMASTER WA	L19	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
123	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
124	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
125	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
126	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
127	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
128	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
129	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
130	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
131	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
132	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
133	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
134	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
135	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
136	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
137	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
138	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
139	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
140	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
141	Surfacemount Anchor	SAFEMASTER WA	L22	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
142	Surfacemount Anchor	SAFEMASTER WA	L22	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
143	Surfacemount Anchor	SAFEMASTER WA	L22	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
144	Step (AI)	SAFEMASTER WA	L24	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Step Bridge (Al)	Unknown	L25	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
146	Surfacemount Anchor	SAFEMASTER WA	L26	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
147	Surfacemount Anchor	SAFEMASTER WA	L26	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
148	Ladder Access Bracket	SAFEMASTER WA	L26	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
149	Step Bridge (Al)	Unknown	L27	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
150	Ladder Access Bracket	Unknown	L28	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
151	Surfacemount Anchor	SAFEMASTER WA	L28	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
152	Surfacemount Anchor	SAFEMASTER WA	L28	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
153	Sign	SAFEMASTER WA	L28	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1319-1994	PASS	
154	Access Ladder - 7 (Galv)	Unknown	L29	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
155	Surfacemount Anchor	SAFEMASTER WA	L30	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
156	Surfacemount Anchor	SAFEMASTER WA	L30	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
157	Ladder Access Bracket	SAFEMASTER WA	L30	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
158	Surfacemount Anchor	SAFEMASTER WA	L31	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
159	Surfacemount Anchor	SAFEMASTER WA	L31	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
160	Ladder Access Bracket	SAFEMASTER WA	L31	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
161	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
162	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
163	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
164	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
165	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
166	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
167	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
168	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
169	Ladder Access Bracket	SAFEMASTER WA	L32	15/02/2017	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
170	Access Ladder - 8 (Al)	SAFEMASTER WA	L33	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
171	Access Ladder - 9 (Galv)	Unknown	L34	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	FAIL	Out of Service sign installed
172	Access Ladder - 10 (Galv)	Unknown	L34	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	FAIL	Out of Service sign installed
173	Roof Access Hatch-3	Unknown	L34	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	FAIL	Out of Service sign installed
174	Access Ladder - 11 (Al)	Unknown	L35	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
175	Aluminium Guardrail	SAFEMASTER WA	L34 & L35	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
176	Access Ladder - 12 (Al)	Unknown	L36	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
177	Access Ladder - 13 (Al)	Unknown	L37	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
178	Step Bridge (Al)	SAFEMASTER WA	L38	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
179	Access Ladder - 14 (Galv)	Unknown	L39	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
180	Step Bridge (Al)	Unknown	L40	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Access Ladder - 15 (Al)	SAFEMASTER WA	L41	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
182	Handrail	SAFEMASTER WA	L41	30/04/2014	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
183	Surfacemount Anchor	SAFEMASTER WA	L42	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
184	Surfacemount Anchor	SAFEMASTER WA	L42	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
185	Ladder Access Bracket	SAFEMASTER WA	L42	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
186	Surfacemount Anchor	SAFEMASTER WA	L43	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
187	Surfacemount Anchor	SAFEMASTER WA	L43	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
188	Surfacemount Anchor	SAFEMASTER WA	L43	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
189	Surfacemount Anchor	SAFEMASTER WA	L43	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
190	Surfacemount Anchor	SAFEMASTER WA	L43	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
191	Surfacemount Anchor	SAFEMASTER WA	L43	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
192	Ladder Access Bracket	SAFEMASTER WA	L43	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
193	Surfacemount Anchor	SAFEMASTER WA	L44	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
194	Surfacemount Anchor	SAFEMASTER WA	L44	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
195	Ladder Access Bracket	SAFEMASTER WA	L44	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
196	Surfacemount Anchor	SAFEMASTER WA	L45	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
197	Surfacemount Anchor	SAFEMASTER WA	L45	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
198	Ladder Access Bracket	SAFEMASTER WA	L45	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
199	Surfacemount Anchor	SAFEMASTER WA	L46	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
200	Surfacemount Anchor	SAFEMASTER WA	L46	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
201	Surfacemount Anchor	SAFEMASTER WA	L46	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
202	Ladder Access Bracket	SAFEMASTER WA	L46	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
203	Access Ladder - 16 (Al)	SAFEMASTER WA	L49	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
204	Step Bridge (Al)	SAFEMASTER WA	L50	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
205	Access Ladder - 17 (Al)	Unknown	L51	Unknown	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
206	Access Ladder - 18 (Al)	SAFEMASTER WA	L52	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
207	Surfacemount Anchor	SAFEMASTER WA	L52	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
208	Access Ladder - 19 (Al)	SAFEMASTER WA	L54	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
209	Aluminium Guardrail	SAFEMASTER WA	L54	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
210	Access Ladder - 19 (Al)	SAFEMASTER WA	L55	18/09/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
211	Access Ladder (Al)	SAFEMASTER WA	L57	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
212	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
213	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
214	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
215	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
216	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
217	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
218	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
219	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
220	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
221	Strop line	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
222	Sign	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1319-1994	PASS	
223	Ladder Access Bracket	SAFEMASTER WA	L58	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
224	Surfacemount Anchor	SAFEMASTER WA	L59	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
225	Surfacemount Anchor	SAFEMASTER WA	L59	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
226	Strop line	SAFEMASTER WA	L59	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
227	Sign	SAFEMASTER WA	L59	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1319-1994	PASS	
228	Ladder Access Bracket	SAFEMASTER WA	L59	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
229	Surfacemount Anchor	SAFEMASTER WA	L60	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
230	Surfacemount Anchor	SAFEMASTER WA	L60	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
231	Strop line	SAFEMASTER WA	L60	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
232	Sign	SAFEMASTER WA	L60	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1319-1994	PASS	
233	Ladder Access Bracket	SAFEMASTER WA	L60	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
234	Access Ladder (Al)	SAFEMASTER WA	L60	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
235	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
236	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
237	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
238	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
239	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
240	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
241	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
242	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
243	Access Ladder - 22 (AI)	Unknown	L61 - Ground Floor	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
244	Access Ladder - 23 (AI)	Unknown	L61 - Mid Level	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
245	Ladder Access Bracket	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1657-2013	PASS	
246	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
247	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
248	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
249	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
250	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
251	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
252	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
253	Strop line	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1891.4-2009	PASS	
254	Sign	SAFEMASTER WA	L62	15/02/2018	25/06/2020	25/06/2021	AS/NZS 1319-1994	PASS	

AUTHORISED BY: Tyron Menikides

DATE: 25-06-2020

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au