

Roof Safety Report

Karratha City, WA 6714

Prepared By: Safemaster Safety Products
Date: 11 July 2018

CONFIDENTIALITY/SECURITY

Information obtained from and about Karratha City in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Karratha City and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tony Pennington (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Tony Pennington (Height Safety Inspector)

Roof Safety Report for
Karratha City, WA 6714

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Karratha City Shopping Centre	Welcome Road, Karratha WA 6714	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

29/06/2018

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Karratha City buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
2	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
3	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
4	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
5	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
6	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
7	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
8	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
9	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
10	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
11	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
12	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
13	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
14	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
15	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
16	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
17	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
18	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
19	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
20	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
21	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
22	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
23	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
24	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
25	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
26	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
27	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
28	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
29	Surfacemount Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
30	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
31	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
32	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
33	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
34	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
35	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
36	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
37	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
38	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
39	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
40	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
41	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
42	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
43	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
44	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
45	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
46	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
47	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
48	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
49	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
50	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
51	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
52	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
53	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
54	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
55	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
56	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
57	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
58	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
59	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
60	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
61	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
62	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
63	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
64	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
65	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
66	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
67	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
68	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
69	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
70	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
71	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
72	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
73	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
74	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
75	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
76	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
77	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
78	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
79	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
80	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
81	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
82	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
83	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
84	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
85	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
86	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
87	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
88	Purlin Fix Anchor	SAFEMASTER WA	Main Roof	30/04/2014	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
89	Access Ladder (Al)	Unknown	L1 - Ground Floor	Unknown	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
90	Roof Access Hatch-1	Unknown	L1 - Roof Level	Unknown	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
91	Roof Walkway	Unknown	Roof	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
92	Access Stair/Step(Al)	Unknown	L4	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
93	Access Ladder - 1 (Al)	Unknown	L6	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
94	Access Ladder - 2 (Al)	Unknown	L7	Unknown	27/06/2017	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
95	Access Ladder - 3 (Galv)	Unknown	L8	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
96	Galvanized Guardrail	Unknown	L8	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
97	Access Ladder - 4 (Galv)	Unknown	L9	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
98	Galvanized Guardrail	Unknown	L9	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
99	Access Ladder - 5 (Galv)	Unknown	L10	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
100	Access Ladder - 6 (Al)	Unknown	L12	Unknown	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
101	Roof Access Hatch-2	Unknown	L12	Unknown	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
102	Access Stair/Step(Al)	Unknown	L13	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
103	Step Bridge (Al)	Unknown	L25	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
104	Step Bridge (Al)	Unknown	L27	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
105	Ladder Access Bracket	Unknown	L28	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
106	Access Ladder - 7 (Galv)	Unknown	L29	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
107	Access Ladder - 8 (Al)	Unknown	L33	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
108	Access Ladder - 9 (Galv)	Unknown	L34	Unknown	27/06/2017	N/A	AS/NZS 1657-2013	FAIL	Out of Service sign installed
109	Access Ladder - 10 (Galv)	Unknown	L34	Unknown	27/06/2017	N/A	AS/NZS 1657-2013	FAIL	Out of Service sign installed
110	Roof Access Hatch-3	Unknown	L34	Unknown	27/06/2017	N/A	AS/NZS 1657-2013	FAIL	Out of Service sign installed
111	Access Ladder - 11 (Al)	Unknown	L35	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
112	Aluminium Guardrail	Unknown	L34 & L35	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
113	Access Ladder - 12 (Al)	Unknown	L36	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
114	Access Ladder - 13 (Al)	Unknown	L37	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
115	Step Bridge (Al)	Unknown	L38	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
116	Access Ladder - 14 (Galv)	Unknown	L39	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
117	Step Bridge (Al)	Unknown	L40	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
118	Access Ladder - 15 (Al)	Unknown	L41	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
119	Access Ladder - 16 (Al)	Unknown	L49	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
120	Step Bridge (Al)	Unknown	L50	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
121	Access Ladder - 17 (Al)	Unknown	L51	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
122	Access Ladder - 18 (Al)	Unknown	L52	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
123	Access Ladder - 19 (Al)	Unknown	L54	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
124	Aluminium Guardrail	Unknown	L54	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
125	Access Ladder - 19 (Al)	Unknown	L55	Unknown	5/05/2016	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
126	Access Ladder - 22 (Al)	Unknown	L61 - Ground Floor	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
127	Access Ladder - 23 (Al)	Unknown	L61 - Mid Level	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
128	Handrail	Unknown	L3	30/04/2014	29/06/2018	N/A	AS/NZS 1657-2013	FAIL	Non-Compliant
129	Steps	SAFEMASTER WA	L11	30/04/2014	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
130	Handrail	SAFEMASTER WA	L41	30/04/2014	5/05/2016	N/A	AS/NZS 1657-2013	PASS	
131	Surfacemount Anchor	SAFEMASTER WA	L14	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
132	Surfacemount Anchor	SAFEMASTER WA	L14	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
133	Surfacemount Anchor	SAFEMASTER WA	L14	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
134	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
135	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
136	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
137	Surfacemount Anchor	SAFEMASTER WA	L16	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
138	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
139	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
140	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
141	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
142	Surfacemount Anchor	SAFEMASTER WA	L17	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
143	Surfacemount Anchor	SAFEMASTER WA	L18	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
144	Surfacemount Anchor	SAFEMASTER WA	L19	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
145	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
146	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
147	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
148	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
149	Surfacemount Anchor	SAFEMASTER WA	L20	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
150	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
151	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
152	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
153	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
154	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
155	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
156	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
157	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
158	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
159	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
160	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
161	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
162	Surfacemount Anchor	SAFEMASTER WA	L21	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
163	Surfacemount Anchor	SAFEMASTER WA	L22	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
164	Surfacemount Anchor	SAFEMASTER WA	L22	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
165	Surfacemount Anchor	SAFEMASTER WA	L22	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
166	Surfacemount Anchor	SAFEMASTER WA	L26	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
167	Surfacemount Anchor	SAFEMASTER WA	L26	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
168	Surfacemount Anchor	SAFEMASTER WA	L28	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
169	Surfacemount Anchor	SAFEMASTER WA	L28	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
170	Surfacemount Anchor	SAFEMASTER WA	L30	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
171	Surfacemount Anchor	SAFEMASTER WA	L30	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
172	Surfacemount Anchor	SAFEMASTER WA	L31	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
173	Surfacemount Anchor	SAFEMASTER WA	L31	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
174	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
175	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
176	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
177	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
178	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
179	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
180	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
181	Surfacemount Anchor	SAFEMASTER WA	L32	15/02/2017	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
182	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
183	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
184	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
185	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
186	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
187	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
188	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
189	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
190	Surfacemount Anchor	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
191	Strop line	SAFEMASTER WA	L58	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
192	Surfacemount Anchor	SAFEMASTER WA	L59	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
193	Surfacemount Anchor	SAFEMASTER WA	L59	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
194	Strop line	SAFEMASTER WA	L59	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
195	Surfacemount Anchor	SAFEMASTER WA	L60	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
196	Surfacemount Anchor	SAFEMASTER WA	L60	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
197	Strop line	SAFEMASTER WA	L60	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
198	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
199	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
200	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
201	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
202	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
203	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
204	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
205	Surfacemount Anchor	SAFEMASTER WA	L61	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
206	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
207	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
208	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
209	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
210	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
211	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
212	Surfacemount Anchor	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
213	Strop line	SAFEMASTER WA	L62	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
214	Surfacemount Anchor	SAFEMASTER WA	L52	15/02/2018	29/06/2018	29/06/2019	AS/NZS 1891.4-2009	PASS	
215	Sign	SAFEMASTER WA	L28	15/02/2017	29/06/2018	N/A	AS/NZS 1319-1994	PASS	
216	Sign	SAFEMASTER WA	L58	15/02/2018	29/06/2018	N/A	AS/NZS 1319-1994	PASS	
217	Sign	SAFEMASTER WA	L59	15/02/2018	29/06/2018	N/A	AS/NZS 1319-1994	PASS	
218	Sign	SAFEMASTER WA	L60	15/02/2018	29/06/2018	N/A	AS/NZS 1319-1994	PASS	
219	Sign	SAFEMASTER WA	L62	15/02/2018	29/06/2018	N/A	AS/NZS 1319-1994	PASS	
220	Ladder Access Bracket	SAFEMASTER WA	L26	15/02/2017	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
221	Ladder Access Bracket	SAFEMASTER WA	L30	15/02/2017	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
222	Ladder Access Bracket	SAFEMASTER WA	L31	15/02/2017	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
223	Ladder Access Bracket	SAFEMASTER WA	L32	15/02/2017	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
224	Ladder Access Bracket	SAFEMASTER WA	L58	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
225	Ladder Access Bracket	SAFEMASTER WA	L59	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
226	Ladder Access Bracket	SAFEMASTER WA	L60	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
227	Ladder Access Bracket	SAFEMASTER WA	L62	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
228	Access Ladder (Al)	SAFEMASTER WA	L60	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

INSPECTION LOG RECORD- INSTALLED SYSTEMS

KARRATHA CITY

Client: Vicinity Centres

Address: 28/35 Colins St, Melbourne VIC 3000

Job Ref: SM12182-KarrathaCity

Site: Karratha City

Address: Welcome Road, Karratha, WA 6714

98 Catalano Circuit, Canning Vale 6155
ALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

No	Equipment Type& Description	Manufacturer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
229	Handrail	SAFEMASTER WA	L1	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
230	Handrail	SAFEMASTER WA	L12	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
231	Access Ladder (Al)	SAFEMASTER WA	L57	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	
232	Step (Al)	SAFEMASTER WA	L24	15/02/2018	29/06/2018	N/A	AS/NZS 1657-2013	PASS	

AUTHORISED BY: TONT PENNINGTON

DATE:29-06-2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

COMPLIANT REQUIREMENTS

There are no recommendations at this point in time.

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au