

Roof Safety Report

Kingston Primary School

Prepared By: Safemaster Safety Products
Date: 20/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about Kingston Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Kingston Primary School and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Trevor Harris (Recertification Technician)

Roof Safety Report for
Kingston Primary School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Client Name Here	Admin Learning Area 1 Learning Area 2 Learning Area 3 Learning Area 4 Library Covered Assembly Early Learning Year 6 Pre Primary	Anchor Points Signage Ladder Bracket

DATE OF INSPECTION

20/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Kingston Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
9	Ladder Bracket	Safemaster	Admin	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
10	Sign	Safemaster	Admin	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
11	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
12	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
23	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Ladder Bracket	Safemaster	Teaching Block 1	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
26	Sign	Safemaster	Teaching Block 1	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
27	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
34	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
39	Ladder Bracket	Safemaster	Teaching Block 2	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
40	Sign	Safemaster	Teaching Block 2	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
41	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
45	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
46	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
47	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
48	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
51	Purlin Fix Anchor Point	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
52	Ladder Bracket	Safemaster	Teaching Block 3	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
53	Sign	Safemaster	Teaching Block 3	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
54	Purlin Fix Anchor Point	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
56	Purlin Fix Anchor Point	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
57	Purlin Fix Anchor Point	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
58	Purlin Fix Anchor Point	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
59	Purlin Fix Anchor Point	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
60	Purlin Fix Anchor Point	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Ladder Bracket	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
62	Ladder Bracket	Safemaster	Teaching Block 4	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
63	Sign	Safemaster	Teaching Block 4	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
64	Sign	Safemaster	Teaching Block 4	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
65	Purlin Fix Anchor Point	Safemaster	Library	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
66	Purlin Fix Anchor Point	Safemaster	Library	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
67	Purlin Fix Anchor Point	Safemaster	Library	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
68	Purlin Fix Anchor Point	Safemaster	Library	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
69	Purlin Fix Anchor Point	Safemaster	Library	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
70	Ladder Bracket	Safemaster	Library	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
71	Sign	Safemaster	Library	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
72	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
74	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
75	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
76	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
77	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
78	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
79	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
80	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
81	Purlin Fix Anchor Point	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
82	Ladder Bracket	Safemaster	Covered Assembly	1/08/2009	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
83	Sign	Safemaster	Covered Assembly	1/11/2014	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
84	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
86	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
87	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
88	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
89	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
90	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
91	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
92	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
93	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
94	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
95	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
96	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Surfacemount Anchor Point	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
98	Ladder Bracket	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
99	Sign	RSS	Early Learning	1/07/2011	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
100	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
101	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
102	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
103	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
104	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
105	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
106	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
107	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
108	Purlin Fix Anchor Point	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Ladder Bracket	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
110	Sign	RSS	Year 6	1/07/2010	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	
111	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
112	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
113	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
114	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
115	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
116	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
117	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
118	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
119	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
120	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 7160

Site: Kingston Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Purlin Fix Anchor Point	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
122	Ladder Bracket	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1891.4:2009	Pass	
123	Sign	RSS	Pre Primary	1/07/2010	20/04/2018	20/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 20/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Compliance Requirements

There are no recommendations at this point in time.

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au