

Roof Safety Report

**Lidcombe Shopping Centre,
NSW 2141**

Prepared By: Safemaster Safety Products
Date: 10 Dec 2018

CONFIDENTIALITY/SECURITY

Information obtained from and about Lidcombe Shopping Centre in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Lidcombe Shopping Centre and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
31-33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



James Townsend (Recertification Technician)

Roof Safety Report for
Lidcombe Shopping Centre, NSW 2141

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Lidcombe Shopping Centre, NSW 2141	Lidcombe Shopping Centre	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

09/10/2018

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Lidcombe Shopping Centre buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
2	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
3	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
4	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
5	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
6	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
7	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
8	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
9	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
10	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
11	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
13	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
14	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
15	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
16	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
17	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
18	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
19	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
20	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
21	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
22	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
24	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
25	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
26	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
27	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
28	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
29	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
30	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
31	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
32	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
33	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
37	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
46	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
47	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
48	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
49	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
51	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
52	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
53	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
54	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
57	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
58	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
59	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
60	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
61	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
62	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
63	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
64	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
65	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
66	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
68	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
69	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
70	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
71	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
72	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
73	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
74	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
75	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
76	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
77	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
79	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
80	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
81	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
82	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
83	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
84	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
85	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
86	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
87	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
88	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
90	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
91	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
92	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
93	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
94	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
95	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
96	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
97	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
98	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
99	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Purlin Fix Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
101	Surfcemount Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
102	Surfcemount Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
103	Surfcemount Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
104	Surfcemount Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
105	Surfcemount Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
106	Surfcemount Anchor Point	Roof Safe	Main Roof	1/07/2006	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
107	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
108	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
109	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
110	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
112	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
113	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
114	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
115	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
116	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
117	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
118	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
119	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
120	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
121	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
123	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
124	Abseil Anchor Point	Proactive	Main Roof	1/02/2015	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
125	Surfcemount Anchor Point	ASG	Main Roof	Unknown	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
126	Surfcemount Anchor Point	ASG	Main Roof	Unknown	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
127	Surfcemount Anchor Point	ASG	Main Roof	Unknown	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
128	Surfcemount Anchor Point	ASG	Main Roof	Unknown	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
129	Surfcemount Anchor Point	ASG	Main Roof	Unknown	9/10/2018	9/10/2019	AS1891.4:2009	Fail	Loose eyebolt
130	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
131	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
132	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
134	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
135	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
136	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
137	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
138	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
139	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
140	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
141	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
142	Low Pro Anchor Point	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
143	Handrail	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Walkway	Safemaster	Main Roof	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
145	Walkway	Unknown	Main Roof	Unknown	9/10/2018	9/10/2019	AS1657:2013	Pass	
146	900mm Access Ladder	Safemaster	L2	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
147	900mm Access Ladder	Safemaster	L3	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
148	2 metre Access Ladder	Safemaster	L7	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
149	600mm Access Ladder	Safemaster	L7	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
150	700mm Access Ladder	Safemaster	L10	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
151	Low Head Room Signage	Safemaster	L10	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
152	800mm Access Ladder	Safemaster	L12	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
153	800mm Access Ladder	Safemaster	L18	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
154	800mm Access Ladder	Safemaster	L19	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	EWP Access Only Signage	Safemaster	L26	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
156	1.2 metre Access Ladder	Safemaster	L27	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
157	Fragile Roof Signage	Safemaster	L28	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
158	Fragile Roof Signage	Safemaster	L28	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
159	EWP Access Only Signage	Safemaster	L38	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
160	Fragile Roof Signage	Safemaster	L41	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
161	Fragile Roof Signage	Safemaster	L41	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
162	Fragile Roof Signage	Safemaster	L41	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
163	Fragile Roof Signage	Safemaster	L41	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
164	Fragile Roof Signage	Safemaster	L41	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
165	Fragile Roof Signage	Safemaster	L41	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Low Pro Anchor Point	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
167	Low Pro Anchor Point	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
168	Low Pro Anchor Point	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
169	Low Pro Anchor Point	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
170	Low Pro Anchor Point	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
171	Low Pro Anchor Point	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
172	Low Pro Anchor Point	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
173	Access Hatch	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019		Pass	
174	Ceiling Ladder	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
175	Fold Down Ladder	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1657:2013	Pass	
176	Access Sign	Safemaster	L42	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
177	Fragile Roof Signage	Safemaster	L47	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
178	Fragile Roof Signage	Safemaster	L47	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
179	Fragile Roof Signage	Safemaster	L47	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
180	Fragile Roof Signage	Safemaster	L47	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
181	Fragile Roof Signage	Safemaster	L60	42917	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
182	Fragile Roof Signage	Safemaster	L60	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
183	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
184	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
185	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
186	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
187	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
188	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
189	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
190	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
191	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
192	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
193	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
194	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
195	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
196	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
197	Low Pro Anchor Point	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
198	Surfacemount Anchor Point	Unknown	L72	Unknown	9/10/2018	9/10/2019	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres


Job Ref: SM12182

Site: Lidcombe Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
199	Ladder Bracket	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1891.4:2009	Pass	
200	Access Sign	Safemaster	L72	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
201	EWP Access Only Signage	Safemaster	L97	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
202	EWP Access Only Signage	Safemaster	L98	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
203	EWP Access Only Signage	Safemaster	L99	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
204	EWP Access Only Signage	Safemaster	L100	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
205	EWP Access Only Signage	Safemaster	L103	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
206	EWP Access Only Signage	Safemaster	L104	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	
207	EWP Access Only Signage	Safemaster	L111	1/07/2017	9/10/2018	9/10/2019	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 09/10/2018



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au