

Roof Safety Report

**Livingston Market Place,
WA 6155**

Prepared By: Safemaster Safety Products
Date: 06-08-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Livingston Market Place in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Livingston Market Place and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Brandon Vitek (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Brandon Vitek (Recertification Technician)

Roof Safety Report for
Livingston Market Place, WA 6155

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres - Livingston Market Place	Livingston Market Place	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

21-06-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Livingston Market Place buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Single step	Safemaster / Safemaster	L1	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
2	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L2	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
3	Step Bridge	Safemaster / Safemaster	L23	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
4	Single step	Safemaster / Safemaster	L28	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
5	Single step	Safemaster / Safemaster	L33	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
6	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L36	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
7	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L36	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
8	Access Ladder (Al)	Safemaster / Safemaster	L36	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
9	Access Ladder (Al)	Safemaster / Safemaster	L36	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
10	Access Ladder (Al)	Safemaster / Safemaster	L36	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
11	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L37	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L37	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
13	Access Ladder (Al)	Safemaster / Safemaster	L37	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
14	Access Ladder (Al)	Safemaster / Safemaster	L37	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
15	Access Ladder (Al)	Safemaster / Safemaster	L37	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
16	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L38	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
17	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L38	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
18	Access Ladder (Al)	Safemaster / Safemaster	L38	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
19	Access Ladder (Al)	Safemaster / Safemaster	L38	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
20	Access Ladder (Al)	Safemaster / Safemaster	L38	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
21	Horizontal static line	Safemaster / Safemaster	L42	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
22	Surfacemount anchor point	Safemaster / Safemaster	L42	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Double step	Safemaster / Safemaster	L44	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
24	Step Bridge	Safemaster / Safemaster	L45	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
25	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L49	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
26	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L49	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
27	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L49	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
28	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L49	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
29	Access Ladder (AI)	Safemaster / Safemaster	L49	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
30	Grabrail set (AI)	Safemaster / Safemaster	L50	14/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
31	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
32	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
33	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
35	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
36	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
37	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
38	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
39	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
40	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
41	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
42	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
43	Surfacemount anchor point	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
44	Ladder access bracket	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Sign	Safemaster / Safemaster	L51	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
46	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L53	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
47	Anchor Point-Purlin Fix-15kN	Safemaster / Safemaster	L53	14/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
48	Sign-Roof Access	Safemaster / Safemaster	Woolworths Loading Dock	17/07/2018	21/06/2019	21/06/2020	AS1319:1994 AS1891.4-2009	Pass	New sign installed
49	Roof Access Stairs	Unknown/ Unknown	Woolworths Loading Dock - L08	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	No toe boards on mid landing. No yellow nosings
50	Walkway (provides access to central mall and general retail only)	Unknown/ Unknown	Central Mall and General Retail (West of Parapet)	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	Height variations, slip resistance, height above adjacent areas
51	Guardrail (ball and pipe with cable infill)	Unknown/ Unknown	Woolworths - Ranford Road Side	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
52	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Woolworths - Ranford Road Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
53	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Woolworths - Ranford Road Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
54	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Ranford Road Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
55	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Ranford Road Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Ranford Road Side	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
57	Guardrail (ball and pipe with cable infill)	Unknown / Unknown	General Retail - Ranford Road Side	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
58	Parapet Crossover Ladder (Alu)	Safetmaster / Safemaster	Woolworths Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
59	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Woolworths Entrance	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
60	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Woolworths Entrance	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
61	Permanent Incline Ladder	Safetmaster / Safemaster	Woolworths Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
62	Permanent Incline Ladder	Safetmaster / Safemaster	Woolworths Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
63	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
64	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
65	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
66	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
68	Anchor Point-Purlin Fix-15kN (LowPro)	Safetmaster / Safemaster	General Retail - Main Carpark Side	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
69	Roof Access Hatch	Unknown/ Unknown	Roof Above Central Service Corridor	Unknown	21/06/2019	21/06/2020	AS1657:2018 OHS Regs. 1996	Fail	There is no access to the hatch from inside
70	Guardrail Surround	Safetmaster / Safemaster	Roof Above Central Service Corridor	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
71	Vertical Ladder (Galv)	Unknown / Unknown	Store Room Off Central Service Corridor	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	Ladder has been cut off and new ceiling installed. Room now used as storage
72	Parapet Crossover Step Ladder (Alu)	RSS / Unknown	Central Mall and General Retail (centre of roof)	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
73	Walkway (provides access to central mall and general retail only)	Unknown/ Unknown	Central Mall and General Retail (East of Parapet)	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
74	Mechanical Plant Platform	Unknown/ Unknown	Central Mall and General Retail (East of Parapet)	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
75	Mechanical Plant Platform	Unknown/ Unknown	Central Mall and General Retail (East of Parapet)	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
76	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
77	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Main Carpark Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
79	Parapet Crossover Ladder (Alu)	Safetmaster / Safemaster	Big W Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
80	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Entrance	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
81	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Entrance	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
82	Permanent Incline Ladder	Safetmaster / Safemaster	Big W Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
83	Permanent Incline Ladder	Safetmaster / Safemaster	Big W Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
84	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Nicholson Road Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
85	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Nicholson Road Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
86	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	General Retail - Nicholson Road Side	1/11/2012	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
87	Guardrail (ball and pipe with cable infill)	Unknown / Unknown	General Retail - Nicholson Road Side	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
88	Parapet Crossover Ladder (Alu)	Safetmaster / Safemaster	Nicholson Road Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingstons Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Nicholson Road Entrance	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
90	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Nicholson Road Entrance	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
91	Permanent Incline Ladder	Safetmaster / Safemaster	Nicholson Road Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
92	Permanent Incline Ladder	Safetmaster / Safemaster	Nicholson Road Entrance	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
93	Anchor Point-Purlin Fix-15kN (LowPro)	Safetmaster / Safemaster	General Retail - Nicholson Road Side	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
94	Stairs (Conc.)	Unknown / Unknown	Woolworths Plant Room	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	No toe board on mid landing
95	Step Ladder (Galv)	Unknown / Unknown	Woolworths Plant Room	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	Handrails non compliant, no toeboard on landing, over allow maximum width
96	Roof Access Door	Unknown / Unknown	Woolworths Plant Room	Unknown	21/06/2019	21/06/2020	AS1657:2018 OHS Regs. 1996	Fail	Low headroom signage required
97	Walkway (provides access to Woolworths roof only)	Unknown / Unknown	Woolworths Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	Height variations, slip resistance
98	Mechanical Plant Platform	Unknown / Unknown	Woolworths Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
99	Sign-Roof Access	Safetmaster / Safemaster	Woolworths Roof - Plant Room Roof	1/04/2016	21/06/2019	21/06/2020	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Ladder Access Bracket	Safetmaster / Safemaster	Woolworths Roof - Plant Room Roof	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
101	Anchor Point-Purlin Fix-15kN (LowPro)	Safetmaster / Safemaster	Woolworths Roof - Plant Room Roof	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
102	Anchor Point-Purlin Fix-15kN	Unknown / Unknown	Woolworths Roof - Plant Room Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
103	Anchor Point-Purlin Fix-15kN	Unknown / Unknown	Woolworths Roof - Plant Room Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
104	Guardrail (ball and pipe with cable infill)	Unknown / Unknown	Woolworths Roof - Central Corridor Side	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
105	Stairs (Galv)	Unknown / Unknown	Big W Plant Room	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	No mid rail, toe board or yellow nosings
106	Vertical Ladder (Galv)	Unknown / Unknown	Big W Plant Room	Unknown	21/06/2019	21/06/2020	AS1657:2018	Fail	Clearances less than required minimum, no non slip rung
107	Sign-Roof Access	Safemaster / Safemaster	Big W Plant Room	1/04/2016	21/06/2019	21/06/2020	AS1319:1994 AS1891.4-2009	Pass	
108	Roof Access Door	Unknown / Unknown	Big W Plant Room	Unknown	21/06/2019	21/06/2020	AS1657:2018 OHS Regs. 1996	Fail	
109	Walkway (provides access to Woolworths roof only)	Unknown / Unknown	Big W Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
110	Mechanical Plant Platform	Unknown / Unknown	Big W Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
112	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
113	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
114	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
115	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
116	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
117	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
118	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
119	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
120	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
121	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
123	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
124	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
125	Anchor Point-Purlin Fix-15kN	Safetylink / Unknown	Big W Roof	1/11/2012	21/06/2019	21/06/2020	AS1657:2018	Pass	
126	Guardrail (ball and pipe with cable infill)	Unknown / Unknown	Big W Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
127	Guardrail (ball and pipe with cable infill)	Unknown / Unknown	Big W Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
128	Guardrail (ball and pipe with cable infill)	Unknown / Unknown	Big W Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
129	Guardrail (ball and pipe with cable infill)	Unknown / Unknown	Big W Roof	Unknown	21/06/2019	21/06/2020	AS1657:2018	Pass	
130	Parapet Crossover Ladder (Alu)	Safetmaster / Safemaster	Big W Loading Dock	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
131	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Loading Dock	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
132	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Loading Dock	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Loading Dock	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
134	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Loading Dock	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
135	Sign	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
136	Ladder Access Bracket	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
137	Access Strop-15kN	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
138	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
139	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
140	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
141	Permanent Incline Ladder	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1657:2018	Pass	
142	Hotizontal Static Line-15kN	Safetmaster / Safemaster	Big W Garden Centre	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
143	Sign-EWP Access Only	Safety Signs / Safemaster	Woolworths Loading Dock	1/03/2018	21/06/2019	21/06/2020	AS1319:1994	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingstons Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Sign-EWP Access Only	Safety Signs / Safemaster	High Voltage Distribution Room	1/03/2018	21/06/2019	21/06/2020	AS1319:1994	Pass	
145	Sign-EWP Access Only	Safety Signs / Safemaster	Awning - Ranford Road Side	1/03/2018	21/06/2019	21/06/2020	AS1319:1994	Pass	
146	Sign-EWP Access Only	Safety Signs / Safemaster	Awning - Nicholson Road Side	1/03/2018	21/06/2019	21/06/2020	AS1319:1994	Pass	
147	Sign-Roof Access	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1319:1994 AS1891.4:2009	Pass	
148	Ladder Access Bracket	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
149	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
150	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
151	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
152	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
153	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
154	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centres

Job Ref: SM12182

Site: Livingsgton Marketplace

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
156	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
157	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
158	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
159	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
160	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	
161	Anchor Point-Surface Mount-15kN	Safetmaster / Safemaster	External Retail - Dominos, Subway, TAB	1/03/2018	21/06/2019	21/06/2020	AS1891.4:2009	Pass	

AUTHORISED BY: Brandon Vitek

DATE: 06-08-2019

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au