

Roof Safety Report

Mandurah Forum, WA 6210

Prepared By: Safemaster Safety Products
Date: 07-08-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Vicinity Centres Mandurah Forum Shopping Centre, WA in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Mandurah Forum Shopping Centre, WA and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you. If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Brandon Vitek (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Brandon Vitek (Recertification Technician)

Roof Safety Report for
Mandurah Forum, WA 6210

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres - Mandurah Forum Shopping Centre, WA	Mandurah Forum Shopping Centre, WA	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

25-07-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Mandurah Forum Shopping Centre, WA.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
2	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
3	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
4	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
5	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
6	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
7	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
8	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
9	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
10	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
11	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
13	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
14	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
15	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
16	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
17	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
18	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
19	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
20	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
21	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
22	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
24	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
25	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
26	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
27	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
28	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
29	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
30	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
31	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
32	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
33	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
35	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
36	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
37	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
38	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
39	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
40	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
41	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
42	Low Pro Anchor Point	Safemaster	Woolworths Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
43	Low Pro Anchor Point	Safemaster	Electrical Room	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
44	Low Pro Anchor Point	Safemaster	Electrical Room	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Low Pro Anchor Point	Safemaster	Electrical Room	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
46	Low Pro Anchor Point	Safemaster	Electrical Room	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
47	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
48	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
49	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
50	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
51	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
52	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
53	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
54	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
55	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
57	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
58	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
59	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
60	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
61	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
62	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
63	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
64	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
65	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
66	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
68	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
69	Low Pro Anchor Point	Safemaster	Coles/Kmart Roof	1/07/2010	25/07/2019	25/07/2020	AS1891.4:2009	Pass	
70	Access Ladder (Al)	Unknown	L1	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
71	Access Ladder (Al)	Unknown	L3	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
72	Access Ladder (Al)	Unknown	L4	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
73	Handrail (Galv)	Unknown	L5	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
74	Access Ladder (Al)	Unknown	L8	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
75	Handrail (Galv)	Unknown	L8	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
76	Access Ladder (Al)	Unknown	L10	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
77	Handrail (Galv)	Unknown	L10	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Step (Al)	Unknown	L14	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
79	Access Ladder (Al)	Unknown	L15	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
80	Handrail (Galv)	Unknown	L15	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
81	Access Ladder (Al)	Unknown	L15	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
82	Access Ladder (Al)	Unknown	L16	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
83	Handrail (Al)	Unknown	L16	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
84	Access Ladder (Al)	Unknown	L17	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
85	Access Ladder (Al)	Unknown	L18	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
86	Handrail (Al)	Unknown	L18	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
87	Access Stair (Al)	Unknown	L20	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
88	Access Stair (Al)	Unknown	L21	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mandurah Forum

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Handrail (Al)	Unknown	L26	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
90	Access Ladder (Galv)	Unknown	L27	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
91	Handrail (Galv)	Unknown	L27	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	
92	Access Ladder (Galv)	Unknown	L27	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
93	Access Ladder (Galv)	Unknown	L27	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Fail	
94	Handrail (Al)	Unknown	L28	1/07/2010	25/07/2019	25/07/2020	AS1657:2013	Pass	

AUTHORISED BY: Brandon Vitek

DATE: 25-07-2019

SIGNATURE:

B. Vitek

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au