

Roof Safety Report

**Midland Gate Shopping Centre,
WA 6056**

Prepared By: Safemaster Safety Products
Date: 13-08-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Midland Gate Shopping Centre, WA 6056 in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Midland Gate Shopping Centre and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Brandon Vitek (Safemaster Safety Products)
31-33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Brandon Vitek (Recertification Technician)

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres, WA 6056	Midland Gate Shopping Centre, WA 6056	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

13-08-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Midland Gate Shopping Centre buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
2	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
3	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
4	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
5	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
6	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
7	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
8	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
9	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
10	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
11	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
13	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
14	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
15	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
16	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
17	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
18	Purlin Fix Anchor	Roof Safe	BIG W	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
19	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
20	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
21	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
22	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
24	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
25	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
26	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
27	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
28	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
29	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
30	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
31	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
32	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
33	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
35	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
36	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
37	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
38	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
39	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
40	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
41	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
42	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
43	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
44	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
46	Purlin Fix Anchor	Roof Safe	Cinema	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
47	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
48	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
49	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
50	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
51	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
52	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
53	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
54	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
55	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
57	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
58	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
59	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
60	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
61	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
62	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
63	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
64	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
65	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
66	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
68	Purlin Fix Anchor	Roof Safe	City Beach	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
69	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
70	Surfacemount Anchor Point 15 Kn	Safemaster	Target	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
71	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
72	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
73	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
74	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
75	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
76	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
77	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
79	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
80	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
81	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
82	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
83	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
84	Purlin Fix Anchor	Roof Safe	Coles	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
85	Purlin Fix Anchor	Roof Safe	Coles	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
86	Purlin Fix Anchor	Roof Safe	Coles	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
87	Purlin Fix Anchor	Roof Safe	Coles	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
88	Purlin Fix Anchor	Roof Safe	Coles	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Purlin Fix Anchor	Roof Safe	Coles	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
90	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
91	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
92	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
93	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
94	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
95	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
96	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
97	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
98	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
99	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Purlin Fix Anchor	Roof Safe	Speilaty Stores	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
101	Purlin Fix Anchor	Safemaster	Out Building	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
102	Purlin Fix Anchor	Safemaster	Out Building	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
103	Purlin Fix Anchor	Safemaster	Out Building	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
104	Purlin Fix Anchor	Safemaster	Out Building	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
105	Purlin Fix Anchor	Roof Safe	Out Building	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
106	Purlin Fix Anchor	Roof Safe	Out Building	Unknown	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
107	Access Ladder (Al)	Safemaster	L1 - Ground Floor	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
108	Roof Access Hatch	Unknown	L1	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
109	Guardrail (Al)	Safemaster	L1	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
110	Step (Al)	Safemaster	L1	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Ladder access Bracket	Safemaster	L2	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
112	Anchor Strop	Safemaster	L2	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
113	Surfacemount Anchor Point 15 Kn	Safemaster	L2	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
114	Surfacemount Anchor Point 15 Kn	Safemaster	L2	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
115	Surfacemount Anchor Point 15 Kn	Safemaster	L2	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
116	Surfacemount Anchor Point 15 Kn	Safemaster	L2	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
117	Surfacemount Anchor Point 15 Kn	Safemaster	L2	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
118	Access Ladder (Al)	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
119	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
120	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
121	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
123	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
124	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
125	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
126	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
127	Surfacemount Anchor Point 15 Kn	Safemaster	L3	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
128	Handrail (Al)	Safemaster	L4	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
129	Ladder access Bracket	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
130	Anchor Strop	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
131	Surfacemount Anchor Point 15 Kn	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
132	Surfacemount Anchor Point 15 Kn	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Surfacemount Anchor Point 15 Kn	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
134	Surfacemount Anchor Point 15 Kn	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
135	Surfacemount Anchor Point 15 Kn	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
136	Step (Al)	Safemaster	L5	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
137	Access Ladder (Al)	Safemaster	L7	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
138	Guardrail (Galv)	Unknown	L7	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
139	Access Ladder (Al)	Safemaster	L8	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
140	Guardrail (Galv)	Unknown	L8	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
141	Access Ladder (Al)	Safemaster	L9	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
142	Guardrail (Galv)	Unknown	L9	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
143	Access Ladder (Al)	Safemaster	L10	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Guardrail (Galv)	Unknown	L10	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
145	Handrail (Al)	Safemaster	L10	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
146	Access Ladder (Al)	Unknown	L11	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
147	Access Ladder (Al)	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
148	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
149	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
150	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
151	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
152	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
153	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
154	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
156	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
157	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
158	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
159	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
160	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
161	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
162	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
163	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
164	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
165	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
167	Surfacemount Anchor Point 15 Kn	Safemaster	L11	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
168	Access Ladder (Al)	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
169	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
170	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
171	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
172	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
173	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
174	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
175	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
176	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
177	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
178	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
179	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
180	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
181	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
182	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
183	Surfacemount Anchor Point 15 Kn	Safemaster	L13	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
184	Access Ladder (Al)	Unknown	L15	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
185	Access Ladder (Al)	Safemaster	L16	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
186	Handrail (Al)	Safemaster	L16	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
187	Surfacemount Anchor Point 15 Kn	Safemaster	L16	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
188	Surfacemount Anchor Point 15 Kn	Safemaster	L16	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
189	Surfacemount Anchor Point 15 Kn	Safemaster	L16	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
190	Access Ladder (Al)	Unknown	L17	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
191	Access Ladder (Al)	Safemaster	L18	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
192	Surfacemount Anchor Point 15 Kn	Safemaster	L18	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
193	Surfacemount Anchor Point 15 Kn	Safemaster	L18	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
194	Surfacemount Anchor Point 15 Kn	Safemaster	L18	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
195	Surfacemount Anchor Point 15 Kn	Safemaster	L18	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
196	Surfacemount Anchor Point 15 Kn	Safemaster	L18	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
197	Surfacemount Anchor Point 15 Kn	Safemaster	L18	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
198	Access Ladder (Al)	Unknown	L20	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
199	Roof Access Hatch	Unknown	L21	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
200	Guardrail (Al)	Unknown	L21	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
201	Access Ladder (Al)	Safemaster	L21	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
202	Ceiling Walkway	Unknown	L21	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
203	Ceiling Handrail (Al)	Safemaster	L21	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
204	Access Ladder (Al)	Safemaster	L22	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
205	Handrail (Al)	Safemaster	L22	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
206	Surfacemount Anchor Point 15 Kn	Safemaster	L22	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
207	Surfacemount Anchor Point 15 Kn	Safemaster	L22	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
208	Surfacemount Anchor Point 15 Kn	Safemaster	L22	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
209	Access Ladder (Al)	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
210	Access Ladder (Al)	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
211	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
212	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
213	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
214	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
215	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
216	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
217	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
218	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
219	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
220	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
221	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
222	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
223	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
224	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
225	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
226	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
227	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
228	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
229	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
230	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
231	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
232	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
233	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
234	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
235	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
236	Surfacemount Anchor Point 15 Kn	Safemaster	L23	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
237	Access Ladder (Al)	Safemaster	L24	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
238	Stair (Galv)	Unknown	L26	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
239	Guardrail (Galv)	Unknown	L26	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
240	Stair (Galv)	Unknown	L30	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
241	Stair (Galv)	Unknown	L31	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
242	Guardrail (Galv)	Unknown	L31	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
243	Access Ladder (Al)	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
244	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
245	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
246	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
247	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
248	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
249	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
250	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
251	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
252	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
253	Surfacemount Anchor Point 15 Kn	Safemaster	L32	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
254	Access Ladder (Al)	Safemaster	L34	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
255	Surfacemount Anchor Point 15 Kn	Safemaster	L34	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
256	Surfacemount Anchor Point 15 Kn	Safemaster	L34	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
257	Surfacemount Anchor Point 15 Kn	Safemaster	L34	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
258	Surfacemount Anchor Point 15 Kn	Safemaster	L34	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
259	Guardrail (Galv)	Unknown	L35	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
260	Handrail (Al)	Safemaster	L36	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
261	Access Ladder (Galv)	Unknown	L38	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
262	Access Ladder (Galv)	Unknown	L38	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
263	Guardrail (Galv)	Unknown	L38	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
264	Access Ladder (Al)	Safemaster	L38	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Purlin Fix Anchor	Safemaster	L38	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
266	Handrail (Al)	Safemaster	L39	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
267	Stair (Galv)	Unknown	L39	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
268	Guardrail (Galv)	Unknown	L39	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
269	Stair (Galv)	Unknown	L40	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
270	Guardrail (Galv)	Unknown	L40	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
271	Access Ladder (Galv)	Unknown	L41	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
272	Step Bridge (Galv)	Unknown	L42	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
273	Step (Al)	Safemaster	L43	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
274	Step Bridge (Galv)	Unknown	L44	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
275	Step Bridge (Galv)	Unknown	L45	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
276	Purlin Fix Anchor	Safemaster	L46	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
277	Purlin Fix Anchor	Safemaster	L46	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
278	Purlin Fix Anchor	Safemaster	L46	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
279	Access Ladder (Al)	Safemaster	L47	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
280	Purlin Fix Anchor	Safemaster	L47	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
281	Purlin Fix Anchor	Safemaster	L47	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
282	Purlin Fix Anchor	Safemaster	L47	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
283	Purlin Fix Anchor	Safemaster	L47	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
284	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
285	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
286	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
287	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
288	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
289	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
290	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
291	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
292	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
293	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
294	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
295	Purlin Fix Anchor	Safemaster	L48	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
296	Access Ladder (AI)	Safemaster	L49	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
297	Handrail (AI)	Safemaster	L50	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
298	Step Bridge (AI)	Safemaster	L51	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
299	Ladder access Bracket	Safemaster	L53	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
300	Anchor Strop	Safemaster	L53	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
301	Surfacemount Anchor Point 15 Kn	Safemaster	L53	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
302	Surfacemount Anchor Point 15 Kn	Safemaster	L53	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
303	Access Ladder (AI)	Safemaster	L54	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
304	Surfacemount Anchor Point 15 Kn	Safemaster	L54	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
305	Surfacemount Anchor Point 15 Kn	Safemaster	L54	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
306	Surfacemount Anchor Point 15 Kn	Safemaster	L54	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
307	Ladder access Bracket	Safemaster	L55	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
308	Anchor Strop	Safemaster	L55	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
309	Surfacemount Anchor Point 15 Kn	Safemaster	L55	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
310	Surfacemount Anchor Point 15 Kn	Safemaster	L55	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
311	Step Bridge (Al)	Safemaster	L58	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
312	Guardrail (Al)	Unknown	L59	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
313	Access Ladder (Al)	Unknown	L61	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
314	Access Ladder (Al)	Unknown	L62	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
315	Step Bridge (Al)	Safemaster	L63	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
316	Step Bridge (Al)	Safemaster	L64	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
317	Step Bridge (Al)	Safemaster	L67	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
318	Step Bridge (Al)	Safemaster	L68	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
319	Step Bridge (Al)	Safemaster	L68	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
320	Access Ladder (Al)	Safemaster	L69	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
321	Roof Access Hatch	Unknown	L70	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
322	Guardrail (Galv)	Unknown	L70	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
323	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
324	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
325	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
326	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
327	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
328	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
329	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
330	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
331	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
332	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
333	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
334	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
335	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
336	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
337	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
338	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
339	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
340	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
341	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
342	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
343	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
344	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
345	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
346	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
347	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
348	Surfacemount Anchor Point 15 Kn	Safemaster	L71	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
349	Surfacemount Anchor Point 15 Kn	Safemaster	L72	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
350	Surfacemount Anchor Point 15 Kn	Safemaster	L72	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
351	Surfacemount Anchor Point 15 Kn	Safemaster	L72	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
352	Surfacemount Anchor Point 15 Kn	Safemaster	L72	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
353	Surfacemount Anchor Point 15 Kn	Safemaster	L72	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
354	Roof Access Hatch	Unknown	L72	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
355	Access Ladder (Al)	Unknown	L72 - TANK	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
356	Access Ladder (Al)	Unknown	L73	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
357	Handrail (Al)	Unknown	L73	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
358	Surfacemount Anchor Point 15 Kn	Safemaster	L74	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
359	Surfacemount Anchor Point 15 Kn	Safemaster	L74	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
360	Surfacemount Anchor Point 15 Kn	Safemaster	L74	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
361	Surfacemount Anchor Point 15 Kn	Safemaster	L74	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
362	Access Ladder (Al)	Safemaster	L77	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
363	Surfacemount Anchor Point 15 Kn	Safemaster	L77	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
364	Surfacemount Anchor Point 15 Kn	Safemaster	L77	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
365	Surfacemount Anchor Point 15 Kn	Safemaster	L77	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
366	Access Ladder (Al)	Safemaster	L78	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
367	Access Ladder (Al)	Unknown	L82	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
368	Step Bridge (Galv)	Unknown	L82	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
369	Access Ladder (Al)	Safemaster	L83 - Ground Floor	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
370	Guardrail (Al)	Safemaster	L83 - Mid Level	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
371	Access Ladder (Al)	Safemaster	L83 - Mid Level	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
372	Roof Access Hatch	Safemaster	L83	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
373	Handrail (Al)	Safemaster	L84	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
374	Step Bridge (Al)	Safemaster	L84	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
375	Access Ladder (AI)	Safemaster	L85	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
376	Access Ladder (AI)	Safemaster	L86	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
377	Handrail (AI)	Safemaster	L86	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
378	Access Ladder (AI)	Safemaster	L87	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
379	Handrail (AI)	Safemaster	L87	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
380	Access Ladder (AI)	Safemaster	L88	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
381	Handrail (AI)	Safemaster	L88	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
382	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
383	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
384	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
385	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
386	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
387	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
388	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
389	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
390	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
391	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
392	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
393	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
394	Surfacemount Anchor Point 15 Kn	Safemaster	L89	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
395	Access Ladder (AI)	Safemaster	L90	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
396	Stair (AI)	Safemaster	L91	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
 CALL US: (08) 6243 3111
 EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
397	Handrail (Al)	Safemaster	L92	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
398	Access Ladder (Al)	Safemaster	L93	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
399	Guardrail (Al)	Unknown	L94	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
400	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
401	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
402	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
403	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
404	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
405	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
406	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
407	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
408	Surfacemount Anchor Point 15 Kn	Safemaster	L95	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
409	Handrail (Al)	Safemaster	L96	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
410	Guardrail (Al)	Unknown	L96	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
411	Access Ladder (Al)	Unknown	L97	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
412	Access Ladder (Al)	Unknown	L97	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Fail	
413	Access Ladder (Al)	Safemaster	L98	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
414	Guardrail (Galv)	Unknown	L98	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
415	Ladder Access Bracket	Unknown	L99	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
416	Access Ladder (Al)	Safemaster	L99	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
417	Ladder Access Bracket	Unknown	L100	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
418	Access Ladder (Al)	Unknown	L100	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
419	Ladder Access Bracket	Safemaster	L101	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
420	Handrail (Al)	Safemaster	L101	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
421	Surfacemount Anchor Point 15 Kn	Safemaster	L102	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
422	Surfacemount Anchor Point 15 Kn	Safemaster	L102	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
423	Access Ladder (Al)	Unknown	L103	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
424	Guardrail (Galv)	Unknown	L103	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
425	Access Ladder (Al)	Safemaster	L104	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
426	Step (Al)	Safemaster	L104	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
427	Access Ladder (Al)	Safemaster	L105	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
428	Ladder Access Bracket	Safemaster	L106	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
429	Anchor Strop	Safemaster	L106	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
430	Surfacemount Anchor Point 15 Kn	Safemaster	L106	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
431	Access Ladder (Al)	Safemaster	L107	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
432	Anchor Strop	Safemaster	L107	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
433	Surfacemount Anchor Point 15 Kn	Safemaster	L107	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
434	Ladder Access Bracket	Safemaster	L108	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
435	Anchor Strop	Safemaster	L108	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
436	Surfacemount Anchor Point 15 Kn	Safemaster	L108	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
437	Roof Access Hatch	Unknown	L109	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
438	Access Ladder (Al)	Safemaster	L109	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
439	Surfacemount Anchor Point 15 Kn	Safemaster	L109	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
440	Access Ladder (Al)	Safemaster	L109	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
441	Surfacemount Anchor Point 15 Kn	Safemaster	L110	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
442	Access Ladder (Al)	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
443	Access Ladder (Al)	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
444	Access Ladder (Al)	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
445	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
446	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
447	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
448	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
449	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
450	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
451	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
452	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
453	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
454	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
455	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
456	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
457	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
458	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
459	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
460	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
461	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
462	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
463	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
464	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
465	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
466	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
467	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
468	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
469	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
470	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
471	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
472	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
473	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
474	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
475	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
476	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
477	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
478	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
479	Surfacemount Anchor Point 15 Kn	Safemaster	L114	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
480	Access Ladder (Al)	Safemaster	L115	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
481	Surfacemount Anchor Point 15 Kn	Safemaster	L115	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
482	Surfacemount Anchor Point 15 Kn	Safemaster	L115	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
483	Surfacemount Anchor Point 15 Kn	Safemaster	L115	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
484	Access Ladder (Al)	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
485	Access Ladder (Al)	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
486	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
487	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
488	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
489	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
490	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
491	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
492	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
493	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
494	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
495	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
496	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
497	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
498	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
499	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
500	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
501	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
502	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
503	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
504	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
505	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
506	Surfacemount Anchor Point 15 Kn	Safemaster	L116	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
507	Step Bridge (AI)	Safemaster	L119	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
508	Surfacemount Anchor Point 15 Kn	Safemaster	L119	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
509	Roof Access Hatch	Unknown	L119	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
510	Access Ladder (AI)	Safemaster	L119	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
511	Access Ladder (AI)	Safemaster	L120	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
512	Step (AI)	Safemaster	L121	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
513	Ladder Access Bracket	Unknown	L121	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
514	Access Ladder (AI)	Safemaster	L121	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
515	Surfacemount Anchor Point 15 Kn	Safemaster	L121	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
516	Access Ladder (AI)	Safemaster	L122	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
517	Access Ladder (AI)	Safemaster	L122	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
518	Access Ladder (Galv)	Unknown	L122	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
519	Roof Access Hatch	Unknown	L123	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
520	Access Ladder (Al)	Safemaster	L123	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
521	Ladder Access Bracket	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
522	Anchor Strop	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
523	Access Ladder (Al)	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
524	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
525	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
526	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
527	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
528	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
529	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
530	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
531	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
532	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
533	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
534	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
535	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
536	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
537	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
538	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
539	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
540	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
541	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
542	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
543	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
544	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
545	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
546	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
547	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
548	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
549	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
550	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
551	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
552	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
553	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
554	Surfacemount Anchor Point 15 Kn	Safemaster	L124	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
555	Access Ladder (Al)	Safemaster	L125 - Ground Floor	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
556	Roof Access Hatch	Unknown	L125	Unknown	13/08/2019	13/08/2020	AS 1657-2018	Pass	
557	Purlin Fix Anchor	Safemaster	L125	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
558	Ladder Access Bracket	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
559	Anchor Strop	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
560	Access Ladder (Al)	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS 1657-2018	Pass	
561	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
562	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
563	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
564	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
565	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
566	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
567	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
568	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
569	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
570	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
571	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
572	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
573	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
574	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
575	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
576	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
577	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
578	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
579	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
580	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
581	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
582	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
583	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Midland Gate Shopping Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
584	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	
585	Surfacemount Anchor Point 15 Kn	Safemaster	L130	1/11/2017	13/08/2019	13/08/2020	AS/NZS 1891.4-2009	Pass	

AUTHORISED BY: Brandon Vitek

DATE: 13-08-2019

SIGNATURE:

B. Vitek

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au