

Roof Safety Report

Morley Senior High School

Prepared By: Safemaster Safety Products
Date: 28/3/2018

CONFIDENTIALITY/SECURITY

Information obtained from and about Morley SHS in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Morley SHS and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification, then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tyron Menikides (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Tony Pennington (Recertification Technician)

Roof Safety Report for
Morley Senior High School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Programmed Facility Management	Gym & Canteen Manual Arts Study Room Admin Upper Science Block D Science Library Social Studies	Anchor Points Signage Ladder Brackets Access Ladders Ladder Support Platforms

DATE OF INSPECTION

28/3/2018

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Morley Senior High School buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Fail	Out of service. Wrong fixing.
2	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
3	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
4	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
5	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
6	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
7	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
8	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
9	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
10	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
11	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
12	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
14	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
15	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
16	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
17	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
18	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
19	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
20	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
21	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
22	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
23	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
24	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
26	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
27	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
28	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
29	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
30	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
31	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
32	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
33	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
34	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
35	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
36	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
38	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
39	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
40	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
41	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
42	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
43	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
44	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
45	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
46	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
47	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
48	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
50	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
51	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
52	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
53	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
54	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
55	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
56	Anchor Point-Surfacemount-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
57	Sign	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1319:1994 AS1891.4-2009	Pass	
58	Ladder Access Bracket	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
59	Anchor Strop-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
60	Ladder Access Bracket	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Anchor Strop-15kN	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
62	Access Ladder 3.0m With static line.	RIS / RIS	Gym & Canteen	1/07/2013	28/03/2018	28/09/2018	AS1657:2013	Fail	Out of service Not properly secured at top.
63	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Fail	Out of service. Anchor's rivets missing.
64	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
65	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
66	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
67	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
68	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
69	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
70	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
71	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
72	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
74	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
75	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
76	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
77	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
78	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
79	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
80	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
81	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
82	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
83	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
84	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Anchor Point-Surfacemount-15kN	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
86	Sign	RIS / RIS	Manual Arts	1/10/2013	28/03/2018	28/09/2018	AS1319:1994 AS1891.4-2009	Pass	
87	Access Ladder	Unknown	Manual Arts	Unknown	28/03/2018	28/09/2018	AS1657:2013	Pass	
88	Access Ladder	Unknown	Manual Arts	Unknown	28/03/2018	28/09/2018	AS1657:2013	Pass	
89	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
90	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
91	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
92	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
93	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
94	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
95	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
96	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
98	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
99	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
100	Sign	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1319:1994 AS1891.4-2009	Pass	
101	Ladder Access Bracket	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
102	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
103	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
104	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
105	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
106	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
107	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
108	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
110	Anchor Point-Surfacemount-15kN	RIS / RIS	Study Room	1/05/2011	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
111	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
112	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
113	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
114	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
115	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
116	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
117	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
118	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
119	Sign	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1319:1994 AS1891.4-2009	Pass	
120	Ladder Access Bracket	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Anchor Strop-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
122	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
123	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
124	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
125	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
126	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
127	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
128	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
129	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
130	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
131	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
132	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Anchor Point-Surfacemount-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
134	Sign	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1319:1994 AS1891.4-2009	Pass	
135	Ladder Access Bracket	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
136	Anchor Strop-15kN	RIS / RIS	Admin	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
137	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
138	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
139	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
140	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
141	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
142	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
143	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
144	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
146	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
147	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
148	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
149	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
150	Ladder Access Bracket	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
151	Ladder Support Platform	Safemaster/ Safemaster	Upper Science	1/10/2013	28/03/2018	28/09/2018	AS1657:2013	Pass	
152	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
153	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
154	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
155	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
156	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
157	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
158	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
159	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
160	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
161	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
162	Access Ladder	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1657:2013	Pass	
163	Access Ladder	Safemaster/ Safemaster	Block D	1/09/2013	28/03/2018	28/09/2018	AS1657:2013	Pass	
164	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
165	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
166	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
167	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
168	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
170	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
171	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
172	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
173	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
174	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
175	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
176	Sign	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1319:1994 AS1891.4-2009	Pass	
177	Access Ladder	Safemaster/ Safemaster	Science	1/09/2013	28/03/2018	28/09/2018	AS1657:2013	Pass	
178	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
179	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
180	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management
Job Ref: SM 8424
Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
181	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
182	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
183	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
184	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
185	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
186	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
187	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
188	Access Ladder	Safemaster/ Safemaster	Library	1/09/2013	28/03/2018	28/09/2018	AS1657:2013	Pass	
189	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
190	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
191	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
192	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Programmed Facility Management

Job Ref: SM 8424

Site: Morley Senior High School - 19-43 Bramwell Road, Morley

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
193	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
194	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
195	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
196	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
197	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
198	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
199	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
200	Anchor Point-Surfacemount-15kN	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1891.4:2009	Pass	
201	Access Ladder	Safemaster/ Safemaster	Social Studies	1/09/2013	28/03/2018	28/09/2018	AS1657:2013	Pass	

AUTHORISED BY: TONY PENNINGTON

DATE: 28/3/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

COMPLIANCE REQUIREMENTS

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au