

Roof Safety Report

**Mornington Central,
VIC 3931**

Prepared By: Safemaster Safety Products
Date: 18-09-2019

CONFIDENTIALITY/SECURITY

Information obtained from and about Mornington Central in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Mornington Central and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

A handwritten signature in black ink, appearing to be 'JT' followed by a horizontal line and a diagonal stroke.

James Townsend (Recertification Technician)

Roof Safety Report for
Mornington Central, VIC 3931

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Vicinity Centres- Mornington Central	Mornington Central	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

06-09-2019

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Mornington Central buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Mornington Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Access Ladder (Al)	Unknown	L1 - Ground Floor	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
2	Roof Access Hatch	Unknown	L1	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
3	Surfacemount Anchor Point	SAFEMASTER	L2	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point	SAFEMASTER	L2	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point	SAFEMASTER	L2	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point	SAFEMASTER	L2	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point	SAFEMASTER	L2	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point	SAFEMASTER	L2	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point	SAFEMASTER	L2	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point	SAFEMASTER	L4	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point	SAFEMASTER	L4	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Mornington Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Surfacemount Anchor Point	SAFEMASTER	L4	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
13	Surfacemount Anchor Point	SAFEMASTER	L4	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
14	Surfacemount Anchor Point	SAFEMASTER	L4	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
15	Surfacemount Anchor Point	SAFEMASTER	L4	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
16	Ladder Access Bracket	SAFEMASTER	L4	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
17	Low Pro Anchor Point	SAFEMASTER	L5	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
18	Access Ladder (Al)	SAFEMASTER	L5	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
19	Low Pro Anchor Point	SAFEMASTER	L6	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
20	Access Ladder (Al)	SAFEMASTER	L6	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
21	Access Stair (Al)	Unknown	L7	Unknown	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
22	Guardrail (Galv)	Unknown	L7	Unknown	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Mornington Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Access Stair (Al)	Unknown	L10	Unknown	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
24	Access Stair (Galv)	Unknown	L12	Unknown	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
25	Access Stair (Galv)	Unknown	L23	Unknown	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
26	Access Stair (Al)	Unknown	L24	Unknown	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
27	Surfacemount Static Line	SAFEMASTER	L27	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
28	Anchor Strop	SAFEMASTER	L27	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
29	Ladder Access Bracket	SAFEMASTER	L27	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
30	Surfacemount Static Line	SAFEMASTER	L28	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
31	Anchor Strop	SAFEMASTER	L28	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
32	Ladder Access Bracket	SAFEMASTER	L28	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
33	Surfacemount Static Line	SAFEMASTER	L29	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Mornington Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Anchor Strop	SAFEMASTER	L29	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
35	Ladder Access Bracket	SAFEMASTER	L29	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
36	Access Ladder (Al)	SAFEMASTER	L30	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
37	Handrail (Al)	SAFEMASTER	L30	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
38	Low Pro Anchor Point	SAFEMASTER	L31	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
39	Access Ladder (Al)	SAFEMASTER	L31	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
40	Low Pro Anchor Point	SAFEMASTER	L32	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
41	Access Ladder (Al)	SAFEMASTER	L32	10/05/2018	6/09/2019	6/09/2020	AS/NZS 1657-2013	Pass	
42	Surfacemount Anchor Point	SAFEMASTER	L33	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
43	Surfacemount Anchor Point	SAFEMASTER	L33	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
44	Surfacemount Anchor Point	SAFEMASTER	L33	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres
Job Ref: SM12182
Site: Mornington Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Surfacemount Anchor Point	SAFEMASTER	L33	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point	SAFEMASTER	L33	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
47	Surfacemount Anchor Point	SAFEMASTER	L33	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
48	Surfacemount Anchor Point	SAFEMASTER	L33	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
49	Ladder Access Bracket	SAFEMASTER	L34	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
50	Surfacemount Anchor Point	SAFEMASTER	L34	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
51	Surfacemount Anchor Point	SAFEMASTER	L34	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
52	Surfacemount Anchor Point	SAFEMASTER	L34	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
53	Surfacemount Anchor Point	SAFEMASTER	L34	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
54	Surfacemount Anchor Point	SAFEMASTER	L34	10/05/2018	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
55	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182

Site: Mornington Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
57	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
58	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
59	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
60	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
61	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
62	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
63	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
64	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
65	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	
66	Low Pro Anchor Point	Unknown	Main Roof	Unknown	6/09/2019	6/09/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centres

Job Ref: SM12182


Site: Mornington Central

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Access Sign	Safemaster	Hatch	6/06/2016	6/09/2019	6/09/2020	AS1319:1994 AS1891.4-2009	Pass	
68	Access Sign	Safemaster	Access Stair	6/06/2016	6/09/2019	6/09/2020	AS1319:1994 AS1891.4-2009	Pass	
69	Access Sign	Safemaster	Access Stair	6/06/2016	6/09/2019	6/09/2020	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 06/09/2019

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au