

Roof Safety Report

Narrogin Government Building

Prepared By: Safemaster Safety Products
Date: 05/04/18

Roof Safety Report for Narrogin Government Building

CONFIDENTIALITY/SECURITY

Information obtained from and about Narrogin Government Building in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Narrogin Government Building and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Trevor Harris (Recertification Technician)

Roof Safety Report for
Narrogin Government Building

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
JLL	Narrogin Government Building	Anchor Points Signage Access Ladder Static Line

DATE OF INSPECTION

05/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Narrogin Government Building.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: JLL

Job Ref: SM 11468

Site: Narrogin Government Building

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
2	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
3	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
4	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
5	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
6	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
7	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
8	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
9	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
10	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
11	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
12	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: JLL

Job Ref: SM 11468

Site: Narrogin Government Building

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
14	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
15	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
16	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
17	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
18	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
19	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
20	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
21	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
22	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
23	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
24	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: JLL

Job Ref: SM 11468

Site: Narrogin Government Building

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Frog Link Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
26	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
27	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
28	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
29	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
30	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
31	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
32	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
33	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
34	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
35	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
36	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: JLL

Job Ref: SM 11468

Site: Narrogin Government Building

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Abseil Anchor Point 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
38	Access Strop 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
39	Access Strop 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
40	Access Strop 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
41	Access Ladder	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1657:2013	Pass	
42	Vertical Static Line 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
43	Access Ladder	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1657:2013	Pass	
44	Vertical Static Line 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
45	Access Ladder	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1657:2013	Pass	
46	Vertical Static Line 15 kn	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1891.4:2009	Pass	
47	Access Sign	Safemaster	Narrogin Government Building	1/11/2015	5/04/2018	5/10/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: JLL

Job Ref: SM 11468

Site: Narrogin Government Building

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
---------	-----------------------------	-------------------------	----------	-----------------	-----------	----------------	---------------------	--------	----------

AUTHORISED BY: Trevor Harris

DATE: 05/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Roof Safety Report for Narrogin Government Building

COMPLIANCE REQUIREMENTS

There are no recommendations at this point in time.

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au