

# Roof Safety Report

Newton Moore Senior High  
School

Prepared By: Safemaster Safety Products  
Date: 1/05/18

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Newton Moore Senior High School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Newton Moore Senior High School and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Trevor Harris (Recertification Technician)**

Roof Safety Report for  
Newton Moore Senior High School

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Student Services/Staff Room/ S1-S5 Gym IRC T1-T5 Canteen/C1-C4 C5-C11/D11-D12 E1-E11 F1-F5 G1-G7 G1A	Anchor Points Signage Ladder Bracket Ladders

DATE OF INSPECTION

1/05/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Newton Moore Senior High School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
12	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
13	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
14	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
15	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
16	Surfacemount Anchor Point	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
17	Ladder Bracket	Safemaster	Student Services/Staff Room/S1-S5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	See requirements
18	Sign	Safemaster	Student Services/Staff Room/S1-S5	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	See requirements
19	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
20	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
21	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
22	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
23	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
25	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point	RSS	Gym	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
31	Surfacemount Anchor Point	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
32	Surfacemount Anchor Point	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
33	Vertical ladder & Static Line	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1647-2013	Pass	
34	Parapet Ladder	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1647-2013	Pass	
35	Walkway	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1647-2013	Pass	
36	Guardrail	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1647-2013	Pass	
37	Strop	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
38	Ladder Bracket	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
39	Sign	Safemaster	Gym	1/07/2017	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
40	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
44	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
45	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
46	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
47	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
48	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
49	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
50	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
51	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
52	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
53	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
54	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
55	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Not Certified	No access to roof
56	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Not Certified	No access to roof
57	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Not Certified	No access to roof
58	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Not Certified	No access to roof
59	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Not Certified	No access to roof
60	Purlin Fix Anchor Point	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Not Certified	No access to roof

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Ladder Bracket	Safemaster	IRC	1/02/2011	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
62	Sign	Safemaster	IRC	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
63	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
64	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
65	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
66	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
67	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
68	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
69	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
70	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
71	Surfacemount Anchor Point	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
72	Ladder Bracket	Safemaster	T1-T5	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
73	Sign	Safemaster	T1-T5	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
74	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
75	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
76	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
77	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
78	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
79	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
80	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
81	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
82	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
83	Surfacemount Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
84	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
85	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
86	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
87	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
88	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
89	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
90	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
91	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
92	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
93	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
94	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
95	Purlin Fix Anchor Point	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
96	Ladder Bracket	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
97	Ladder Bracket	Safemaster	Canteen/C1-C4	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
98	Sign	Safemaster	Canteen/C1-C4	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
99	Sign	Safemaster	Canteen/C1-C4	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
100	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
101	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
102	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
103	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
104	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
105	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
106	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
107	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
108	Surfacemount Anchor Point	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
109	Ladder Bracket	Safemaster	C5-C11/D11-D12	1/05/2008	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
110	Sign	Safemaster	C5-C11/D11-D12	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
111	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
112	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
113	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
114	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
115	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
116	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
117	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
118	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
119	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
120	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
122	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
123	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
124	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
125	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
126	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
127	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
128	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
129	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
130	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
131	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
132	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
133	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
134	Surfacemount Anchor Point	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
135	Ladder Bracket	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
136	Ladder Bracket	Safemaster	E1-E11	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
137	Sign	Safemaster	E1-E11	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
138	Sign	Safemaster	E1-E11	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
139	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
140	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
141	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
142	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
143	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
144	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
145	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
146	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
147	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
148	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
149	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
150	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
151	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
152	Surfacemount Anchor Point	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
153	Ladder Bracket	Safemaster	F1-F5	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
154	Sign	Safemaster	F1-F5	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
155	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
156	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
157	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
158	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
159	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
160	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
161	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
162	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
163	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
164	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
165	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
167	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
168	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

**Client:** BMW Bunbury  
**Job Ref:** SM 7173  
**Site:** Newton Moore Senior High School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
169	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
170	Surfacemount Anchor Point	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
171	Ladder Bracket	Safemaster	G1-G7	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
172	Sign	Safemaster	G1-G7	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	
173	Purlin Fix Anchor Point	RSS	G1A	1/06/2010	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
174	Purlin Fix Anchor Point	RSS	G1A	1/06/2010	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
175	Purlin Fix Anchor Point	RSS	G1A	1/06/2010	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
176	Purlin Fix Anchor Point	RSS	G1A	1/06/2010	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
177	Purlin Fix Anchor Point	RSS	G1A	1/06/2010	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
178	Purlin Fix Anchor Point	RSS	G1A	1/06/2010	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
179	Ladder Bracket	RSS	G1A	1/10/2013	1/05/2018	1/11/2018	AS1891.4:2009	Pass	
180	Sign	Safemaster	G1A	1/10/2015	1/05/2018	1/11/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 1/05/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## Compliance requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)