

Roof Safety Report

Ocean Road Primary School

Prepared By: Safemaster Safety Products
Date: 19/10/2016

CONFIDENTIALITY/SECURITY

Information obtained from and about Ocean Road Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Ocean Road Primary School and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6218 5158 EMAIL: recertifications@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:

A handwritten signature in black ink, appearing to read 'Jb' followed by a stylized horizontal line and a vertical stroke.

James Townsend (Recertification Technician)

Roof Safety Report for
Ocean Road Primary School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	Music/Science Pre Primary	Anchor Points Signage

DATE OF INSPECTION

18/10/2016

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Ocean Road Primary School buildings.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 12850

Site: Ocean Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Low Pro Anchor Point	Safemaster	Music/Science	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
2	Low Pro Anchor Point	Safemaster	Music/Science	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
3	Low Pro Anchor Point	Safemaster	Music/Science	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
4	Low Pro Anchor Point	Safemaster	Music/Science	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
5	Low Pro Anchor Point	Safemaster	Music/Science	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
6	Low Pro Anchor Point	Safemaster	Music/Science	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
7	Sign	Safemaster	Music/Science	1/11/2012	18/10/2016	18/04/2017	AS1319:1994 AS1891.4-2009	Pass	
8	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
9	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
10	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
11	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6218 5158
EMAIL: inspections@safemaster.net.au

Client: BMW Bunbury

Job Ref: SM 12850


Site: Ocean Road Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
13	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
14	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
15	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
16	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
17	Low Pro Anchor Point	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1891.4:2009	Pass	
18	Sign	Safemaster	Pre Primary	1/11/2012	18/10/2016	18/04/2017	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 19/10/2016

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

RECOMMENDATIONS

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6218 5158

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au