

# Roof Safety Report

**Perth Airport Fire Station**

Prepared By: Safemaster Safety Products  
Date: 7/5/2018

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Perth Airport Fire Station in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Perth Airport Fire Station and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Tony Pennington (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6218 5158 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



**Tony Pennington (Recertification Technician)**

Roof Safety Report for  
**Perth Airport Fire Station**

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Bayside	Fire Station Special Vehicle Bay PPE/OES Store EVT Store Lawnmower Store	Anchor Points Signage Ladder Brackets Ladders Static Line

---

**DATE OF INSPECTION**

7/5/2018

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Perth Airport Fire Station buildings.

The inspection is based on:

- Work Health and Safety Regulations 2012
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Bayside

**Job Ref:** SM 11436

**Site:** Perth Airport

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	Legible
2	Ladder Bracket	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
3	Access Strop -15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
4	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
5	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
6	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
7	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
8	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
9	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
10	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
11	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
12	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Bayside

**Job Ref:** SM 11436

**Site:** Perth Airport

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
14	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
15	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
16	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
17	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
18	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
19	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
20	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
21	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
22	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
23	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
24	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Bayside

**Job Ref:** SM 11436

**Site:** Perth Airport

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
26	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
27	Anchor Point-Purlin Fix-15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
28	Permanent Incline Ladder 1.5m	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1657:2013	Pass	In Working Order
29	Permanent Incline Ladder 1.5m	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1657:2013	Pass	In Working Order
30	Vertical Parapet Ladder With Static Line 3.0m	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1657:2013 AS1891.4-2009	Pass	In Working Order
31	Ladder Bracket	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
32	Ladder Bracket	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
33	Access Strop -15kN	RIS/RIS	Main Building	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
34	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
35	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
36	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Client: Bayside

Job Ref: SM 11436

Site: Perth Airport

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
38	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
39	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
40	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
41	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Special Vehicle Bay	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
42	Ladder Bracket	RIS/RIS	Observation Tower	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
43	Anchor Point-Purlin Fix-15kN	RIS/RIS	Observation Tower	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
44	Anchor Point-Purlin Fix-15kN	RIS/RIS	Observation Tower	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
45	Anchor Point-Purlin Fix-15kN	RIS/RIS	Observation Tower	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
46	Anchor Point-Purlin Fix-15kN	RIS/RIS	Observation Tower	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
47	Anchor Point-Purlin Fix-15kN	RIS/RIS	Observation Tower	26/03/2010	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	In Working Order
48	Sign	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	Legible

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Bayside

**Job Ref:** SM 11436

**Site:** Perth Airport

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Ladder Bracket	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
50	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
51	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
52	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
53	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
54	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
55	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
56	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
57	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	PPE/OES Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
58	Sign	Safemaster / Safemaster	EVT/Store	1/02/2016	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	Legible
59	Ladder Bracket	Safemaster / Safemaster	EVT/Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
60	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	EVT/Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

Client: Bayside

Job Ref: SM 11436

Site: Perth Airport

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	EVT/Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
62	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	EVT/Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
63	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	EVT/Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
64	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	EVT/Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
65	Sign	Safemaster / Safemaster	Lawnmower Store	1/02/2016	7/05/2018	7/05/2019	AS1319:1994 AS1891.4-2009	Pass	Legible
66	Ladder Bracket	Safemaster / Safemaster	Lawnmower Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
67	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lawnmower Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
68	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lawnmower Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
69	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lawnmower Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order
70	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Lawnmower Store	1/02/2016	7/05/2018	7/05/2019	AS1891.4:2009	Pass	In Working Order

AUTHORISED BY: Tony Pennington

DATE: 7/5/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## RECOMMENDATIONS

There are no recommendations at this point in time.

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6218 5158

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)