

Roof Safety Report

Pinjarra Primary School

Prepared By: Safemaster Safety Products
Date: 17/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about Pinjarra Primary School in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Pinjarra Primary School and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Trevor Harris (Recertification Technician)

Roof Safety Report for
Pinjarra Primary School

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
BMW Bunbury	17-20 21-25 26-27/Music Library	Anchor Points Signage Ladder Bracket

DATE OF INSPECTION

17/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Pinjarra Primary School buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 12848

Site: Pinjarra Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Low Pro Anchor Point	Safemaster	17-20	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
2	Low Pro Anchor Point	Safemaster	17-20	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
3	Low Pro Anchor Point	Safemaster	17-20	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
4	Low Pro Anchor Point	Safemaster	17-20	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
5	Low Pro Anchor Point	Safemaster	17-20	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
6	Low Pro Anchor Point	Safemaster	17-20	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
7	Sign	Safemaster	17-20	21/10/2016	17/04/2018	17/10/2018	AS1319:1994 AS1891.4-2009	Pass	New Supplied
8	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
9	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
10	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
11	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
12	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 12848

Site: Pinjarra Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
14	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
15	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
16	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
17	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
18	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
19	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
20	Low Pro Anchor Point	Safemaster	21-25	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
21	Sign	Safemaster	21-25	21/10/2016	17/04/2018	17/10/2018	AS1319:1994 AS1891.4-2009	Pass	New Supplied
22	Low Pro Anchor Point	Safemaster	26-27/Music	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
23	Low Pro Anchor Point	Safemaster	26-27/Music	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
24	Low Pro Anchor Point	Safemaster	26-27/Music	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 12848

Site: Pinjarra Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Low Pro Anchor Point	Safemaster	26-27/Music	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
26	Low Pro Anchor Point	Safemaster	26-27/Music	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
27	Low Pro Anchor Point	Safemaster	26-27/Music	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point	RIS	26-27/Music	1/12/2012	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point	RIS	26-27/Music	1/12/2012	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point	RIS	26-27/Music	1/12/2012	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
31	Access Strop	RIS	26-27/Music	1/12/2012	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
32	Ladder Bracket	RIS	26-27/Music	1/12/2012	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
33	Sign	Safemaster	26-27/Music	21/10/2016	17/04/2018	17/10/2018	AS1319:1994 AS1891.4-2009	Pass	
34	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
35	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
36	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: BMW Bunbury

Job Ref: SM 12848

Site: Pinjarra Primary School

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
38	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
39	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
40	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
41	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
42	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
43	Purlin Fix Anchor Point	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
44	Surfacemount Anchor Point	RIS	Library	1/12/2012	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
45	Access Strop	RIS	Library	1/12/2012	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
46	Ladder Bracket	Safemaster	Library	1/11/2010	17/04/2018	17/10/2018	AS1891.4:2009	Pass	
47	Sign	Safemaster	Library	21/10/2016	17/04/2018	17/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 17/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au