

# Roof Safety Report

**Rockingham Centre, WA 6168**

Prepared By: Safemaster Safety Products  
Date: 13 May 2019

**CONFIDENTIALITY/SECURITY**

Information obtained from and about Rockingham Centre, WA in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Rockingham Centre, WA and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)  
31-33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:



**James Townsend (Recertification Technician)**

Roof Safety Report for  
**Rockingham Centre, WA 6168**

---

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Rockingham Centre	Rockingham Centre, Rockingham WA 6168	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

---

**DATE OF INSPECTION**

23/04/2019

**INSPECTION METHODOLOGY**

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Rockingham Centre, WA 6168 buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

**TESTING INSTRUMENT**

Product: HILTI Tester



# **Inspection Log**

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Access Stair (Galv)	Unknown	L1	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
2	Access Ladder (Al)	Safemaster	L1	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
3	Anchor Strop	Safemaster	L1	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
4	Surfacemount Anchor Point	Safemaster	L1	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
5	Surfacemount Anchor Point	Safemaster	L1	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
6	Surfacemount Anchor Point	Safemaster	L1	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
7	Surfacemount Anchor Point	Safemaster	L1	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
8	Surfacemount Anchor Point	Safemaster	L1	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
9	Access Stair (Galv)	Unknown	L3	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
10	Surfacemount Anchor Point	Safemaster	L4	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
11	Surfacemount Anchor Point	Safemaster	L4	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Surfacemount Anchor Point	Safemaster	L4	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
13	Surfacemount Anchor Point	Safemaster	L4	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
14	Surfacemount Anchor Point	Safemaster	L6	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
15	Surfacemount Anchor Point	Safemaster	L6	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
16	Surfacemount Anchor Point	Safemaster	L6	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
17	Surfacemount Anchor Point	Safemaster	L6	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
18	Surfacemount Anchor Point	Safemaster	L6	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
19	Surfacemount Anchor Point	Safemaster	L6	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
20	Surfacemount Anchor Point	Safemaster	L11	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
21	Surfacemount Anchor Point	Safemaster	L20	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
22	Static line	SALA	L16	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Access Sign	SALA	L16	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
24	Static line	SALA	L17	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
25	Access Sign	SALA	L17	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
26	Access Ladder (AI)	Unknown	L18	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
27	Access Ladder (AI)	Unknown	L19	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
28	Access Ladder (AI)	Unknown	L21	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
29	Access Ladder (AI)	Safemaster	L22	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
30	Anchor Strop	Safemaster	L22	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
31	Surfacemount Anchor Point	Safemaster	L22	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
32	Surfacemount Anchor Point	Safemaster	L22	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
33	Surfacemount Anchor Point	Safemaster	L22	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Surfacemount Anchor Point	Safemaster	L22	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
35	Surfacemount Anchor Point	Safemaster	L22	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
36	Surfacemount Anchor Point	Safemaster	L22	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
37	Surfacemount Anchor Point	Safemaster	L22	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
38	Surfacemount Anchor Point	Safemaster	L22	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
39	Surfacemount Anchor Point	Safemaster	L22	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
40	Guardrail (Galv)	Unknown	L24	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
41	Access Stair (Galv)	Unknown	L24	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
42	Access Ladder (Al)	Unknown	L25	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
43	Access Ladder (Al)	Unknown	L26	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
44	Access Ladder (Al)	Unknown	L27	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Access Ladder (Galv)	Unknown	L29	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
46	Access Ladder (Galv)	Unknown	L30	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
47	Anchor Strop	Safemaster	L31	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
48	Surfacemount Anchor Point	Unknown	L31	Unknown	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
49	Surfacemount Anchor Point	Safemaster	L31	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
50	Surfacemount Anchor Point	Safemaster	L31	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
51	Surfacemount Anchor Point	Safemaster	L31	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
52	Surfacemount Anchor Point	Safemaster	L31	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
53	Surfacemount Anchor Point	Safemaster	L31	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
54	Surfacemount Anchor Point	Safemaster	L31	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
55	Surfacemount Anchor Point	Safemaster	L31	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Surfacemount Anchor Point	Safemaster	L31	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
57	Surfacemount Anchor Point	Safemaster	L31	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
58	Surfacemount Anchor Point	Safemaster	L31	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
59	Surfacemount Anchor Point	Safemaster	L31	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
60	Access Ladder (Al)	Unknown	L32	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
61	Access Ladder (Galv)	Unknown	L33	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
62	Surfacemount Anchor Point	Safemaster	L34	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
63	Surfacemount Anchor Point	Safemaster	L34	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
64	Surfacemount Anchor Point	Safemaster	L34	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
65	Surfacemount Anchor Point	Safemaster	L34	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
66	Surfacemount Anchor Point	Safemaster	L34	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Surfacemount Anchor Point	Safemaster	L34	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
68	Surfacemount Anchor Point	Safemaster	L34	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
69	Ladder Bracket	Safemaster	L35	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
70	Anchor Strop	Safemaster	L35	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
71	Surfacemount Anchor Point	Safemaster	L35	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
72	Surfacemount Anchor Point	Safemaster	L35	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
73	Surfacemount Anchor Point	Safemaster	L35	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
74	Surfacemount Anchor Point	Safemaster	L35	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
75	Static line	Safemaster	L36	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
76	Access Stair (Galv)	Unknown	L38	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
77	Static line	SALA	L39	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Access Sign	SALA	L39	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
79	Static line	SALA	L43	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
80	Access Sign	SALA	L43	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
81	Access Ladder (Al)	Safemaster	L46	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
82	Anchor Strop	Safemaster	L46	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
83	Surfacemount Anchor Point	Safemaster	L46	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
84	Surfacemount Anchor Point	Safemaster	L46	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
85	Surfacemount Anchor Point	Safemaster	L46	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
86	Surfacemount Anchor Point	Safemaster	L46	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
87	Surfacemount Anchor Point	Safemaster	L46	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
88	Surfacemount Anchor Point	Safemaster	L46	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Surfacemount Anchor Point	Safemaster	L46	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
90	Surfacemount Anchor Point	Safemaster	L46	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
91	Surfacemount Anchor Point	Safemaster	L46	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
92	Access Stair (Galv)	Unknown	L48	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
93	Access Stair (Galv)	Unknown	L50	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
94	Guardrail (Galv)	Unknown	L50	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
95	Handrail (Al)	Safemaster	L50	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
96	Step (Al)	Safemaster	L50	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
97	Handrail (Al)	Safemaster	L52	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
98	Handrail (Al)	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
99	Surfacemount Anchor Point	Safemaster	L55	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Surfacemount Anchor Point	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
101	Surfacemount Anchor Point	Safemaster	L55	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
102	Surfacemount Anchor Point	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
103	Surfacemount Anchor Point	Safemaster	L55	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
104	Surfacemount Anchor Point	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
105	Surfacemount Anchor Point	Safemaster	L55	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
106	Surfacemount Anchor Point	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
107	Surfacemount Anchor Point	Safemaster	L55	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
108	Surfacemount Anchor Point	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
109	Surfacemount Anchor Point	Safemaster	L55	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
110	Surfacemount Anchor Point	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Surfacemount Anchor Point	Safemaster	L55	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
112	Surfacemount Anchor Point	Safemaster	L55	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
113	Access Ladder (Al)	Safemaster	L56	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
114	Surfacemount Anchor Point	Safemaster	L57	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
115	Surfacemount Anchor Point	Safemaster	L57	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
116	Surfacemount Anchor Point	Safemaster	L57	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
117	Surfacemount Anchor Point	Safemaster	L57	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
118	Surfacemount Anchor Point	Safemaster	L57	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
119	Access Stair (Galv)	Unknown	L57	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
120	Static line	Safemaster	L58	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
121	Access Sign	SALA	L58	1/08/2009	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre  
**Job Ref:** SM12182-RockinghamCentre  
**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Access Ladder (Galv)	Unknown	L60	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
123	Static line	Safemaster	L61	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
124	Access Sign	SALA	L61	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
125	Handrail (Al)	Safemaster	L61	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
126	Low Pro Anchor Point	Unknown	L61	Unknown	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
127	Low Pro Anchor Point	Unknown	L61	Unknown	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
128	Low Pro Anchor Point	Unknown	L61	Unknown	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
129	Access Ladder (Al)	Unknown	L62	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
130	Ladder Bracket	Safemaster	L65	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
131	Anchor Strop	Safemaster	L65	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
132	Surfacemount Anchor Point	Safemaster	L65	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Surfacemount Anchor Point	Safemaster	L65	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
134	Surfacemount Anchor Point	Safemaster	L65	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
135	Ladder Bracket	Safemaster	L66	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
136	Anchor Strop	Safemaster	L66	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
137	Surfacemount Anchor Point	Safemaster	L66	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
138	Surfacemount Anchor Point	Safemaster	L66	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
139	Surfacemount Anchor Point	Safemaster	L66	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
140	Static line	Safemaster	L68	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
141	Access Sign	SALA	L68	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
142	Surfacemount Anchor Point	Safemaster	L70	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
143	Surfacemount Anchor Point	Safemaster	L70	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Static line	SALA	L71	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
145	Access Sign	SALA	L71	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
146	Static line	SALA	L74	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
147	Access Sign	SALA	L74	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
148	Access Ladder (Al)	Unknown	L74	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
149	Handrail (Al)	Safemaster	L75	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
150	Handrail (Al)	Safemaster	L83	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
151	Static line	Safemaster	L85	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
152	Access Sign	SALA	L85	1/08/2009	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
153	Access Ladder (Al)	Unknown	L87	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
154	Purlin Fix Anchor Point	Safemaster	L88	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Purlin Fix Anchor Point	Safemaster	L88	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
156	Purlin Fix Anchor Point	Safemaster	L88	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
157	Purlin Fix Anchor Point	Safemaster	L88	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
158	Ladder Bracket	Safemaster	L88	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
159	Access Stair (Al)	Unknown	L89	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
160	Guardrail (Galv)	Unknown	L89	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
161	Surfacemount Anchor Point	Safemaster	L92	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
162	Surfacemount Anchor Point	Safemaster	L92	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
163	Surfacemount Anchor Point	Safemaster	L92	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
164	Surfacemount Anchor Point	Safemaster	L92	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
165	Surfacemount Anchor Point	Safemaster	L92	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Surfacemount Anchor Point	Safemaster	L92	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
167	Access Ladder (AI)	Unknown	L93	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
168	Access Ladder (AI)	Unknown	L94	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
169	Access Ladder (AI)	Unknown	L96	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
170	Surfacemount Anchor Point	Safemaster	L97	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
171	Access Ladder (AI)	Unknown	L97	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
172	Guardrail (AI)	Unknown	L97	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
173	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
174	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
175	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
176	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
177	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
178	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
179	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
180	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
181	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
182	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
183	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
184	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
185	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
186	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
187	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
188	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
189	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
190	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
191	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
192	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
193	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
194	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
195	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
196	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
197	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
198	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
199	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
200	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
201	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
202	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
203	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
204	Surfacemount Anchor Point	RIS	L97-L105	Unknown	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
205	Access Ladder (AI)	Unknown	L98	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
206	Access Ladder (AI)	Unknown	L98	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
207	Guardrail (AI)	Unknown	L98	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
208	Access Ladder (AI)	Unknown	L98	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
209	Guardrail (AI)	Unknown	L98	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
210	Access Ladder (Al)	Unknown	L98	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
211	Access Ladder (Al)	Unknown	L99	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
212	Access Ladder (Al)	Unknown	L99	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
213	Access Ladder (Al)	Unknown	L99	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
214	Guardrail (Al)	Unknown	L99	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
215	Access Stair (Galv)	Unknown	L100	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
216	Ladder Bracket	Safemaster	L100	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
217	Anchor Strop	Safemaster	L100	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
218	Surfacemount Anchor Point	Safemaster	L100	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
219	Surfacemount Anchor Point	Safemaster	L100	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
220	Access Ladder (Al)	Unknown	L102	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
221	Guardrail (Al)	Unknown	L102	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
222	Access Ladder (Al)	Unknown	L103	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
223	Guardrail (Al)	Unknown	L103	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
224	Step Bridge (Al)	Unknown	L104	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
225	Access Ladder (Al)	Unknown	L105	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
226	Guardrail (Al)	Unknown	L105	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
227	Static line	Safemaster	L106	40360	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
228	Access Ladder (Galv)	Unknown	L106	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
229	Purlin Fix Anchor Point	Safemaster	L108	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
230	Purlin Fix Anchor Point	Safemaster	L108	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
231	Purlin Fix Anchor Point	Safemaster	L108	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
232	Purlin Fix Anchor Point	Safemaster	L108	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
233	Purlin Fix Anchor Point	Safemaster	L108	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
234	Purlin Fix Anchor Point	Safemaster	L108	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
235	Ladder Bracket	Safemaster	L108	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
236	Access Stair (AI)	Unknown	L108	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
237	Guardrail (AI)	Unknown	L108	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
238	Surfacemount Anchor Point	Safemaster	L109	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
239	Access Ladder (AI)	Unknown	L111	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
240	Access Ladder (AI)	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
241	Anchor Strop	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
242	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
243	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
244	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
245	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
246	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
247	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
248	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
249	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
250	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
251	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
252	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
253	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
254	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
255	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
256	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
257	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
258	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
259	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
260	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
261	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
262	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
263	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
264	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
266	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
267	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
268	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
269	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
270	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
271	Surfacemount Anchor Point	Safemaster	L111	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
272	Surfacemount Anchor Point	Safemaster	L111	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
273	Access Stair (Galv)	Unknown	L112	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
274	Access Stair (Galv)	Unknown	L112	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
275	Guardrail (Galv)	Unknown	L112	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
276	Access Stair (Galv)	Unknown	L113	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
277	Guardrail (Galv)	Unknown	L113	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
278	Access Ladder (Al)	Safemaster	L118	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
279	Strop	Safemaster	L118	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
280	Surfacemount Anchor Point	Safemaster	L118	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
281	Surfacemount Anchor Point	Safemaster	L118	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
282	Handrail (Al)	Safemaster	L119	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
283	Surfacemount Anchor Point	Safemaster	L120	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
284	Surfacemount Anchor Point	Safemaster	L120	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
285	Surfacemount Anchor Point	Safemaster	L120	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
286	Surfacemount Anchor Point	Safemaster	L120	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
287	Surfacemount Anchor Point	Safemaster	L120	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
288	Access Ladder (Al)	Unknown	L121	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
289	Static line	Safemaster	L121	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
290	Access Sign	Bayside Australia 2000	L121	1/02/2012	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
291	Surfacemount Anchor Point	Bayside Australia 2000	L121	40940	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
292	Access Stair (Galv)	Unknown	L121	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
293	Static line	Safemaster	L122	40360	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
294	Static line	Safemaster	L123	1/07/2010	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
295	Static line	Safemaster	L124	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
296	Static line	Safemaster	L124	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
297	Static line	Safemaster	L124	40360	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
298	Static line	Safemaster	L125	1/07/2010	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
299	Access Stair (Galv)	Unknown	L126	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
300	Access Stair (Galv)	Unknown	L126	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
301	Guardrail (Galv)	Unknown	L126	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
302	Purlin Fix Anchor Point	Safemaster	L127	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
303	Purlin Fix Anchor Point	Safemaster	L127	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
304	Purlin Fix Anchor Point	Safemaster	L127	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
305	Purlin Fix Anchor Point	Safemaster	L127	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
306	Access Ladder (Al)	Unknown	L128	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
307	Access Stair (Galv)	Unknown	L129	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
308	Guardrail (Galv)	Unknown	L129	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
309	Access Stair (Galv)	Unknown	L130	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
310	Guardrail (Galv)	Unknown	L130	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
311	Access Stair (Galv)	Unknown	L131	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
312	Guardrail (Galv)	Unknown	L131	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
313	Purlin Fix Anchor Point	Safemaster	L131	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
314	Purlin Fix Anchor Point	Safemaster	L131	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
315	Purlin Fix Anchor Point	Safemaster	L131	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
316	Purlin Fix Anchor Point	Safemaster	L131	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
317	Ladder Bracket	Safemaster	L131	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
318	Access Ladder (Al)	Safemaster	L131	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
319	Anchor Strop	Safemaster	L131	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
320	Purlin Fix Anchor Point	Safemaster	L132	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
321	Purlin Fix Anchor Point	Safemaster	L132	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
322	Purlin Fix Anchor Point	Safemaster	L132	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
323	Purlin Fix Anchor Point	Safemaster	L132	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
324	Purlin Fix Anchor Point	Safemaster	L132	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
325	Purlin Fix Anchor Point	Safemaster	L132	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
326	Access Ladder (Al)	Unknown	L132	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
327	Access Ladder (Al)	Safemaster	L133	43272	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
328	Anchor Strop	Safemaster	L133	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
329	Surfacemount Anchor Point	Safemaster	L133	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
330	Surfacemount Anchor Point	Safemaster	L133	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
331	Surfacemount Anchor Point	Safemaster	L133	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
332	Access Ladder (AI)	Unknown	L133	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
333	Purlin Fix Anchor Point	Safemaster	L134	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
334	Purlin Fix Anchor Point	Safemaster	L134	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
335	Purlin Fix Anchor Point	Safemaster	L134	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
336	Purlin Fix Anchor Point	Safemaster	L134	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
337	Purlin Fix Anchor Point	Safemaster	L134	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
338	Purlin Fix Anchor Point	Safemaster	L134	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
339	Purlin Fix Anchor Point	Safemaster	L134	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
340	Purlin Fix Anchor Point	Safemaster	L134	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
341	Purlin Fix Anchor Point	Safemaster	L134	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
342	Access Ladder (Al)	Unknown	L134	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
343	Purlin Fix Anchor Point	Safemaster	L135	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
344	Purlin Fix Anchor Point	Safemaster	L135	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
345	Purlin Fix Anchor Point	Safemaster	L135	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
346	Purlin Fix Anchor Point	Safemaster	L135	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
347	Purlin Fix Anchor Point	Safemaster	L135	40360	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
348	Ladder Bracket	Safemaster	L135	1/07/2010	23/04/2019	23/04/2020	AS1891.4:2009	Fail	
349	Access Ladder (Al)	Unknown	L135	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
350	Access Stair (Galv)	Unknown	L136	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
351	Guardrail (Galv)	Unknown	L136	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
352	Access Ladder (Al)	Unknown	L137	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
353	Surfacemount Anchor Point	Safemaster	L138	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
354	Surfacemount Anchor Point	Safemaster	L138	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
355	Surfacemount Anchor Point	Safemaster	L138	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
356	Surfacemount Anchor Point	Safemaster	L138	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
357	Surfacemount Anchor Point	Safemaster	L138	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
358	Surfacemount Anchor Point	Safemaster	L138	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
359	Surfacemount Anchor Point	Safemaster	L146	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
360	Surfacemount Anchor Point	Safemaster	L146	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
361	Surfacemount Anchor Point	Safemaster	L146	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
362	Surfacemount Anchor Point	Safemaster	L146	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
363	Surfacemount Anchor Point	Safemaster	L146	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
364	Surfacemount Anchor Point	Safemaster	L146	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
365	Surfacemount Anchor Point	Safemaster	L146	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
366	Surfacemount Anchor Point	Safemaster	L146	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
367	Ladder Bracket	Safemaster	L147	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
368	Anchor Strop	Safemaster	L147	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
369	Static line	Safemaster	L147	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
370	Surfacemount Anchor Point	Safemaster	L148	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
371	Surfacemount Anchor Point	Safemaster	L148	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
372	Surfacemount Anchor Point	Safemaster	L148	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
373	Surfacemount Anchor Point	Safemaster	L148	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
374	Surfacemount Anchor Point	Safemaster	L148	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
375	Surfacemount Anchor Point	Safemaster	L148	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
376	Surfacemount Anchor Point	Safemaster	L148	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
377	Surfacemount Anchor Point	Safemaster	L148	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
378	Surfacemount Anchor Point	Safemaster	L148	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
379	Access Ladder (Al)	Safemaster	L149	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
380	Surfacemount Anchor Point	Safemaster	L149	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
381	Surfacemount Anchor Point	Safemaster	L149	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
382	Surfacemount Anchor Point	Safemaster	L149	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
383	Surfacemount Anchor Point	Safemaster	L149	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
384	Surfacemount Anchor Point	Safemaster	L149	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
385	Surfacemount Anchor Point	Safemaster	L149	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
386	Surfacemount Anchor Point	Safemaster	L149	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
387	Surfacemount Anchor Point	Safemaster	L149	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
388	Access Ladder (AI)	Unknown	L150	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
389	Access Ladder (AI)	Unknown	L151	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
390	Surfacemount Anchor Point	Safemaster	L152	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
391	Surfacemount Anchor Point	Safemaster	L152	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
392	Surfacemount Anchor Point	Safemaster	L152	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
393	Ladder Bracket	Safemaster	L155	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
394	Anchor Strop	Safemaster	L155	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
395	Static line	Safemaster	L155	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
396	Ladder Bracket	Safemaster	L155	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
397	Anchor Strop	Safemaster	L155	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
398	Static line	Safemaster	L155	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
399	Surfacemount Anchor Point	Safemaster	L156	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
400	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
401	Low Pro Anchor Point	Safemaster	L156-L160	41913	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
402	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
403	Low Pro Anchor Point	Safemaster	L156-L160	41913	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
404	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
405	Low Pro Anchor Point	Safemaster	L156-L160	41913	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
406	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
407	Low Pro Anchor Point	Safemaster	L156-L160	41913	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre  
**Job Ref:** SM12182-RockinghamCentre  
**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
408	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
409	Low Pro Anchor Point	Safemaster	L156-L160	41913	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
410	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
411	Low Pro Anchor Point	Safemaster	L156-L160	41913	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
412	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
413	Low Pro Anchor Point	Safemaster	L156-L160	41913	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
414	Low Pro Anchor Point	Safemaster	L156-L160	1/10/2014	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
415	Access Ladder (Al)	Unknown	L158	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
416	Static line	Safemaster	L160	1/10/2014	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
417	Access Ladder (Galv)	Unknown	L163	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
418	Handrail (Al)	Safemaster	L163	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
419	Surfacemount Anchor Point	Safemaster	L163	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
420	Surfacemount Anchor Point	Safemaster	L163	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
421	Surfacemount Anchor Point	Safemaster	L163	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
422	Surfacemount Anchor Point	Safemaster	L163	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
423	Surfacemount Anchor Point	Safemaster	L163	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
424	Handrail (Al)	Safemaster	L163	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
425	Access Ladder (Galv)	Unknown	L164	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
426	Access Ladder (Galv)	Unknown	L168	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
427	Access Ladder (Galv)	Unknown	L171	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
428	Access Ladder (Galv)	Unknown	L172	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
429	Fold down ladder	Unknown	L173	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
430	Handrail (AI)	Safemaster	L173	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
431	Surfacemount Anchor Point	Safemaster	L173	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
432	Surfacemount Anchor Point	Safemaster	L173	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
433	Surfacemount Anchor Point	Safemaster	L173	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
434	Surfacemount Anchor Point	Safemaster	L173	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
435	Access Ladder (AI)	Safemaster	L173	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
436	Surfacemount Anchor Point	Safemaster	L174	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
437	Surfacemount Anchor Point	Safemaster	L174	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
438	Surfacemount Anchor Point	Safemaster	L174	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
439	Surfacemount Anchor Point	Safemaster	L174	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
440	Surfacemount Anchor Point	Safemaster	L174	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
441	Access Ladder (Al)	Safemaster	L174	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
442	Surfacemount Anchor Point	Safemaster	L174	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
443	Access Ladder (Galv)	Unknown	L175	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
444	Access Ladder (Galv)	Unknown	L175	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
445	Surfacemount Anchor Point	Safemaster	L176	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
446	Surfacemount Anchor Point	Safemaster	L176	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
447	Surfacemount Anchor Point	Safemaster	L176	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
448	Surfacemount Anchor Point	Safemaster	L176	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
449	Surfacemount Anchor Point	Safemaster	L176	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
450	Surfacemount Anchor Point	Safemaster	L176	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
451	Surfacemount Anchor Point	Safemaster	L176	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
452	Access Ladder (AI)	Safemaster	L176	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
453	Access Ladder (AI)	Unknown	L177	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
454	Access Ladder (AI)	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
455	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
456	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
457	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
458	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
459	Ladder Bracket	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
460	Ladder Bracket	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
461	Ladder Bracket	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
462	Anchor Strop	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
463	Anchor Strop	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
464	Anchor Strop	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
465	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
466	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
467	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
468	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
469	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
470	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
471	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
472	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
473	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
474	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
475	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
476	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
477	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
478	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
479	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
480	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
481	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
482	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
483	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
484	Surfacemount Anchor Point	Safemaster	L177	21/06/2018	23/04/2019	23/04/2020	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
485	Surfacemount Anchor Point	Safemaster	L177	43272	23/04/2019	23/04/2020	AS1891.4:2009	Pass	
486	Static line	RIS	L178	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
487	Ladder Bracket	RIS	L178	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
488	Access Sign	RIS	L178	1/08/2009	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
489	Static line	RIS	L179	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
490	Guardrail (Al)	Unknown	L180	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
491	Purlin Fix Anchor Point	RIS	L180	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
492	Purlin Fix Anchor Point	RIS	L180	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
493	Purlin Fix Anchor Point	RIS	L180	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
494	Purlin Fix Anchor Point	RIS	L180	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
495	Purlin Fix Anchor Point	RIS	L180	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
496	Purlin Fix Anchor Point	RIS	L180	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
497	Purlin Fix Anchor Point	RIS	L180	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
498	Purlin Fix Anchor Point	RIS	L180	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
499	Purlin Fix Anchor Point	RIS	L180	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
500	Ladder Bracket	RIS	L180	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
501	Access Sign	RIS	L180	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
502	Access Stair	Unknown	L182	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
503	Access Sign	RIS	L182	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
504	Static line	RIS	L183	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
505	Static line	RIS	L184	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
506	Ladder Bracket	RIS	L184	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
507	Access Sign	RIS	L184	40026	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Fail	
508	Anchor Strop	Safemaster	L184	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
509	Surfacemount Anchor Point	Safemaster	L184	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
510	Surfacemount Anchor Point	Safemaster	L184	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
511	Surfacemount Anchor Point	Safemaster	L184	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
512	Surfacemount Anchor Point	Safemaster	L184	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
513	Surfacemount Anchor Point	Safemaster	L184	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
514	Surfacemount Anchor Point	Safemaster	L184	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
515	Purlin Fix Anchor Point	RIS	L186	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
516	Purlin Fix Anchor Point	RIS	L186	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
517	Purlin Fix Anchor Point	RIS	L186	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre  
**Job Ref:** SM12182-RockinghamCentre  
**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
518	Purlin Fix Anchor Point	RIS	L186	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
519	Purlin Fix Anchor Point	RIS	L186	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
520	Purlin Fix Anchor Point	RIS	L186	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
521	Purlin Fix Anchor Point	RIS	L186	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
522	Access Sign	RIS	L186	1/08/2009	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
523	Static line	RIS	L187	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
524	Purlin Fix Anchor Point	RIS	L187	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
525	Purlin Fix Anchor Point	RIS	L187	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
526	Purlin Fix Anchor Point	RIS	L187	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
527	Purlin Fix Anchor Point	RIS	L187	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
528	Purlin Fix Anchor Point	RIS	L187	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
529	Ladder Bracket	RIS	L187	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
530	Access Sign	RIS	L187	1/08/2009	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
531	Guardrail (Al)	Unknown	L187	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
532	Purlin Fix Anchor Point	RIS	L188	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
533	Purlin Fix Anchor Point	RIS	L188	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
534	Purlin Fix Anchor Point	RIS	L188	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
535	Purlin Fix Anchor Point	RIS	L188	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
536	Purlin Fix Anchor Point	RIS	L188	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
537	Purlin Fix Anchor Point	RIS	L188	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
538	Guardrail (Al)	Unknown	L188	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
539	Access Ladder (Al)	Unknown	L188	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre  
**Job Ref:** SM12182-RockinghamCentre  
**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
540	Static line	Unknown	L189	Unknown	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
541	Access Hatch	RIS	L189	40026	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
542	Access Sign	RIS	L189	1/08/2009	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
543	Handrail (Al)	Safemaster	L189	43272	23/04/2019	23/04/2020	AS/NZS 1657-2018	Pass	
544	Static line	Unknown	L190	Unknown	23/04/2019	23/04/2020	AS/NZS 1891.4		Test before use EWP access only
545	Purlin Fix Anchor Point	RIS	L190	40026	23/04/2019	23/04/2020	AS/NZS 1891.4		Test before use EWP access only
546	Purlin Fix Anchor Point	RIS	L190	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4		Test before use EWP access only
547	Static line	Unknown	L191	Unknown	23/04/2019	23/04/2020	AS/NZS 1891.4		Test before use EWP access only
548	Purlin Fix Anchor Point	RIS	L191	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4		Test before use EWP access only
549	Purlin Fix Anchor Point	RIS	L191	40026	23/04/2019	23/04/2020	AS/NZS 1891.4		Test before use EWP access only
550	Purlin Fix Anchor Point	RIS	L191	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4		Test before use EWP access only

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
551	Guardrail (AI)	Unknown	L192	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
552	Purlin Fix Anchor Point	RIS	L192	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
553	Purlin Fix Anchor Point	RIS	L192	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
554	Purlin Fix Anchor Point	RIS	L192	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
555	Purlin Fix Anchor Point	RIS	L192	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
556	Purlin Fix Anchor Point	RIS	L192	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
557	Purlin Fix Anchor Point	RIS	L192	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
558	Purlin Fix Anchor Point	RIS	L192	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
559	Purlin Fix Anchor Point	RIS	L192	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
560	Access Ladder (AI)	Unknown	L193	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
561	Access Ladder (AI)	Unknown	L194	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
562	Purlin Fix Anchor Point	RIS	L195	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
563	Purlin Fix Anchor Point	RIS	L195	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
564	Purlin Fix Anchor Point	RIS	L195	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
565	Purlin Fix Anchor Point	RIS	L195	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
566	Purlin Fix Anchor Point	RIS	L196	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
567	Purlin Fix Anchor Point	RIS	L196	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
568	Purlin Fix Anchor Point	RIS	L196	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
569	Access Ladder (Al)	Unknown	L197	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
570	Access Ladder (Al)	Unknown	L198	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
571	Static line	RIS	L198	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
572	Purlin Fix Anchor Point	RIS	L198	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centre  
**Job Ref:** SM12182-RockinghamCentre  
**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
573	Purlin Fix Anchor Point	RIS	L198	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
574	Static line	RIS	L199	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
575	Ladder Bracket	RIS	L199	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
576	Access Sign	RIS	L199	1/08/2009	23/04/2019	23/04/2020	AS1319:1994 AS1891.4-2009	Pass	
577	Anchor Strop	Safemaster	L199	43272	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
578	Static line	RIS	L200	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
579	Access Ladder (AI)	Unknown	L202	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
580	Static line	RIS	L203	1/08/2009	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
581	Static line	RIS	L203	40026	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
582	Access Ladder (AI)	Unknown	L204	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
583	Guardrail (AI)	Unknown	L204	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
584	Static line	RSS	L205	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
585	Surfacemount Anchor Point	RSS	L205	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
586	Surfacemount Anchor Point	RSS	L205	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
587	Surfacemount Anchor Point	RSS	L205	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
588	Surfacemount Anchor Point	RSS	L205	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
589	Surfacemount Anchor Point	RSS	L207	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
590	Surfacemount Anchor Point	RSS	L207	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
591	Surfacemount Anchor Point	RSS	L207	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
592	Static line	RSS	L208	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
593	Surfacemount Anchor Point	RSS	L207	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
594	Surfacemount Anchor Point	RSS	L207	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre

**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
595	Surfacemount Anchor Point	RSS	L207	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
596	Surfacemount Anchor Point	RSS	L207	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
597	Access Ladder (Al)	Unknown	L210	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Pass	
598	Anchor Strop	Safemaster	L210	21/06/2018	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
599	Access Ladder (Al)	Unknown	L211	Unknown	23/04/2019	23/04/2020	AS/NZS 1657-2013	Fail	
600	Surfacemount Anchor Point	RSS	L211	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
601	Surfacemount Anchor Point	RSS	L211	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
602	Surfacemount Anchor Point	RSS	L211	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
603	Surfacemount Anchor Point	RSS	L211	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
604	Surfacemount Anchor Point	RSS	L211	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
605	Surfacemount Anchor Point	RSS	L211	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: inspections@safemaster.net.au

**Client:** Vicinity Centre

**Job Ref:** SM12182-RockinghamCentre


**Site:** Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
606	Surfacemount Anchor Point	RSS	L211	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
607	Surfacemount Anchor Point	RSS	L211	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
608	Surfacemount Anchor Point	RSS	L211	1/05/2016	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	
609	Static line	RSS	L212	42491	23/04/2019	23/04/2020	AS/NZS 1891.4	Pass	

AUTHORISED BY: Tyron Menikides

DATE: 23-04-2019



SIGNATURE:





All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

### ADDITIONAL FINDINGS & RECOMMENDATIONS



Table below summarises additional findings and recommendations in support of the Roof Safety Report.

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
48 8	Building: General Stores Location Reference: <a href="#">L01</a> Task: Access to the roof									
		Variation in height between walkway panels are greater than required maximum	Trips, Slips and Falls	Awareness induction	Med	Existing walkway section to be removed. New walkway section and high visibility safety yellow nosing to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7  AS/NZS 1657-2018 3.3.4
48 9	Building: General Stores Location Reference: <a href="#">L28</a> Task: Access to the roof									
		Gap between walkway panels are greater than required maximum and not fully secured	Trips, Slips and Falls	Awareness induction	Med	Additional walkway section including new channels to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7  AS/NZS 1657-2013 3.2.3.4



Roof Safety Report for  
**Rockingham Centre, WA 6168**

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
490	Building: General Stores Location Reference: <a href="#">L39</a> Task: Access to the roof									
		Existing static line will expire on 13-8-2019	Trips, Slips and Falls	Awareness induction	High	Existing static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55  AS/NZS 1891.4:2009 6.3(vi)
491	Building: General Stores Location Reference: <a href="#">L43</a> Task: Access to the roof									
		Existing static line will expire on 13-8-2019	Trips, Slips and Falls	Awareness induction	High	Existing static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55  AS/NZS 1891.4:2009 6.3(vi)

Roof Safety Report for  
**Rockingham Centre, WA 6168**

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
49 2	Building: General Stores Location Reference: <a href="#">L75</a> Task: Access to the roof									
		Gap between walkway and fall edge is less than required minimum	Trips, Slips and Falls	Awareness induction	High	Handrail to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7  AS/NZS 1657-2018 5.4.1
49 3	Building: General Stores Location Reference: <a href="#">L82</a> Task: Access to the A/c unit									
		No safe access to the A/c unit	Trips, Slips and Falls	N/A	Low	Supply walkway to the A/c unit	Low	Client advised	Outstanding	-

Roof Safety Report for  
**Rockingham Centre, WA 6168**

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
49 4	Building: General Stores Location Reference: <a href="#">L105</a> Task: Access to the roof									
		Ladder landing is less than required minimum	Trips, Slips and Falls	Awareness induction	Med	Additional walkway sections to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7  AS/NZS 1657-2018 7.3.6
49 5	Building: General Stores Location Reference: <a href="#">L122</a> Task: Access to the roof									
		Damaged anchor point is present	Trips, Slips and Falls	Awareness induction	High	Existing anchor point to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55



**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)