

Roof Safety Report

Rockingham Centre, WA 6168

Prepared By: Safemaster Safety Products
Date: 23-04-2020

CONFIDENTIALITY/SECURITY

Information obtained from and about Rockingham Centre, WA in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Rockingham Centre, WA and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Andrew Treen (Safemaster Safety Products)
31-33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: recertifications3@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Andrew Treen (Recertification Technician)

Roof Safety Report for
Rockingham Centre, WA 6168

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Rockingham Centre	Rockingham Centre, Rockingham WA 6168	Signage Anchor Points Ladder Bracket Landings Hatch Guardrail Ladder Stair Static Line Mechanical Platform Roof Walkway A/C Safe Working Platform

DATE OF INSPECTION

08-04-2020

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors trained in RIIWHS204D & PUAEQU001B to evaluate the roof safety system on Rockingham Centre, WA 6168 buildings.

The inspection is based on:

- OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS 1657:2018 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Access Stair (Galv)	Unknown	L1	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
2	Access Ladder (Al)	Safemaster	L1	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
3	Anchor Strop	Safemaster	L1	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
4	Purlinfix Anchor Point	Safemaster	L1	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
5	Purlinfix Anchor Point	Safemaster	L1	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
6	Purlinfix Anchor Point	Safemaster	L1	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
7	Purlinfix Anchor Point	Safemaster	L1	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
8	Purlinfix Anchor Point	Safemaster	L1	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
9	Purlinfix Anchor Point	Safemaster	L1	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
10	Access Stair (Galv)	Unknown	L3	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
11	Purlinfix Anchor Point	Safemaster	L4	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
12	Purlinfix Anchor Point	Safemaster	L4	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
13	Purlinfix Anchor Point	Safemaster	L4	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
14	Purlinfix Anchor Point	Safemaster	L4	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
15	Purlinfix Anchor Point	Safemaster	L6	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
16	Purlinfix Anchor Point	Safemaster	L6	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
17	Purlinfix Anchor Point	Safemaster	L6	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
18	Purlinfix Anchor Point	Safemaster	L6	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
19	Surfacemount Anchor Point	Safemaster	L11	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
20	Static line	SALA	L16	13/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service- Serviceable life expired.
21	Access Sign	SALA	L16	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
22	Static line	SALA	L17	13/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service- Serviceable life expired.

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
23	Access Sign	SALA	L17	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
24	Access Ladder (Al)	Unknown	L18	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
25	Access Ladder (Al)	Unknown	L19	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
26	Purlinfix Anchor Point	Safemaster	L20	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
27	Surfacemount Anchor Point	Safemaster	L20	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
28	Access Ladder (Al)	Unknown	L21	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
29	Access Ladder (Al)	Safemaster	L22	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
30	Anchor Strop	Safemaster	L22	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
31	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
32	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
33	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
34	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
35	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
36	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
37	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
38	Purlinfix Anchor Point	Safemaster	L22	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
39	Guardrail (Galv)	Unknown	L24	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
40	Access Stair (Galv)	Unknown	L24	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
41	Access Ladder (Al)	Unknown	L25	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
42	Access Ladder (Al)	Unknown	L26	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
43	Access Ladder (Al)	Unknown	L27	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
44	Access Ladder (Galv)	Unknown	L29	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
45	Access Ladder (Galv)	Unknown	L30	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
46	Anchor Strop	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
47	Surfacemount Anchor Point	Unknown	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
48	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
49	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
50	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
51	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
52	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
53	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
54	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
55	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
56	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
57	Surfacemount Anchor Point	Safemaster	L31	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
58	Access Ladder (Al)	Unknown	L32	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
59	Access Ladder (Galv)	Unknown	L33	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
60	Purlinfix Anchor Point	Safemaster	L34	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
61	Purlinfix Anchor Point	Safemaster	L34	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
62	Purlinfix Anchor Point	Safemaster	L34	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
63	Purlinfix Anchor Point	Safemaster	L34	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
64	Purlinfix Anchor Point	Safemaster	L34	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
65	Purlinfix Anchor Point	Safemaster	L34	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
66	Purlinfix Anchor Point	Safemaster	L34	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
67	Ladder Bracket	Safemaster	L35	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
68	Anchor Strop	Safemaster	L35	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
69	Surfacemount Anchor Point	Safemaster	L35	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
70	Surfacemount Anchor Point	Safemaster	L35	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
71	Surfacemount Anchor Point	Safemaster	L35	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
72	Surfacemount Anchor Point	Safemaster	L35	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
73	Static line	Safemaster	L36	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
74	Access Stair (Galv)	Unknown	L38	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
75	Static line - Surfacemount	SALA	L39	1/08/2019	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
76	Access Sign	SALA	L39	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
77	Static line - Surfacemount	SALA	L43	1/08/2019	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
78	Access Sign	SALA	L43	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
79	Access Ladder (AI)	Safemaster	L46	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
80	Anchor Strop	Safemaster	L46	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
81	Surfacemount Anchor Point	Safemaster	L46	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
82	Surfacemount Anchor Point	Safemaster	L46	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
83	Surfacemount Anchor Point	Safemaster	L46	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
84	Surfacemount Anchor Point	Safemaster	L46	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
85	Surfacemount Anchor Point	Safemaster	L46	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
86	Purlinfix Anchor Point	Safemaster	L47	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
87	Purlinfix Anchor Point	Safemaster	L47	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
88	Purlinfix Anchor Point	Safemaster	L47	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
89	Access Stair (Galv)	Unknown	L48	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
90	Access Stair (Galv)	Unknown	L50	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
91	Guardrail (Galv)	Unknown	L50	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
92	Handrail (Al)	Safemaster	L50	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
93	Step (Al)	Safemaster	L50	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
94	Handrail (Al)	Safemaster	L52	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
95	Handrail (Al)	Safemaster	L55	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
96	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
97	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
98	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
99	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
100	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
101	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
102	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
103	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
104	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
105	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
106	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
107	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
108	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
109	Purlinfix Anchor Point	Safemaster	L55	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
110	Access Ladder (AI)	Safemaster	L56	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
111	Purlinfix Anchor Point	Safemaster	L57	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
112	Purlinfix Anchor Point	Safemaster	L57	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
113	Access Stair (Galv)	Unknown	L57	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
114	Static line - Surfacemount	Safemaster	L58	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
115	Access Sign	SALA	L58	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
116	Access Ladder (Galv)	Unknown	L60	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
117	Static line - Surfacemount	Safemaster	L61	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
118	Access Sign	SALA	L61	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
119	Handrail (Al)	Safemaster	L61	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
120	Low Pro Anchor Point	Unknown	L61	1/09/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
121	Low Pro Anchor Point	Unknown	L61	1/09/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
122	Low Pro Anchor Point	Unknown	L61	1/09/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
123	Access Ladder (Al)	Unknown	L62	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
124	Ladder Bracket	Safemaster	L65	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
125	Surfacemount Anchor Point	Safemaster	L65	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
126	Surfacemount Anchor Point	Safemaster	L65	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
127	Surfacemount Anchor Point	Safemaster	L65	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
128	Ladder Bracket	Safemaster	L66	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
129	Anchor Strop	Safemaster	L66	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
130	Purlin Fix Anchor Point	Safemaster	L66	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
131	Purlin Fix Anchor Point	Safemaster	L66	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
132	Purlin Fix Anchor Point	Safemaster	L66	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Static line	Safemaster	L68	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
134	Access Sign	SALA	L68	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
135	Surfacemount Anchor Point	Safemaster	L70	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
136	Surfacemount Anchor Point	Safemaster	L70	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
137	Static line	SALA	L71	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service- Serviceable life expired.
138	Access Sign	SALA	L71	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
139	Static line	SALA	L74	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service- Serviceable life expired.
140	Access Sign	SALA	L74	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
141	Access Ladder (AI)	Unknown	L74	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
142	Handrail (AI)	Safemaster	L75	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
143	Handrail (AI)	Safemaster	L83	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
144	Static line - Surfacemount	Safemaster	L85	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
145	Access Sign	SALA	L85	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
146	Access Ladder (Al)	Unknown	L87	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
147	Purlin Fix Anchor Point	Safemaster	L88	1/09/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
148	Purlin Fix Anchor Point	Safemaster	L88	1/09/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
149	Purlin Fix Anchor Point	Safemaster	L88	1/09/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
150	Purlin Fix Anchor Point	Safemaster	L88	1/09/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
151	Ladder Bracket	Safemaster	L88	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
152	Access Stair (Al)	Unknown	L89	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
153	Guardrail (Galv)	Unknown	L89	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
154	Purlinfix Anchor Point	Safemaster	L92	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
155	Purlinfix Anchor Point	Safemaster	L92	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
156	Purlinfix Anchor Point	Safemaster	L92	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
157	Purlinfix Anchor Point	Safemaster	L92	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
158	Purlinfix Anchor Point	Safemaster	L92	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
159	Purlinfix Anchor Point	Safemaster	L92	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
160	Access Ladder (Al)	Unknown	L93	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
161	Access Ladder (Al)	Unknown	L94	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
162	Access Ladder (Al)	Unknown	L96	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
163	Surfacemount Anchor Point	Safemaster	L97	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
164	Access Ladder (Al)	Unknown	L97	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
165	Guardrail (Al)	Unknown	L97	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
166	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
167	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
168	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
169	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
170	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
171	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
172	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
173	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
174	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
175	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
176	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
177	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
178	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
179	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
180	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
181	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
182	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
183	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
184	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
185	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
186	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
187	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
188	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
189	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
190	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
191	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
192	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
193	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
194	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
195	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
196	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
197	Surfacemount Anchor Point	RIS	L97-L105	1/07/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
198	Access Ladder (Al)	Unknown	L98	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
199	Access Ladder (Al)	Unknown	L98	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
200	Guardrail (Al)	Unknown	L98	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
201	Access Ladder (Al)	Unknown	L98	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
202	Guardrail (Al)	Unknown	L98	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
203	Access Ladder (Al)	Unknown	L98	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
204	Access Ladder (Al)	Unknown	L99	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
205	Access Ladder (Al)	Unknown	L99	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
206	Access Ladder (Al)	Unknown	L99	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
207	Guardrail (Al)	Unknown	L99	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
208	Access Stair (Galv)	Unknown	L100	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
209	Ladder Bracket	Safemaster	L100	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
210	Anchor Strop	Safemaster	L100	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
211	Surfacemount Anchor Point	Safemaster	L100	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
212	Surfacemount Anchor Point	Safemaster	L100	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
213	Ladder Bracket	RIS	L100	1/07/2014	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
214	Anchor Strop	RIS	L100	1/07/2014	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
215	Surfacemount Anchor Point	RIS	L100	1/07/2014	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
216	Surfacemount Anchor Point	RIS	L100	1/07/2014	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
217	Access Ladder (AI)	Unknown	L102	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
218	Guardrail (AI)	Unknown	L102	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
219	Access Ladder (AI)	Unknown	L103	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
220	Guardrail (AI)	Unknown	L103	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
221	Step Bridge (Al)	Unknown	L104	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
222	Access Ladder (Al)	Unknown	L105	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
223	Guardrail (Al)	Unknown	L105	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
224	Static line	Safemaster	L106	1/07/2010	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
225	Access Ladder (Galv)	Unknown	L106	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
226	Purlin Fix Anchor Point	Safemaster	L108	1/01/2009	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
227	Purlin Fix Anchor Point	Safemaster	L108	1/01/2009	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
228	Purlin Fix Anchor Point	Safemaster	L108	1/01/2009	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
229	Purlin Fix Anchor Point	Safemaster	L108	1/01/2009	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
230	Purlin Fix Anchor Point	Safemaster	L108	1/01/2009	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
231	Purlin Fix Anchor Point	Safemaster	L108	1/01/2009	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
232	Ladder Bracket	Safemaster	L108	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
233	Access Stair (Al)	Unknown	L108	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
234	Guardrail (Al)	Unknown	L108	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
235	Surfacemount Anchor Point	Safemaster	L109	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
236	Access Ladder (Al)	Unknown	L111	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
237	Access Ladder (Al)	Safemaster	L111	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
238	Anchor Strop	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
239	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
240	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
241	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
242	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
243	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
244	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
245	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
246	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
247	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
248	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
249	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
250	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
251	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
252	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
253	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
254	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
255	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
256	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
257	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
258	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
259	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
260	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
261	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
262	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
263	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
264	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
265	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
266	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
267	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
268	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
269	Surfacemount Anchor Point	Safemaster	L111	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
270	Access Stair (Galv)	Unknown	L112	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
271	Access Stair (Galv)	Unknown	L112	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
272	Guardrail (Galv)	Unknown	L112	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
273	Access Stair (Galv)	Unknown	L113	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
274	Guardrail (Galv)	Unknown	L113	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
275	Access Ladder (Al)	Safemaster	L118	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
276	Strop	Safemaster	L118	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
277	Surfacemount Anchor Point	Safemaster	L118	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
278	Surfacemount Anchor Point	Safemaster	L118	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
279	Handrail (Al)	Safemaster	L119	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
280	Surfacemount Anchor Point	Safemaster	L120	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
281	Surfacemount Anchor Point	Safemaster	L120	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
282	Surfacemount Anchor Point	Safemaster	L120	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
283	Surfacemount Anchor Point	Safemaster	L120	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
284	Surfacemount Anchor Point	Safemaster	L120	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
285	Access Ladder (Al)	Unknown	L121	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
286	Static line	Safemaster	L121	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
287	Access Sign	Bayside Australia 2000	L121	1/02/2012	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
288	Surfacemount Anchor Point	Bayside Australia 2000	L121	1/02/2012	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
289	Access Stair (Galv)	Unknown	L121	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
290	Static line - Purlin Fix	Safemaster	L122	1/04/2012	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
291	Static line - Purlin Fix	Safemaster	L123	1/04/2012	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
292	Static line - Surfacemount	Safemaster	L124	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
293	Static line - Surfacemount	Safemaster	L124	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
294	Static line - Surfacemount	Safemaster	L124	1/03/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
295	Static line - Purlin Fix	Safemaster	L125	1/04/2012	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
296	Access Stair (Galv)	Unknown	L126	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
297	Access Stair (Galv)	Unknown	L126	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
298	Guardrail (Galv)	Unknown	L126	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
299	Purlin Fix Anchor Point	Safemaster	L127	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
300	Purlin Fix Anchor Point	Safemaster	L127	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
301	Purlin Fix Anchor Point	Safemaster	L127	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
302	Purlin Fix Anchor Point	Safemaster	L127	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
303	Access Ladder (Al)	Unknown	L128	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
304	Access Stair (Galv)	Unknown	L129	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
305	Guardrail (Galv)	Unknown	L129	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
306	Access Stair (Galv)	Unknown	L130	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
307	Guardrail (Galv)	Unknown	L130	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
308	Access Stair (Galv)	Unknown	L131	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
309	Guardrail (Galv)	Unknown	L131	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
310	Purlin Fix Anchor Point	Safemaster	L131	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
311	Purlin Fix Anchor Point	Safemaster	L131	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
312	Purlin Fix Anchor Point	Safemaster	L131	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
313	Purlin Fix Anchor Point	Safemaster	L131	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
314	Ladder Bracket	Safemaster	L131	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
315	Access Ladder (Al)	Safemaster	L131	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
316	Anchor Strop	Safemaster	L131	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
317	Purlin Fix Anchor Point	Sayfa	L132	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
318	Purlin Fix Anchor Point	Sayfa	L132	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
319	Purlin Fix Anchor Point	Sayfa	L132	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
320	Purlin Fix Anchor Point	Sayfa	L132	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
321	Purlin Fix Anchor Point	Sayfa	L132	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
322	Purlin Fix Anchor Point	Sayfa	L132	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
323	Access Ladder (Al)	Unknown	L132	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
324	Access Ladder (Al)	Safemaster	L133	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
325	Anchor Strop	Safemaster	L133	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
326	Surfacemount Anchor Point	Safemaster	L133	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
327	Surfacemount Anchor Point	Safemaster	L133	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
328	Surfacemount Anchor Point	Safemaster	L133	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
329	Access Ladder (Al)	Unknown	L133	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
330	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
331	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
332	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
333	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
334	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
335	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
336	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
337	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
338	Purlin Fix Anchor Point	Sayfa	L134	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
339	Access Ladder (Al)	Unknown	L134	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
340	Purlin Fix Anchor Point	Safemaster	L135	1/04/2012	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
341	Purlin Fix Anchor Point	Safemaster	L135	1/04/2012	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
342	Purlin Fix Anchor Point	Safemaster	L135	1/04/2012	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
343	Purlin Fix Anchor Point	RIS	L135	1/04/2012	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
344	Purlin Fix Anchor Point	RIS	L135	1/04/2012	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
345	Ladder Bracket	Safemaster	L135	1/07/2010	8/04/2020	8/04/2021	AS1891.4:2009	Fail	
346	Access Ladder (Al)	Unknown	L135	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
347	Access Stair (Galv)	Unknown	L136	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
348	Guardrail (Galv)	Unknown	L136	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
349	Access Ladder (Al)	Unknown	L137	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
350	Surfacemount Anchor Point	Safemaster	L138	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
351	Surfacemount Anchor Point	Safemaster	L138	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
352	Surfacemount Anchor Point	Safemaster	L138	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
353	Surfacemount Anchor Point	Safemaster	L138	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
354	Surfacemount Anchor Point	Safemaster	L138	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
355	Surfacemount Anchor Point	Safemaster	L138	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
356	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
357	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
358	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
359	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
360	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
361	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
362	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
363	Surfacemount Anchor Point	Safemaster	L146	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
364	Ladder Bracket	Safemaster	L147	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
365	Anchor Strop	Safemaster	L147	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
366	Static line	Safemaster	L147	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
367	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
368	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
369	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
370	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
371	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
372	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
373	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
374	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
375	Surfacemount Anchor Point	Safemaster	L148	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
376	Access Ladder (Al)	Safemaster	L149	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
377	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
378	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
379	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
380	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
381	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
382	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
383	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
384	Surfacemount Anchor Point	Safemaster	L149	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
385	Access Ladder (Al)	Unknown	L150	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
386	Access Ladder (Al)	Unknown	L151	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
387	Surfacemount Anchor Point	Safemaster	L152	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
388	Surfacemount Anchor Point	Safemaster	L152	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
389	Surfacemount Anchor Point	Safemaster	L152	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
390	Ladder Bracket	Safemaster	L155	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
391	Anchor Strop	Safemaster	L155	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
392	Static line	Safemaster	L155	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
393	Ladder Bracket	Safemaster	L155	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
394	Static line	Safemaster	L155	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
395	Surfacemount Anchor Point	Safemaster	L156	21/06/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
396	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
397	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
398	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
399	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
400	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
401	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
402	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
403	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
404	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
405	Low Pro Anchor Point	Safemaster	L156-L160	9/12/2016	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
406	Surfacemount Anchor Point	Safemaster	L156-L160	1/10/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
407	Surfacemount Anchor Point	Safemaster	L156-L160	1/10/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
408	Surfacemount Anchor Point	Safemaster	L156-L160	1/10/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
409	Surfacemount Anchor Point	Safemaster	L156-L160	1/10/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
410	Surfacemount Anchor Point	Safemaster	L156-L160	1/10/2014	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
411	Access Ladder (Al)	Unknown	L158	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
412	Static line - Surfacemount	Safemaster	L160	1/10/2014	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
413	Access Ladder (Galv)	Unknown	L163	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
414	Handrail (Al)	Safemaster	L163	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
415	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
416	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
417	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
418	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
419	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
420	Handrail (Al)	Safemaster	L163	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
421	Access Ladder	Safemaster	L163	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
422	Access Ladder (Galv)	Unknown	L164	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
423	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
424	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
425	Surfacemount Anchor Point	Safemaster	L163	1/03/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
426	Access Ladder (Galv)	Unknown	L168	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
427	Access Ladder (Galv)	Unknown	L171	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
428	Access Ladder (Galv)	Unknown	L172	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
429	Fold down ladder	Unknown	L173	27/02/2018	8/04/2020	8/04/2021	AS 1657-2018	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
430	Handrail (AI)	Safemaster	L173	27/02/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
431	Purlin Fix Anchor Point	Safemaster	L173	27/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
432	Purlin Fix Anchor Point	Safemaster	L173	27/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
433	Purlin Fix Anchor Point	Safemaster	L173	27/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
434	Purlin Fix Anchor Point	Safemaster	L173	27/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
435	Purlin Fix Anchor Point	Safemaster	L173	27/02/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
436	Surfacemount Anchor Point	Safemaster	L174	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
437	Surfacemount Anchor Point	Safemaster	L174	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
438	Surfacemount Anchor Point	Safemaster	L174	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
439	Surfacemount Anchor Point	Safemaster	L174	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
440	Surfacemount Anchor Point	Safemaster	L174	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
441	Access Ladder (Al)	Safemaster	L174	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
442	Surfacemount Anchor Point	Safemaster	L174	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
443	Access Ladder (Galv)	Unknown	L175	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
444	Access Ladder (Galv)	Unknown	L175	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
445	Surfacemount Anchor Point	Safemaster	L176	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
446	Surfacemount Anchor Point	Safemaster	L176	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
447	Surfacemount Anchor Point	Safemaster	L176	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
448	Surfacemount Anchor Point	Safemaster	L176	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
449	Surfacemount Anchor Point	Safemaster	L176	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
450	Surfacemount Anchor Point	Safemaster	L176	1/02/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
451	Access Ladder (Al)	Safemaster	L176	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
452	Access Ladder (AI)	Unknown	L177	1/01/2018	8/04/2020	8/04/2021	AS 1657-2018	Fail	
453	Access Ladder (AI)	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS 1657-2018	Pass	
454	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
455	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
456	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
457	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
458	Ladder Bracket	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
459	Ladder Bracket	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
460	Ladder Bracket	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
461	Anchor Strop	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
462	Anchor Strop	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
463	Anchor Strop	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
464	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
465	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
466	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
467	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
468	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
469	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
470	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
471	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
472	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
473	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
474	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
475	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
476	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
477	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
478	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
479	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
480	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
481	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
482	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
483	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	
484	Surfacemount Anchor Point	Safemaster	L177	1/01/2018	8/04/2020	8/04/2021	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
485	Static line - Concrete Fix	RIS	L178	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
486	Ladder Bracket	RIS	L178	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
487	Access Sign	RIS	L178	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
488	Static line - Concrete Fix	RIS	L179	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
489	Guardrail (AI)	Unknown	L180	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
490	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
491	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
492	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
493	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
494	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
495	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
496	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
497	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
498	Purlin Fix Anchor Point	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
499	Ladder Bracket	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
500	Access Sign	RIS	L180	1/09/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
501	Access Stair	Unknown	L182	1/09/2009	8/04/2020	8/04/2021	AS 1657-2018	Pass	
502	Access Sign	RIS	L182	1/09/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
503	Static line - Purlin Fix	RIS	L183	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service expired
504	Static line - Purlin Fix	RIS	L184	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service expired
505	Ladder Bracket	RIS	L184	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
506	Access Sign	RIS	L184	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Fail	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
507	Anchor Strop	Safemaster	L184	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
508	Surfacemount Anchor Point	Safemaster	L184	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
509	Surfacemount Anchor Point	Safemaster	L184	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
510	Surfacemount Anchor Point	Safemaster	L184	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
511	Surfacemount Anchor Point	Safemaster	L184	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
512	Surfacemount Anchor Point	Safemaster	L184	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
513	Surfacemount Anchor Point	Safemaster	L184	1/02/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
514	Purlin Fix Anchor Point	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
515	Purlin Fix Anchor Point	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
516	Purlin Fix Anchor Point	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
517	Purlin Fix Anchor Point	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
518	Purlin Fix Anchor Point	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
519	Purlin Fix Anchor Point	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
520	Purlin Fix Anchor Point	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
521	Access Sign	RIS	L186	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
522	Static line - Purlin Fix	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service expired
523	Purlin Fix Anchor Point	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
524	Purlin Fix Anchor Point	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
525	Purlin Fix Anchor Point	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
526	Purlin Fix Anchor Point	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
527	Purlin Fix Anchor Point	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
528	Ladder Bracket	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
529	Access Sign	RIS	L187	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
530	Guardrail (Al)	Unknown	L187	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
531	Purlin Fix Anchor Point	RIS	L188	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
532	Purlin Fix Anchor Point	RIS	L188	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
533	Purlin Fix Anchor Point	RIS	L188	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
534	Purlin Fix Anchor Point	RIS	L188	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
535	Purlin Fix Anchor Point	RIS	L188	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
536	Purlin Fix Anchor Point	RIS	L188	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
537	Guardrail (Al)	Unknown	L188	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
538	Access Ladder (Al)	Unknown	L188	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
539	Static line	Unknown	L189	Unknown	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	Full of pigeon and rat poo

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
540	Access Hatch	RIS	L189	1/08/2009	8/04/2020	8/04/2021	AS 1657-2018	Not Inspected	Full of pigeon and rat poo
541	Access Sign	RIS	L189	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Not Inspected	Full of pigeon and rat poo
542	Handrail (AI)	Safemaster	L189	21/06/2018	8/04/2020	8/04/2021	AS 1657-2018	Not Inspected	Full of pigeon and rat poo
543	Static line	Unknown	L190	Unknown	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	
544	Purlin Fix Anchor Point	RIS	L190	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	
545	Purlin Fix Anchor Point	RIS	L190	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	
546	Static line	Unknown	L191	Unknown	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	
547	Purlin Fix Anchor Point	RIS	L191	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	
548	Purlin Fix Anchor Point	RIS	L191	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	
549	Purlin Fix Anchor Point	RIS	L191	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Not Inspected	
550	Guardrail (AI)	Unknown	L192	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
551	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
552	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
553	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
554	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
555	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
556	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
557	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
558	Purlin Fix Anchor Point	RIS	L192	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
559	Access Ladder (Al)	Unknown	L193	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
560	Access Ladder (Al)	Unknown	L194	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
561	Purlin Fix Anchor Point	RIS	L195	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
562	Purlin Fix Anchor Point	RIS	L195	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
563	Purlin Fix Anchor Point	RIS	L195	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
564	Purlin Fix Anchor Point	RIS	L195	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
565	Purlin Fix Anchor Point	RIS	L196	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
566	Purlin Fix Anchor Point	RIS	L196	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
567	Purlin Fix Anchor Point	RIS	L196	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
568	Access Ladder (AI)	Unknown	L197	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
569	Access Ladder (AI)	Unknown	L198	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
570	Static line	RIS	L198	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
571	Purlin Fix Anchor Point	RIS	L198	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
572	Purlin Fix Anchor Point	RIS	L198	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
573	Static line - Purlin Fix	RIS	L199	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
574	Ladder Bracket	RIS	L199	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
575	Access Sign	RIS	L199	1/08/2009	8/04/2020	8/04/2021	AS1319:1994 AS1891.4-2009	Pass	
576	Anchor Strop	Safemaster	L199	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
577	Static line	RIS	L200	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
578	Access Ladder (AI)	Unknown	L202	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
579	Static line - Concrete Fix	RIS	L203	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
580	Static line - Concrete Fix	RIS	L203	1/08/2009	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
581	Access Ladder (AI)	Unknown	L204	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
582	Static line - Concrete Fix	RSS	L204	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
583	Guardrail (AI)	Unknown	L204	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
584	Static line - Concrete Fix	RSS	L205	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Fail	Tagged out of service - Service is expired
585	Surfacemount Anchor Point	RSS	L205	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
586	Surfacemount Anchor Point	RSS	L205	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
587	Surfacemount Anchor Point	RSS	L205	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
588	Surfacemount Anchor Point	RSS	L205	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
589	Surfacemount Anchor Point	RSS	L207	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
590	Surfacemount Anchor Point	RSS	L207	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
591	Surfacemount Anchor Point	RSS	L207	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
592	Static line	RSS	L208	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
593	Surfacemount Anchor Point	RSS	L207	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
594	Surfacemount Anchor Point	RSS	L207	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
595	Surfacemount Anchor Point	RSS	L207	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
596	Surfacemount Anchor Point	RSS	L207	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
597	Access Ladder (Al)	Unknown	L210	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Pass	
598	Anchor Strop	Safemaster	L210	21/06/2018	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
599	Access Ladder (Al)	Unknown	L211	Unknown	8/04/2020	8/04/2021	AS 1657-2018	Fail	
600	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
601	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
602	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
603	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
604	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
605	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Vicinity Centre

Job Ref: SM12182-RockinghamCentre

Site: Rockingham Centre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
606	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
607	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
608	Surfacemount Anchor Point	RSS	L211	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	
609	Static line	RSS	L212	1/05/2016	8/04/2020	8/04/2021	AS/NZS 1891.4	Pass	

AUTHORISED BY: Andrew Treen

DATE: 08-04-2020

SIGNATURE:





All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



Roof Safety Report for
Rockingham Centre, WA 6168

ADDITIONAL FINDINGS & RECOMMENDATIONS



Table below summarises additional findings and recommendations in support of the Roof Safety Report.

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
49 6	Building: General Stores Location Reference: L33 Task: Access to the roof									
		Roof walkway not secured	Trips, Slips and Falls	Awareness induction	Med	Roof walkway to be secured with new channels	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7
49 7	Building: General Stores Location Reference: L62 Task: Access to the roof									
		Gap between walkway panels are greater than required maximum	Trips, Slips and Falls	Awareness induction	Med	Additional walkway sections to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7 AS 1657-2018 3.2.3.4



Roof Safety Report for
Rockingham Centre, WA 6168

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
49 8	Building: General Stores Location Reference: L16 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outsta nding	OH&S REGULATIONS 3.55
49 9	Building: General Stores Location Reference: L17 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outsta nding	OH&S REGULATIONS 3.55



Roof Safety Report for
Rockingham Centre, WA 6168

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Current Risk Level	Proposed Permanent Solution	Residual Risk Assessment	Details of Action Taken	Status	Reference
500	Building: General Stores Location Reference: L71 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55
501	Building: General Stores Location Reference: L74 Task: Access to the A/c unit									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55



Roof Safety Report for
Rockingham Centre, WA 6168

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Current Risk Level	Proposed Permanent Solution	Residual Risk Assessment	Details of Action Taken	Status	Reference
50 2	Building: General Stores Location Reference: L114 Task: Access to the roof									
		No safe access to the roof	Trips, Slips and Falls	Awareness induction	High	Ladder support platform, ladder bracket, strop and anchors to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55 & 3.7
50 3	Building: General Stores Location Reference: L183 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55



Roof Safety Report for
Rockingham Centre, WA 6168

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Curren t Risk Level	Proposed Permanent Solution	Residu al Risk Assess ment	Details of Action Taken	Status	Reference
504	Building: General Stores Location Reference: L184 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55
505	Building: General Stores Location Reference: L187 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55

Roof Safety Report for
Rockingham Centre, WA 6168

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Current Risk Level	Proposed Permanent Solution	Residual Risk Assessment	Details of Action Taken	Status	Reference
506	Building: General Stores Location Reference: L178 & L179 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55
507	Building: General Stores Location Reference: L199 & L200 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55

Roof Safety Report for
Rockingham Centre, WA 6168

No	Photo of Hazard	Details of Hazard	Details of Risk	Existing/ Immediate Control Measure	Current Risk Level	Proposed Permanent Solution	Residual Risk Assessment	Details of Action Taken	Status	Reference
508	Building: General Stores Location Reference: L203 & L204 Task: Access to the roof									
		Static line service is expired	Trips, Slips and Falls	Awareness induction	High	Static line (x3) to be replaced	Low	Client advised	Outstanding	OH&S REGULATIONS 3.55
509	Building: General Stores Location Reference: L189 Task: Access to the roof									
		No safe access to hatch	Trips, Slips and Falls	Awareness induction	Med	Fold down ladder and 2.5m ceiling ladder to be installed	Low	Client advised	Outstanding	OH&S REGULATIONS 3.7



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au