

Roof Safety Report

Rockingham Justice Complex

Prepared By: Safemaster Safety Products
Date: 30/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about Rockingham Justice Complex in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to Rockingham Justice Complex and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.

CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Trevor Harris (Recertification Technician)

Roof Safety Report for
Rockingham Justice Complex

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Programmed	Court House Court House 1 Court House 2 Court House 3	Anchor Points Signage Ladder Ladder Bracket

DATE OF INSPECTION

30/04/18

INSPECTION METHODOLOGY

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on Rockingham court House buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed

Job Ref: SM 10750

Site: Rockingham Justice Complex

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
5	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
6	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
7	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
8	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
9	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
10	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
11	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
12	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed

Job Ref: SM 10750

Site: Rockingham Justice Complex

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
14	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
15	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
16	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
17	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
18	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
19	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
20	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
21	Timber Fix Anchor Point	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
22	Vertical Ladder	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1657:2013	Pass	Top rung too far from parapet
23	Ladder Bracket	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
24	Sign	Safemaster	Court House	1/04/2013	30/04/2018	30/10/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed

Job Ref: SM 10750

Site: Rockingham Justice Complex

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
31	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
32	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
33	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
34	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
35	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
36	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed

Job Ref: SM 10750

Site: Rockingham Justice Complex

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Surfacemount Anchor Point	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
38	Ladder Bracket	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
39	Sign	Safemaster	Court House 1	1/04/2013	30/04/2018	30/10/2018	AS1319:1994 AS1891.4-2009	Pass	
40	Surfacemount Anchor Point	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
41	Surfacemount Anchor Point	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
42	Surfacemount Anchor Point	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
43	Surfacemount Anchor Point	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
44	Surfacemount Anchor Point	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
45	Surfacemount Anchor Point	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
47	Ladder Bracket	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
48	Sign	Safemaster	Court House 2	1/04/2013	30/04/2018	30/10/2018	AS1319:1994 AS1891.4-2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed

Job Ref: SM 10750

Site: Rockingham Justice Complex

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
50	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
51	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
52	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
53	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
54	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
55	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
56	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
57	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
58	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
59	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
60	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed

Job Ref: SM 10750

Site: Rockingham Justice Complex

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
62	Timber Fix Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
63	Surfacemount Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
64	Surfacemount Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
65	Surfacemount Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
66	Surfacemount Anchor Point	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
67	Ladder Bracket	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
68	Ladder Bracket	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1891.4:2009	Pass	
69	Sign	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1319:1994 AS1891.4-2009	Pass	
70	Sign	Safemaster	Court House 3	1/04/2013	30/04/2018	30/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: Trevor Harris

DATE: 30/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au