

# Roof Safety Report

**The Sanctuary**

Prepared By: Safemaster Safety Products  
Date: 06/10/2017

Roof Safety Report for  
**The Sanctuary**

**CONFIDENTIALITY/SECURITY**

Information obtained from and about The Sanctuary in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to The Sanctuary and not to any other source.

**DISCLAIMER**

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


**CONTACT THE INSPECTOR**

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.  
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

James Townsend (Safemaster Safety Products)  
33 Catalano Road, Canning Vale 6155  
PH: (08) 6243 3111 EMAIL: [recertifications@safemaster.net.au](mailto:recertifications@safemaster.net.au)

Signed for and on behalf of Safemaster Safety Products:

A handwritten signature in black ink, appearing to be 'Jb' followed by a stylized horizontal line and a vertical stroke.

**James Townsend (Recertification Technician)**

Roof Safety Report for  
**The Sanctuary**

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Logiudice	The Sanctuary	Anchor Points Signage Access Ladder Access Hatch

**DATE OF INSPECTION**

06/10/2017

**INSPECTION METHODOLOGY**

The audit has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on The Sanctuary buildings.

The inspection is based on:

- WA OSH Regs. 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'



# Inspection Log

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Logiudice

**Job Ref:** SM 7937

**Site:** The Sanctuary

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Surfacemount Anchor Point 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
2	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
3	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
4	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
5	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
6	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
7	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
8	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
9	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
10	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
11	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
12	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Logiudice

**Job Ref:** SM 7937

**Site:** The Sanctuary

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
14	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
15	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
16	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
17	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
18	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
19	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
20	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
21	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
22	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
23	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
24	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Logiudice

**Job Ref:** SM 7937

**Site:** The Sanctuary

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
26	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
27	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
28	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
29	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
30	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
31	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
32	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
33	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
34	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
35	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
36	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Logiudice

**Job Ref:** SM 7937

**Site:** The Sanctuary

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
38	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
39	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
40	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
41	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
42	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
43	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
44	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
45	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
46	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
47	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
48	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.



# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Logiudice

**Job Ref:** SM 7937

**Site:** The Sanctuary

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
50	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
51	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
52	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
53	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
54	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
55	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
56	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
57	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
58	Surfacemount Anchor Point Abseil 15kn	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1891.4:2009	Pass	
59	Access Ladder	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1657:2013	Pass	
60	Access Ladder	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1657:2013	Pass	

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

# CERTIFICATE OF COMPLIANCE

## INSPECTION LOG RECORD - INSTALLED SYSTEMS

31-33 Catalano Road, Canning Vale 6155  
CALL US: (08) 6243 3111  
EMAIL: [inspections@safemaster.net.au](mailto:inspections@safemaster.net.au)

**Client:** Logiudice

**Job Ref:** SM 7937


**Site:** The Sanctuary

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Access Hatch	Safemaster	The Sanctuary	1/06/2013	5/10/2017	5/10/2018	AS1657:2013	Pass	
62	Access Sign	Safemaster	The Sanctuary	5/10/2017	5/10/2017	5/10/2018	AS1319:1994 AS1891.4-2009	Pass	

AUTHORISED BY: JAMES TOWNSEND

DATE: 06/10/2017

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

## COMPLIANT REQUIREMENTS

There are no recommendations at this point in time.

[illegible]

**Safemaster Safety Products**

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: [info@safemaster.net.au](mailto:info@safemaster.net.au)

Web: [www.safemaster.net.au](http://www.safemaster.net.au)