

Roof Safety Report

State Theatre

Prepared By: Safemaster Safety Products
Date: 16/04/18

CONFIDENTIALITY/SECURITY

Information obtained from and about State Theatre in the course of the roof safety systems inspections and recertification's will be treated as strictly confidential. This information will only be used in the compilation and presentation of this report to State Theatre and not to any other source.

DISCLAIMER

Judgements as to the suitability of information herein for the client's purposes are necessarily the client's responsibility. This report does not constitute legal advice. Therefore, although reasonable care has been taken in the preparation of such information, Safemaster Safety Products extends no warranties, makes no representation and assumes no responsibility as to the accuracy or suitability of such information for application to the client's intended purposes or for consequences of its use.


CONTACT THE INSPECTOR

Should you have any difficulty in understanding anything outlined within this report then you should immediately contact the inspector and have the matter explained to you.
If you have any questions at all or require any clarification then contact the inspector prior to acting on this report.

The recertification report was carried out by:

Trevor Harris (Safemaster Safety Products)
33 Catalano Road, Canning Vale 6155
PH: (08) 6243 3111 EMAIL: inspections@safemaster.net.au

Signed for and on behalf of Safemaster Safety Products:



Trevor Harris (Recertification Technician)

Roof Safety Report for State Theatre

CLIENT	BUILDINGS INSPECTED	SYSTEMS INSPECTED
Programmed Facilities Management	State Theatre	Anchor Points Signage Ladder Bracket Ladder Static Lines Hatch

DATE OF INSPECTION

16/04/18

INSPECTION METHODOLOGY

The inspection has been carried out by Safemaster's team of competent inspectors to evaluate the roof safety system on State Theatre buildings.

The inspection is based on:

- Occupational Safety & Health Regulations 1996
- Managing the Risk of Falls at the Workplace
- AS/NZS 1891:2009 (Series)- Industrial Fall Arrest Systems and Devices
- AS/NZS 1319:1994 'Safety Signs for the Occupational Environment'
- AS/NZS 1657:2013 'Fixed Platforms, Walkways, Stairways and Ladders- Design, Construction and Installation'

TESTING INSTRUMENT

Product: HILTI Tester



Inspection Log

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
1	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
2	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
3	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
4	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
5	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
6	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
7	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
8	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
9	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
10	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
11	Sign	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1319:1994 AS1891.4-2009	Pass	Legible
12	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
13	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
14	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
15	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
16	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
17	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
18	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
19	Ladder Bracket	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
20	Parapet Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Pass	In Working Order
21	Incline Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Pass	In Working Order
22	Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Pass	In Working Order
23	Horizontal Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
24	Horizontal Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
25	Horizontal Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
26	Horizontal Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
27	Horizontal Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
28	Horizontal Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
29	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
30	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
31	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
32	Anchor Point-Surface Mount-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
33	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
34	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
35	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
36	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
37	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
38	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
39	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
40	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
41	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
42	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
43	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
44	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
45	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
46	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
47	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
48	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
49	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
50	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
51	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
52	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
53	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
54	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
55	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
56	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
57	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
58	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
59	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
60	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
61	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
62	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
63	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
64	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
65	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
66	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
67	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
68	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
69	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
70	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
71	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
72	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
73	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
74	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
75	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
76	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
77	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
78	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
79	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
80	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
81	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
82	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
83	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
84	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
85	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
86	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
87	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
88	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
89	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
90	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
91	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
92	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
93	Anchor Point-Purlin Fix-21kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	In Working Order
94	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
95	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
96	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
97	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
98	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
99	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
100	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
101	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
102	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
103	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
104	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
105	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
106	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
107	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
108	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
109	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
110	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
111	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
112	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
113	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
114	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
115	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
116	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
117	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
118	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
119	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
120	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
121	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
122	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
123	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
124	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
125	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
126	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
127	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
128	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
129	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
130	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
131	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN
132	Abseil Anchor Point-Concrete Fix-15kN	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1891.4:2009	Pass	Load Tested -7.5kN

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
133	Vertical Ladder- Including Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013 AS1891.4:2009	Pass	In Working Order
134	Hatch	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	N/A	Pass	In Working Order
135	Fold-out Ladder & Static Line	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013 AS1891.4:2009	Pass	In Working Order
136	Vertical Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Pass	In Working Order
137	Hatch	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	N/A	Pass	In Working Order
138	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant
139	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant
140	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant
141	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant
142	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant
143	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant
144	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant

All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

CERTIFICATE OF COMPLIANCE

31-33 Catalano Road, Canning Vale 6155
CALL US: (08) 6243 3111
EMAIL: inspections@safemaster.net.au

INSPECTION LOG RECORD - INSTALLED SYSTEMS

Client: Programmed Facilities Manegement

Job Ref: SM5024

Site: State Theatre

Item No	Equipment Type& Description	Manufacturer/ Installer	Location	Commission Date	Insp Date	Next Insp Date	Complying Standards	Status	Comments
145	Ladder Platform For Portable Ladder	Safemaster / Safemaster	Roof	25/11/2011	16/04/2018	16/10/2018	AS1657:2013	Fail	Not compliant

AUTHORISED BY: TREVOR HARRIS

DATE: 16/04/2018

SIGNATURE:



All inspections are conducted in accordance with current legislation. Equipment status is deemed at the time of inspection. Maintenance and use of the equipment must be conducted in accordance with the manufacturers and legislative requirements after inspection. Removing the installation sign/tag 'Void Warranty' for the system.

Compliance Requirements

[illegible]



Safemaster Safety Products

31-33 Catalano Road, Canning Vale WA 6155

PO Box 1373 Canning Vale WA 6970

Ph: (08) 6243 3111

Fax: (08) 9456 5014

Email: info@safemaster.net.au

Web: www.safemaster.net.au